

ASS. REC. BY:

REF: CS/CTI18005363/Dvd3¹⁷

Special Instruction:

Surveyor
Mennen

Bryon

ASSIGNMENT (Office)

From (Person):

Jouhn Tay

of

CTI

Date/Time:

21/03/2018 @ 4:45pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHA 4139H

Insured:

SJE 4595D

at Workshop m/s

SOON Hack Motor

Tel:

64836016

of

Blk 10, AMK Ind. Park 2A # 01-05/06

Policy No:

DMPCSN3059131601

Claim No:

SNM18D01422C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/03/2018

CA / REV / REP. / REV 24 HRS

lwp'

H.O.D. Endorsement:

Date/Time:

10:23am @ 22/3/18

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 4139H - NBA / INC 18000175/Y
	SJE 4595D - X

D.O.A: 01/01/2018

REF: CTI

ASSIGNMENT

From:

Date: 22/03/2018

Veh No: SHA 4139 H

Yr Regn: Dec 2016

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SHA 4139 H

Make: Hyundai I40

C.C. 1685

at Workshop m/s Soon Hock Motor

Colour: Blue

A/C: Insured / Std / NI / NA

of Blk 10, AMK Ind. Park 2A # 01-05/06

Sp Reading: 186687

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: D4FDGU693168

Policy No:

C/No: KMHLB41UNHU097081

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Good / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Good / Jammed / Leaked / Burnt or

Make of Veh:

Modi: NI / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/60 R 16

R: ———

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 8 mm

R/Bal. 8 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 8 mm

L/Bal. 8 mm

Est. Repairs: 13 days Res: Yes or No

D.O.A. 16/03/2018

D.O.I. 22/03/2018

Lum Sum: 20 % 3 Val: Yes or No

Survey held at Chunn? AMK

CA / REV / REP. / 24 HRS ^{wp}

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front & O/S Body

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Vehicle: IN / OUT

Date / Time Action / Instruction

China Teiping SSE 459517

15/04/18 Inmate 2/5 10,950/- with 13 days of work. (Reel 20,575.12, 65M)

RECEIVED 16 APR 2018

Date/Time: File Pass to?

☐

: Preli. Report

Days Of Repair: 13

1)

☐

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Date/Time: File Return to?

1) S + RE \$

2) Photos

3) Others

Report Format:

merimen

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Tech. Invs. \$☐ Weekend \$

Lump Sum / I.B.I. \$

10,950/2

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005363/Dvd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-03-2018

Code : CTI



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJE 4595D	Veh. Inspected	SHA 4139H
Policy No.	DMPCSN3059131601	Coverage (\$)	0.00
Claim No.	SNM18D01422C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/03/2018	Inspection Date	22/03/2018
Survey held at	SOON HOCK MOTOR PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		21 Mar 2018 16:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TEE CHEW CHUANG, ID: S0237273H		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA4139H	Date of Loss:	16/03/2018 10:00 - :59
Claim Type:	TP / SNM18D01422C02	Policy/Cover Note No.:	DMPCSN3059131601 (Comprehensive)
Vehicle Reg. No. (Insured):	SJE4595D	Policy No. (Claimant):	D-18088936MFSH
		Excess:	S\$0.00
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/04/2018]		
Driver/Custodian (Insured):	PANG KANG LAM (69 / Male), NRIC: S2118850F, Tel: +6590091728		
Adj Asg. Remarks:	EST \$30,683.36 , ASSIGN HENRY NG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCDB18036102 / ComlanDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 18/03/2018 14:00
 SUBMITTED BY: Jareal Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 16/03/2018 14:00
 Date Of Accident 16/03/2018 10:35
 Exact Location Of Accident AYE(CITY) LOWER DELTA EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA4139H
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
 Driver
 Name of Driver MOHD SAPUAN B SAMURI
 NRIC No S0165637F
 Date Of Birth 13/11/1952
 Occupation OUTDOOR
 Date Of Driving Pass 04/12/1986
 Driving Experience 31 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address BLK 363 YISHUN RING ROAD
 #05-1560
 Postcode 760363
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED REFER POLICE REPORT NO: T/20180316/2133 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJE4595D
 Vehicle Make/Model/Colour HYUNDAI
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver PANG KAM LAM
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHD SAPUAN B SAMURI
Approximate Age	
Injuries Sustain	CHEST AND BACK PAIN
Injured person in which vehicle?	SHA4139H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 16 MAR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 16/3/18 @ 12.30pm


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

LISA DIONG

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 16/3/2018 @ 10:35hrs. my taxi (A) (CHA 4139H) was travelling along AYE (Lany) to Lower Delta Rd. with 1 female passenger on board. my female pax name Ms Eugene Tan Chin Hong, ID 79094060. HP no: 97901460.

I was stop at the traffic junction, I saw the traffic turn green so I proceed to turning to Lower Delta Rd. suddenly, vehicle (B) (SEE 4545D) on my right side, dashed out and collided onto my taxi (A) right portion. my taxi (A) right portion was damaged.

NO one was coming by the ambulance.

I had video, fix in my taxi. and scene photos to support my claim.

after the accident, I felt pain on my chest and back, will seek the doctor later on.

A - CHA 4139H.

B - SEE 4545D, Mr. Pang Kam Lam. IC no: 82188509.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 16 MAR 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/3/2018 @ 12.35hrs

Reporting Centre Personnel's Signature
Name: LISA DIONG
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

To Survey by HKK

VEHICLE NO : SHA 4139H

DATE : 16.03.2018

MAKE :

TEL : 6542 5119


MODEL : HYUNDAI i40

FAX : 6542 6039

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Headlamp (RH) <i>mounting cradle</i>			\$ 1,388.00	✓
	Front Fender (RH) <i>inc</i>			\$ 619.00	✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 169.80	✓
	Front Door (RH) <i>inc</i>			\$ 1,403.00	✓
	Front Door Rubber <i>deformed</i>			\$ 290.50	✓
	Front Door Gear / Regulator (RH) <i>✗ BT</i>			\$ 785.50	✗ ✓
	Front Door Hinge Upper (RH) <i>✗ BT</i>			\$ 53.40	✗ ✓
	Front Door Hinge Lower (RH) <i>✗ BT</i>			\$ 53.40	✗ ✓
	Front Door Check (RH) <i>✗ SVC</i>			\$ 110.15	✗ ✗
	Front Door Inner Lock (RH) <i>✗ SVC</i>			\$ 348.95	✗ ✗
	Front Door Mirror (RH) <i>crack</i>			\$ 980.50	✓
	Front Door Power Motor <i>NH</i>			\$ 950.90	✗
	Front Door Trim Board (RH) <i>✗ mounting cradle</i>			\$ 1,196.90	✗ ✓
	Door Centre Pillar Outer (RH) <i>Dented</i>			\$ 1,786.20	✓
	Door Centre Pillar Inner (RH) <i>crack</i>			\$ 1,890.50	✗
	Rocker Panel Outer Garnish <i>BT</i>			\$ 483.60	✓
	Rocker Panel Outer <i>crack</i>			\$ 1,380.50	✗
	Rocker Panel Step Garnish (Front) (RH) <i>SVC</i>			\$ 31.70	✗
	Rear Door (RH) <i>Dented</i>			\$ 1,351.00	✓
	Front Windscreen Glass <i>SVC</i>			\$ 1,059.25	✗
	Front Windscreen Moulding <i>✗ NH</i>			\$ 60.00	✗ ✓
	Front Windscreen Pillar Outer (RH) <i>✗ repair Dented</i>			\$ 1,843.10	✗ ✗ ✓
	Front Windscreen Pillar Inner (RH) <i>NH</i>			\$ 1,743.10	✗
	Front Wheel Rim (RH) <i>✗ distorted NH</i>			\$ 351.90	✗ ✗ ✗
	Front Wheel Hub Cap (RH) <i>✗ NH</i>			\$ 150.70	✗ ✗ ✗
	Front Wheel Bearing <i>✗ Dented NH</i>			\$ 258.50	✗ ✗ ✗
	Front Shock Absorber (Assy) (RH) <i>✗ distorted NH</i>			\$ 342.20	✗ ✗ ✗
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 75.10	✗
	Front Drive Shaft (RH) <i>NH</i>			\$ 1,069.55	✗
	Rack & Pinion Assy <i>✗ distorted NH</i>			\$ 2,184.00	✗ ✗ ✗
	STG Tie End, RH <i>✗ NH</i>			\$ 69.50	✗ ✗ ✗
	Front Suspension Lower Arm (RH) <i>✗ ✗ distorted NH</i>			\$ 715.10	✗ ✗ ✗
	Knuckle Arm (RH) <i>✗ distorted NH</i>			\$ 582.95	✗ ✗ ✗
	Engine Under Cover <i>NH</i>			\$ 343.10	✗
	Engine Crossmember <i>NH</i>			\$ 2,236.90	✗
	Dashboard Complete <i>NH</i>			\$ 2,688.00	✗
	ABS Sensor, RH <i>NH</i>			\$ 261.50	✗
	Front bumper - mounting cradle			1052.20	✓
	SUB TOTAL			\$ 31,307.95	
	LESS 20%			\$ 6,261.59	
	DISCOUNTED TOTAL		13516.10	\$ 25,046.36	
			10812.38		

SHA 4139H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door Comfort Logo (RH) <i>N/C</i>			\$ 75.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>N/C</i>			\$ 80.00	Nett ✓
	Front Windscreen Sealant <i>* N/C</i>			\$ 46.00	Nett ✓
	Front Tyre (RH) <i>2000d 80% N/C</i>		201.00	\$ 216.00	Nett ✓ X 12230
				\$ 417.00	
	Labour Charge				
	Panel Beating			\$ 2,000.00	1200/-
	Spray Painting Charge			\$ 1,500.00	1000/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	20/-
	Towing Charge			\$ 50.00	* N/C
	Transfer of Door	\$ 120.00		\$ 240.00	120/-
	Remove/Refix Undercarriage (FRT)			\$ X 400.00	2180/- N/C
	FRT Wheel Alignment			\$ X 120.00	600 N/C
	Remove/Refix Dashboard			\$ 450.00	2180/-
	Remove/Refix Front Windscreen Glass			\$ 120.00	* 80/-
	Remove/Refix Cushion & Upholstery Front		2690/-	\$ 90.00	60/-
	TOTAL LABOUR			\$ 5,220.00	
	ESTIMATE TOTAL			\$ 30,683.36	13703.88
				31,525.12	41510950/-
	22/03/2018 @ 1130m Not Antenna 2/5mm 13 days Tryer LKK Auto 				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 4139 H

Technician:

Mileage: 186687

Time Printed 22.3.18 1:10 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°45'		-3°00' 3°00'
4°06'		-0°19' 5°41'
-0°06'		-1°30' 1°30'
14°18'		
13°33'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
3°02'		-3°00' 3°00'
3°46'		-0°19' 5°41'
-29°34'		-1°30' 1°30'
10°37'		
13°39'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-3°47'		-3°00' 3°00'
0°20'		-3°00' 3°00'
3°41'		-3°00' 3°00'
-29°41'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°45'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°38'		-3°30' 2°30'
0°09'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°07'		-3°00' 3°00'
0°18'		-3°00' 3°00'
0°00'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005363/DVD3N2

Date: 18/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3059131601
Claimant Vehicle No :	SHA4139H	Insured Vehicle No :	SJE4595D
Date of Loss:	16/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01422C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4139H	Engine No:	D4FDGU693168
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMHU097081
Reg. Date:	15/12/2016 (Man. Year: 2016)	Odometer:	186687 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 8 mm	Rear Left Side:	Hankook 8 mm
Front Right Side:	Hankook 8 mm	Rear Right Side:	Hankook 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,305.12	11,013.88	15,291.24	58.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	2,690.00	2,530.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,525.12	13,703.88	17,821.24	56.53
Approved Total (Overridden) (\$\$)		10,950.00		
(\$\$)	31,525.12	10,950.00	20,575.12	65.27
+ GST 7.00/7.00% (\$\$)	2,206.76	766.50	1,440.26	65.27
Nett Amount (\$\$)	33,731.88	11,716.50	22,015.38	65.27

INSPECTION

Date of Assignment: 21/03/2018

Date Inspected: 22/03/2018 Inspected At:

CHUNNI MOTOR WORK PTE LTD
 BLK 10 ANG MO KIO INDUSTRIAL PK
 2A #01-05/06 AMK AUTOPOINT
 SINGAPORE 568047
 Repairer: Soon Hock Motor Pte Ltd (HQ)

Estimated Period of Repair: 13.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4139H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP (RH)	Mounting Cracked	1,388.00 FL	*1,388.00 FL
2	1		*FRONT FENDER (RH)	Buckled	619.00 FL	*619.00 FL
3	1		*FRONT FENDER SHIELD (RH)	Deformed	169.80 FL	*169.80 FL
4	1		*FRONT DOOR (RH)	Buckled	1,403.00 FL	*1,403.00 FL
5	1		*FRONT DOOR RUBBER	Deformed	290.50 FL	*290.50 FL
6	1		*FRONT DOOR GEAR/REGULATOR (RH)	Bent	785.50 FL	*785.50 FL
7	1		*FRONT DOOR HINGE UPPER (RH)	Bent	53.40 FL	*53.40 FL
8	1		*FRONT DOOR HINGE LOWER (RH)	Bent	53.40 FL	*53.40 FL
9	1		*FRONT DOOR CHECK (RH)	Serviceable	110.15 FL	*- FL
10	1		*FRONT DOOR INNER LOCK (RH)	Serviceable	348.95 FL	*- FL
11	1		*FRONT DOOR MIRROR (RH)	Cracked	980.50 FL	*980.50 FL
12	1		*FRONT DOOR POWER MOTOR	Not Necessary	950.90 FL	*- FL
13	1		*FRONT DOOR TRIM BOARD (RH)	Mounting Cracked	1,196.90 FL	*1,196.90 FL
14	1		*DOOR CENTRE PILLAR OUTER (RH)	Dented	1,786.20 FL	*1,786.20 FL
15	1		*DOOR CENTRE PILLAR INNER (RH)	Repair	1,890.50 FL	*- FL
16	1		*ROCKER PANEL OUTER GARNISH	Bent	483.60 FL	*483.60 FL
17	1		*ROCKER PANEL OUTER	Repair	1,380.50 FL	*- FL
18	1		*ROCKER PANEL STEP GARNISH (FRONT)(RH)	Serviceable	31.70 FL	*- FL
19	1		*REAR DOOR (RH)	Dented	1,351.00 FL	*1,351.00 FL
20	1		*FRONT WINDSCREEN GLASS	Serviceable	1,059.25 FL	*- FL
21	1		*FRONT WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
22	1		*FRONT WINDSCREEN PILLAR OUTER (RH)	Dented	1,843.10 FL	*1,843.10 FL
23	1		*FRONT WINDSCREEN PILLAR INNER (RH)	Not Necessary	1,743.10 FL	*- FL
24	1		*FRONT WHEEL RIM (RH)	Not Necessary	351.90 FL	*- FL
25	1		*FRONT WHEEL HUB CAP (RH)	Not Necessary	150.70 FL	*- FL
26	1		*FRONT WHEEL BEARING	Not Necessary	258.50 FL	*- FL
27	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Not Necessary	342.20 FL	*- FL
28	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	75.10 FL	*- FL
29	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	1,069.55 FL	*- FL
30	1		*RACK & PINION ASSY	Not Necessary	2,184.00 FL	*- FL
31	1		*STG TIE END,RH	Not Necessary	69.50 FL	*- FL
32	1		*FRONT SUSPENSION LOWER ARM (RH)	Not Necessary	715.10 FL	*- FL
33	1		*KNUCKLE ARM (RH)	Not Necessary	582.95 FL	*- FL
34	1		*ENGINE UNDER COVER	Not Necessary	343.10 FL	*- FL
35	1		*ENGINE CROSSMEMBER	Not Necessary	2,236.90 FL	*- FL
36	1		*DASHBOARD COMPLETE	Not Necessary	2,688.00 FL	*- FL
37	1		*ABS SENSOR,RH	Not Necessary	261.50 FL	*- FL
38	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
39	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
40	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS
42	1		*FRONT BUMPER	Mounting Cracked	1,052.20 FL	*1,052.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,777.15	13,717.10
- List Item Discount on L Items 20.00/20.00% (S\$)	6,472.03	2,703.22
Total Parts (S\$)	26,305.12	11,013.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,500.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	20.00
5	TOWING CHARGE	New	50.00	-
6	TRANSFER OF DOOR	New	240.00	120.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	-
8	FRT WHEEL ALIGNMENT	New	120.00	-
9	REMOVE/REFIX DASHBOARD	New	450.00	180.00
10	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
11	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	60.00
Gross Labour Cost (S\$)			5,220.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >