























PAR Automotive Consultancy

Regn No: 5298674L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0554-17-TCA

04 December 2017

ACCIDENT VEHICLE SURVEY REPORT

Viswanatha Ramasubramanian
32 Upper Serangoon View #02-44
Singapore 534209

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SCZ1299B	<i>Odometer:</i>	117981km
<i>Make & Model:</i>	Nissan Teana 2.0L CVT	<i>Colour:</i>	Grey
<i>Chassis number:</i>	JN1BDUJ32Z0001079	<i>Date of accident:</i>	27/03/2017
<i>Year of Regn.:</i>	22/09/2009	<i>Date inspected:</i>	04/04/2017
<i>Repairer at:</i>	Twincar Automotive Pte Ltd	<i>Date inspected (After Repair):</i>	13/04/2017
	2 Kaki Bukit Ave 2 #01-17		
	Kaki Bukit Auto Hub		
	Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



