

ASS. REC. BY:

REF: CS/ICS18005369/Avd3h2

Date/Time:

Survivor  
Merimen

Adnan

ASSIGNMENT (Office)

From (Person):

Janice Goh

of ECICS

Date/Time:

21/3/18 02:38 pm

Estimated Cost:

Bill to:

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLQ 2959P

Insured:

at Workshop in/s:

1st Autoworks

Tel:

68441985

of:

23 Kallie Bkt Ave 4 # 04-01

Policy No.:

MPC17A 00420800

Claim No.:

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

17/03/2018

(Client's Record)

CA /  REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:11am @ 22/3/18

Person Contacted:

Suhaimi

Vehicle IN/

OIT

Date/Time

Action/Instruction (✓) Estimate

SLQ 2959P - CS/ICS18005195/Ad3

-D.O.A-17/3/18

22/3/18

Revert by merimen

27/3/18

Sent Authouse email

23/5/18

Final fig \$12,906.75 confirmed by email (Real 12,747.70, 50%)





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18005369/Avd3

7 TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
SINGAPORE 038987&nbsp; &nbsp; &nbsp;

Date : 22-03-2018



Code : ICS

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLQ 2959P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	500.00
Assign From JANICE GOH	Assign Date	22/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 17/03/2018	Inspection Date 22/03/2018
Survey held at 1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933	

## 5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Date: 22 Mar 2018
<b><u>Preliminary Advice</u></b>	

Vehicle No	: SLQ2959P	Accident Date	: 17/03/2018
Make	: OPEL ASTRA	Policy No.	: MPC17A00420800
Assignment Date	: 22/03/2018	Excess	: S\$0.00
Date of Inspection	: 22/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,897.55
Revised Amount	:S\$	9,862.05
Check Items (Estimated)	:S\$	2,785.50
Total	:S\$	12,647.55

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	27,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,306.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

<b>To:</b> ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	--

**Attn:** \_\_\_\_\_ **Date:** 21 May 2018

## Preliminary Advice

Vehicle No	: SLQ2959P	Accident Date	: 17/03/2018
Make	: OPEL ASTRA	Policy No.	: MPC17A00420800
Assignment Date	: 22/03/2018	Excess	: S\$0.00
Date of Inspection	: 22/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,654.45	(incl.supplementary \$756.90)
Revised Amount	:S\$	12,906.75	(incl.supplementary \$756.90)
Check Items (Estimated)	:S\$	0.00	
<b>Total</b>	<b>:S\$</b>	<b>12,906.75</b>	
Lump Sum Repair	:S\$		

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	27,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,306.00

### Remarks

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Kindly approved on the supplementary.

## ...CLAIM SUBFOLDER...(Pending Mandate Request)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2018 17:02		22 Mar 2018 00:00		<b>Last:IA</b> 22 Mar 2018 17:45		<b>Pending Mandate Request</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LEE THIAM POH, ID: S1366624E, Email: LEETONY@NOVATION.COM.SG		
Vehicle Reg. No.:	SLQ2959P	Date of Loss:	17/03/2018 21:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	MPC17A00420800 (Comprehensive)
		Excess:	
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/04/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### View Received Message

This mail is associated with :  
**\*SLQ2959P (DMPC1800101H)**  
OD  
Mar 17 2018 9:00PM  
[LEE THIAM POH]  
1st Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** ECICS Limited (HQ) (ECICS), sent on 23/05/2018 10:43 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12906.75) - SLQ2959P - Claim Handler: Janice Goh

Approved:12906.75:POLICY EXCESS \$500. THANK YOU.

**DOCUMENTS SUMMARY**  
There are no documents.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 23 May 2018 11:15 AM  
**To:** Kelvin.chew@alpinemotors.sg  
**Cc:** suhaimi@firstautoworks.com.sg; SUR  
**Subject:** RE: FW: SLQ 2959 P ASTRA K ECICS OD DOA 17.03.2018 FINALIZE

Dear Kelvin,

Confirmed part by part \$12,906.75 before excess \$500 @ 6 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]  
**Sent:** Thursday, 17 May 2018 12:28 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** suhaimi@firstautoworks.com.sg; SUR <sur@lkkauto.com>  
**Subject:** re: FW: SLQ 2959 P ASTRA K ECICS OD DOA 17.03.2018 FINALIZE

Hi Veron,

i have confirm again with my parts department.  
amount correct.  
explain to Mr. Adrian yesterday about this.  
thanks.

from,  
kelvin chew  
8292 5595

---

**From:** "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>  
**Sent:** Thursday, May 17, 2018 11:37 AM  
**To:** "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>  
**Cc:** "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>, "SUR" <sur@lkkauto.com>  
**Subject:** FW: SLQ 2959 P ASTRA K ECICS OD DOA 17.03.2018 FINALIZE

Dear Kelvin,

Please re-confirmed supplementary parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]  
**Sent:** Monday, 7 May 2018 3:02 PM  
**To:** SUR <sur@lkkauto.com>  
**Cc:** suhaimi@firstautoworks.com.sg  
**Subject:** SLQ 2959 P ASTRA K ECICS OD DOA 17.03.2018 FINALIZE

Hi Lkk,

attach is finalize report.  
part by part \$12,906.75 before excess \$500 @ 6 working days.  
kindly please check & confirm with me.  
thanks.

from,  
kelvin chew  
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

## Janice Lee (LKKAuto)

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Tuesday, March 27, 2018 9:25 AM  
**To:** 'suhaimi@firstautoworks.com.sg'  
**Cc:** SUR  
**Subject:** SLQ 2959P ECICS OD DOA: 17/03/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 2959P (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

**\*Kindly acknowledge if you have received this email\***

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler(On behalf of Veron)

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [jannicelee@lkkauto.com](mailto:jannicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SLQ2959P**  
OD  
Mar 17 2018 9:00PM  
[LEE THIAM POH]  
1st Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** ECICS Limited (HQ) (ECICS), sent on 26/03/2018 17:35 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$12647.55) - SLQ2959P

Approved:12647.55:POLICY EXCESS \$500. THANK YOU.

### DOCUMENTS SUMMARY

There are no documents.

## Catherine Chong (LKK Auto)

---

**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**Sent:** Wednesday, 21 March, 2018 2:38 PM  
**To:** vincent.sim@alpinemotors.sg; assignments  
**Cc:** Phoebe Jay Xie (ECICS, Claims); Kelvin Chew; suhaimi@alpinemotors.sg;  
motorsurvey  
**Subject:** RE: SLQ2959P - OPEL ASTRA - OWN DAMAGED CLAIMS- ECICS  
**Attachments:** SLQ2959P.PDF; SLQ2959P\_ESTIMATE (2).jpg; SLQ2959P\_ESTIMATE 1.jpg;  
SLQ2959P\_ESTIMATE.JPG

Dear Vincent

Thank you for your email.  
We will appoint LKK for OD survey.

Aside to LKK

Please assist to arrange OD survey.  
Policy excess ~~\$3500.~~ \$ 500.00

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

**From:** Vincent Sim [mailto:vincent.sim@alpinemotors.sg]  
**Sent:** Wednesday, 21 March, 2018 1:25 PM  
**To:** motorsurvey  
**Cc:** Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Kelvin Chew; suhaimi@alpinemotors.sg  
**Subject:** SLQ2959P - OPEL ASTRA - OWN DAMAGED CLAIMS- ECICS

Dear Sir,  
As attached for the above , kindly sent surveyor to inspect the vehicle ,  
location as below ;  
Person in charge :-  
Suhaimi or kelvin  
68441985 – office phone  
E-mail ;  
[suhaimi@alpinemotors.sg](mailto:suhaimi@alpinemotors.sg)  
[Kelvin.chew@alpinemotors.sg](mailto:Kelvin.chew@alpinemotors.sg)

Add;  
First Autoworks Pte Ltd  
23, Kaki Bukit Ave 4


#04-01 ( South Wing )  
singapore 415933  
( Vicom Building )  
tel; 6844-1985

Regards,  
Vincent Sim- Claims Dept

[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	6624E
<b>Vehicle Details</b>	
Vehicle No.:	SLQ2959P
Vehicle to be Exported:	No
Intended De-registration Date:	22 Mar 2018
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.0 AT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	B1170167HRXX0170
Chassis No.:	W0LBE8EA8H8052241
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$19,889.00
Original Registration Date:	04 Jul 2017
First Registration Date:	04 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>OPC Cash Rebate Details</b>	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jul 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	03 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,801.00
COE Rebate Amount:	\$23,944.00
<b>Total Rebate Amount:</b>	<b>\$27,694.00</b>

The information contained herein is correct as at 22 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT


Date Of Report	19/03/2018 09:55
Date Of Accident	17/03/2018 21:50
Exact Location Of Accident	BISHAN ST 11 ONTO BRADELL ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ2959P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE THIAM POH
NRIC No	S1366624E
Email Address	LEETONY@NOVATION.COM.SG
Mobile Phone No	(LOCAL) +65-97367378
Alternative Phone No	OFFICE-97367378
<b>Vehicle Particulars</b>	
Manufacturer	OPEL
Model	OPEL ASTRA 5DR EASYTRONIC 1.0EL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00420800
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE SZE SHUAN MELANIE
NRIC No	S9241543J
Date Of Birth	11/11/1992
Occupation	INDOOR
Date Of Driving Pass	15/11/2011
Driving Experience	6 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97367278
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Sketch Plan

SKETCH PLAN



DISCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS ATTACHED

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18.02.2018

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name

NRIC/PTN No:

## Sketch Plan #3

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 - Please report **correctly** the details of the accident to speed up the claims process.
- 2 - This Form must be **completed by the Policyholder and/or the Authorized Driver**.
- 3 - Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4 - The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - **Any false reporting may be referred to the Police for investigation.**
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8 - Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time 18 MAR 2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Driving License

NEW ZEALAND DRIVING LICENCE



License No: S9241543J  
Name  
LEE SUE PHILIP, MELANIE

Date of Birth: 11 May 1992  
Issue Date: 15 May 2011



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

OTFECTIVE (2011)

Class 1: Motor cars with a gross vehicle weight of 3000kg or less, and  
with not more than 7 passengers, including the driver, and  
OTM motor vehicles with a gross weight of 3000kg



14-204

OWNER IC

1740000



IC NO: S136824E



IC EXPIRES  
17 03-2016

ACTUAL  
140 WEST COAST AVENUE  
SINGAPORE 08793

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S136824E



NAME

LEE THIAM POH

RACE

CHINESE

Date of Birth

21-09-1959

SEX

M

Country of Birth

SINGAPORE

S136824E

Date :20/03/2018

To Whom It May Concern

Dear Sir,

**RE: VEHICLE :SLQ2959P**  
**CHASSIS NO.: W0LB E8EA8H8052241**  
**ENGINE NO.: B1170167HRXX0170**

Name of insured : LEE THIAM POH  
Date of accident.: 17.03.2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Dented</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>new</i>	\$ 312.00
3	4	FRT BONNET STOPED <i>new</i>	\$ 40.00
4	1	FRT BUMPER <i>Distorted</i>	\$ 1,994.00
5	1	FRT BUMPER LOW LIP RH <i>new</i>	\$ 156.00
6	1	FRT BUMPER LOW LIP LH <i>new</i>	\$ 156.00
7	15	FRT BUMPER CLIP <i>new</i>	\$ 97.50
8	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>new</i>	\$ 136.00
9	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
10	1	FRT BUMPER SIDE RETAINER RH - GUIDE <i>new</i>	\$ 136.00
11	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
12	1	FRT BUMPER BRACKET LH <i>new</i>	\$ 192.00
13	1	FRT BUMPER BRACKET RH <i>new</i>	\$ 192.00
14	1	FRT BUMPER BRACKET TOP CENTRE <i>new</i>	\$ 198.00
15	1	FRT BRACE BRACKET CENTRE <i>new</i>	\$ 229.00
16	1	FRT BRACE BRACKET RH <i>new</i>	\$ 118.00
17	1	FRT BRACE BRACKET LH <i>new</i>	\$ 118.00
18	1	FRT BUMPER SPONGE <i>new</i>	\$ 254.00
19	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>new</i>	\$ 798.00
20	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>new</i>	\$ 374.00
21	1	FRT BUMPER PARKING SENSOR <i>new</i>	\$ 272.00
22	1	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 12.00
23	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 394.00
24	1	FRT GRILLE ASSY <i>new</i>	\$ 800.00
25	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
26	1	FRT LOW GRILLE LH <i>new</i>	\$ 132.00
27	1	RH HEADLAMP <i>new</i>	\$ 820.00
28	1	LH HEADLAMP <i>new</i>	\$ 820.00
29	1	LH FOG LAMP <i>new</i>	\$ 434.00
30	1	LH FOG LAMP COVER <i>new</i>	\$ 120.00

31	1	FRT FENDER LH	Broken	\$	682.00	✓
32	1	FRT FENDER BRACKET LH	Not New	\$	192.00	?X
33	1	FRT FENDER INNERSHIELD LH	torn	\$	138.00	✓
34	10	FENDER INNERSHIELD CLIP	in	\$	65.00	✓
35	1	RADIATOR SUPORT PANEL TOP GARNISH RH	from	\$	152.00	+
36	1	RADIATOR SUPORT PANEL TOP GARNISH LH		\$	152.00	+
37	1	RADIATOR SUPORT PANEL TOP	new	\$	334.00	+
38	1	FRT HEADLAMP PANEL LH	Repair	\$	160.00	+
39	1	RADIATOR		\$	1,424.00	+
40	1	RADIATOR COOLANT		\$	164.00	+
41	1	RADIATOR TOP BRACKET LH		\$	124.00	+
42	1	RADIATOR TOP BRACKET RH	new	\$	124.00	+
43	1	RADIATOR TOP MOUTING		\$	18.00	+
44	1	RADIATOR BRACKET LOWER LH		\$	162.00	+
45	1	RADIATOR BRACKET LOWER RH		\$	162.00	+
46	1	A/C CONDENSER		\$	730.00	+
47	1	A/C CONDENSOR AIR GUIDE TOP CENTRE		\$	158.00	+
48	1	A/C CONDENSER AIR GUIDE LH		\$	138.00	+
49	1	INTERCOOLER, TURBOCHARGER		\$	1,060.00	+
50	1	FRT WIPER WASHER TANK	Delud	\$	182.00	+
51	1	FRT WIPER WASHER TANK PUMP	from	\$	214.00	+
52	1	FRT WIPER WASHER TANK NECK		\$	158.00	+

Parts Total: \$ 18,169.50  
Less 10%: \$ 1,816.95  
Total : \$ 16,352.55

**Labour**

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,250.00
2	Carry out spray painting on affected area, Frt bonnet, Frt bumper, Frt suport panel, Frt fender LH, Frt fender RH, Frt door LH	\$ 3,300.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 240.00
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00
5	To remove and refix radiator and conduct pressure test	\$ 260.00
6	Remove and reseal front Off peak license plate	\$ 650.00
7	To refocus headlamp	\$ 180.00

1250 ✓  
1650 ✓  
30 ✓  
+  
+  
120 ✓  
20 ✓

Labour Total : \$ 8,480.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE <i>new</i>	\$ 65.00 <i>30</i>

Other Total: \$ 65.00

*25,654.45* TOTAL: \$ 24,897.55  
 GST (7%): \$ 1,742.83

GRAND TOTAL : \$ 26,640.38

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

*Adrian Lij*  
*p/p 22/03/18*  
*06 Rys.*  
*Exem \$500.*  
*Not Authorized.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



Date :20/03/2018

Reference: OPEL  
Make: ASTRA

To Whom It May Concern

Dear Sir,

**RE: VEHICLE .:SLQ2959P**  
**CHASSIS NO.: W0LB8EA8H8052241**  
**ENGINE NO.: B1170167HRXX0170**

Name of insured .: LEE THIAM POH  
Date of accident.: 17.03.2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Dented</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>new</i>	\$ 312.00
3	4	FRT BONNET STOPED <i>new</i>	\$ 40.00
4	1	FRT BUMPER <i>Distorted</i>	\$ 1,994.00
5	1	FRT BUMPER LOW LIP RH <i>new</i>	\$ 156.00
6	1	FRT BUMPER LOW LIP LH	\$ 156.00
7	15	FRT BUMPER CLIP <i>new</i>	\$ 97.50
8	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>cracked</i>	\$ 136.00
9	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
10	1	FRT BUMPER SIDE RETAINER RH - GUIDE <i>new</i>	\$ 136.00
11	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
12	1	FRT BUMPER BRACKET LH <i>new</i>	\$ 192.00
13	1	FRT BUMPER BRACKET RH <i>new</i>	\$ 192.00
14	1	FRT BUMPER BRACKET TOP CENTRE <i>new</i>	\$ 198.00
15	1	FRT BRACE BRACKET CENTRE	\$ 229.00
16	1	FRT BRACE BRACKET RH <i>new</i>	\$ 118.00
17	1	FRT BRACE BRACKET LH <i>new</i>	\$ 118.00
18	1	FRT BUMPER SPONGE <i>new</i>	\$ 254.00
19	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>new</i>	\$ 798.00
20	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>new</i>	\$ 374.00
21	1	FRT BUMPER PARKING SENSOR <i>new</i>	\$ 272.00
22	1	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 12.00
23	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 394.00
24	1	FRT GRILLE ASSY <i>cracked</i>	\$ 800.00
25	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
26	1	FRT LOW GRILLE LH <i>new</i>	\$ 132.00
27	1	RH HEADLAMP <i>new</i>	\$ 820.00
28	1	LH HEADLAMP <i>new</i>	\$ 820.00
29	1	LH FOG LAMP <i>new</i>	\$ 434.00
30	1	LH FOG LAMP COVER <i>new</i>	\$ 120.00

*Resurveyed Adrian Lim  
20/04/18.*

31	1	FRT FENDER LH <i>Panel</i>		\$ 682.00	✓
32	1	FRT FENDER BRACKET LH		\$ 192.00	?
33	1	FRT FENDER INNERSHIELD LH <i>to in</i>		\$ 138.00	✓
34	10	FENDER INNERSHIELD CLIP <i>in</i>		\$ 65.00	✓
35	1	RADIATOR SUPORT PANEL TOP GARNISH RH <i>from</i>		\$ 152.00	+
36	1	RADIATOR SUPORT PANEL TOP GARNISH LH		\$ 152.00	+
37	1	RADIATOR SUPORT PANEL TOP <i>mark</i>		\$ 334.00	+
38	1	FRT HEADLAMP PANEL LH <i>Repair</i>		\$ 160.00	+
39	1	RADIATOR	}	\$ 1,424.00	+
40	1	RADIATOR COOLANT		\$ 164.00	+
41	1	RADIATOR TOP BRACKET LH		\$ 124.00	+
42	1	RADIATOR TOP BRACKET RH		\$ 124.00	+
43	1	RADIATOR TOP MOUTING		\$ 18.00	+
44	1	RADIATOR BRACKET LOWER LH		\$ 162.00	+
45	1	RADIATOR BRACKET LOWER RH		\$ 162.00	+
46	1	A/C CONDENSER	}	\$ 730.00	+
47	1	A/C CONDENSOR AIR GUIDE TOP CENTRE		\$ 158.00	+
48	1	A/C CONDENSOR AIR GUIDE LH		\$ 138.00	+
49	1	INTERCOOLER, TURBOCHARGER		\$ 1,060.00	+
50	(1)	FRT WIPER WASHER TANK <i>Delud</i>		\$ 182.00	✓
51	1	FRT WIPER WASHER TANK PUMP <i>from</i>		\$ 214.00	+
52	1	FRT WIPER WASHER TANK NECK		\$ 158.00	+

Parts Total: \$ 18,169.50  
Less 10%: \$ 1,816.95  
Total : \$ 16,352.55

### Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ <del>3,200.00</del>	1250
2	Carry out spray painting on affected area, Frt bonnet, Frt bumper, Frt suport panel, Frt fender LH, Frt fender RH, Frt door LH	\$ <del>3,300.00</del>	1650
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ <del>240.00</del>	30
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	X.
5	To remove and refix radiator and conduct pressure test	\$ 260.00	X
6	Remove and reseal front Off peak license plate	\$ <del>050.00</del>	120
7	To refocus headlamp	\$ <del>180.00</del>	30

Labour Total : \$ 8,480.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE <i>per</i>	\$ 65.00 30

Other Total: \$ 65.00

TOTAL: \$ 24,897.55

GST ( 7%): \$ 1,742.83

GRAND TOTAL : \$ 26,640.38

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

*Adria Lj*  
*p/p 22/03/18*

*06 Rys.*

*Exem \$500*

*are Authorized.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:





Wir leben Autos.

FINALIZE

ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: SLQ2959P  
 Chasis No : W0LBE8EA8H8052241  
 Engine No: B1170167HRXX0170  
 Date of accident :17/3/2018

Invoice No:  
 Invoice Date:

DESCRIPTION AMOUNT SGD

**Parts**

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,758.00
2	1	FRT BUMPER	\$ 1,994.00
3	15	FRT BUMPER CLIP	\$ 97.50
4	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
5	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
6	1	FRT BUMPER BRACKET LH	\$ 192.00
7	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
8	1	FRT BRACE BRACKET LH	\$ 118.00
9	1	FRT BUMPER SPONGE	\$ 254.00
10	1	FRT BUMPER REINFORCEMENT UPP ( METAL )	\$ 798.00
11	1	FRT BUMPER REINFORCEMENT LOW ( FIRBE)	\$ 374.00
12	1	FRT GRILLE ASSY	\$ 800.00
13	1	LH HEADLAMP	\$ 820.00
14	1	LH FOG LAMP	\$ 434.00
15	1	LH FOG LAMP COVER	\$ 120.00
16	1	FRT FENDER LH	\$ 682.00
17	1	FRT FENDER INNERSHIELD LH	\$ 138.00
18	10	FENDER INNERSHIELD CLIP	\$ 65.00
19	1	FRT WIPER WASHER TANK	\$ 182.00

**Supplementary**

1	-	FRT HORN LH <i>could</i>	\$ 327.00
2	-	A/C CONDENSER ELECTRONIC AIR GUIDE <i>check</i>	\$ 514.00

Total: \$ 10,107.50  
 Less 10%: \$ 1,010.75  
 Parts Total: \$ 9,096.75

*please get kelinh to check part price.*

**Labour**

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 1,950.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT BONNET , FRT BUMPER , FRT SUPPORT PANEL , FRT FENDER LH , FRT FENDER RH , FRT DOOR LH	\$ 1,650.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 30.00
4	REMOVE AND RESEAL FRONT OFF PEAK LICENSE TEST	\$ 120.00
5	TO REFOCUS HEADLAMP	\$ 30.00

Labour Total : \$ 3,780.00

Other

No.		Price (SGD)
1	1 FRONT NUMBER PLATE	\$ 30.00
2	1	

Other Total : \$ 30.00

Total : \$ 12,906.75  
 Excess: \$ 500.00  
 GST (7%): \$ 868.47  
**Grand Total : \$ 13,275.22**

Yours Faithfully,

---

Kelvin Chew  
 Service Advisor  
 Tel: 68441985 Fax:68445185

**Please check and finalize with me**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
7 Temasek Boulevard, #10-01 Suntec Tower One  
Singapore 038987

Our File No: CS/ICS18005369/AVD3N2

Date: 25/05/2018

#### REFERENCE

Insured/Claimant:	LEE THIAM POH	Policy No:	MPC17A00420800
Date of Loss:	17/03/2018	Nature of Claim:	OD
			Claim No: DMPC1800101H

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ2959P		Engine No:	B1170167HRXX0170
Make & Model:	OPEL ASTRA, 999cc HB (A)		Chassis No:	WOLBE8EAH8052241
Reg. Date:	04/07/2017 (Man. Year: 2017)		Odometer:	4329 km
Colour:	Silver			
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$70,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/45R17		Rear Tyre Size:	225/45R17
Front Left Side:	Bridgestone 6 mm		Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm		Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,174.45	9,126.75	8,047.70	46.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,480.00	3,780.00	4,700.00	55.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,654.45</b>	<b>12,906.75</b>	<b>12,747.70</b>	<b>49.69</b>
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	25,154.45	12,406.75	12,747.70	50.68
<b>+ GST 7.00/7.00% (S\$)</b>	1,760.81	868.47	892.34	50.68
<b>Nett Amount (S\$)</b>	<b>26,915.26</b>	<b>13,275.22</b>	<b>13,640.04</b>	<b>50.68</b>

#### INSPECTION

Date of Assignment:	21/03/2018		
Date Inspected:	22/03/2018	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2018)
<b>Parts:</b> 144	OPEL ASTRA 999cc HB (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ2959P)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BONNET	Dented	1,758.00 FL	*1,758.00 FL
2	1	*FRT BONNET LOCK	Not Necessary	312.00 FL	*- FL
3	1	*FRT BONNET STOPED	Not Necessary	40.00 FL	*- FL
4	1	*FRT BUMPER	Distorted	1,994.00 FL	*1,994.00 FL
5	1	*FRT BUMPER LOW LIP RH	Not Necessary	156.00 FL	*- FL
6	1	*FRT BUMPER LOW LIP LH	Not Necessary	156.00 FL	*- FL
7	15	*FRT BUMPER CLIP	Necessary	97.50 FL	*97.50 FL
8	1	*FRT BUMPER SIDE RETAINER LH-GUIDE	Cracked	136.00 FL	*136.00 FL
9	1	*FRT BUMPER SIDE RETAINER LH-UPP	Cracked	106.00 FL	*106.00 FL
10	1	*FRT BUMPER SIDE RETAINER RH-GUIDE	Not Necessary	136.00 FL	*- FL
11	1	*FRT BUMPER SIDE RETAINER RH-UPP	Not Necessary	106.00 FL	*- FL
12	1	*FRT BUMPER BRACKET LH	Damaged	192.00 FL	*192.00 FL
13	1	*FRT BUMPER BRACKET RH	Not Necessary	192.00 FL	*- FL
14	1	*FRT BUMPER BRACKET TOP CENTRE	Deformed	198.00 FL	*198.00 FL
15	1	*FRT BRACE BRACKET CENTRE	Not Necessary	229.00 FL	*- FL
16	1	*FRT BRACE BRACKET RH	Not Necessary	118.00 FL	*- FL
17	1	*FRT BRACE BRACKET LH	Damaged	118.00 FL	*118.00 FL
18	1	*FRT BUMPER SPONGE	Cracked	254.00 FL	*254.00 FL
19	1	*FRT BUMPER REINFORCEMENT UPP (METAL)	Bent	798.00 FL	*798.00 FL
20	1	*FRT BUMPER REINFORCEMENT LOW (FIRBE)	Deformed	374.00 FL	*374.00 FL
21	1	*FRT BUMPER PARKING SENSOR	Not Necessary	272.00 FL	*- FL
22	1	*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	12.00 FL	*- FL
23	1	*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	394.00 FL	*- FL
24	1	*FRT GRILLE ASSY	Cracked	800.00 FL	*800.00 FL
25	1	*FRT LOW CENTRE GRILLE	Not Necessary	202.00 FL	*- FL
26	1	*FRONT LOW GRILLE LH	Not Necessary	132.00 FL	*- FL
27	1	*RH HEADLAMP	Not Necessary	820.00 FL	*- FL
28	1	*LH HEADLAMP	Cracked	820.00 FL	*820.00 FL
29	1	*LH FOG LAMP	Cut	434.00 FL	*434.00 FL
30	1	*LH FOG LAMP COVER	Missing	120.00 FL	*120.00 FL
31	1	*FRT FENDER LH	Buckled	682.00 FL	*682.00 FL
32	1	*FRT FENDER BRACKET LH	Not Necessary	192.00 FL	*- FL
33	1	*FRT FENDER INNERSHIELD LH	Torn	138.00 FL	*138.00 FL
34	10	*FENDER INNERSHIELD CLIP	Necessary	65.00 FL	*65.00 FL
35	1	*RADIATOR SUPPORT PANEL TOP GARNISH RH	Not Necessary	152.00 FL	*- FL
36	1	*RADIATOR SUPPORT PANEL TOP GARNISH LH	Not Necessary	152.00 FL	*- FL
37	1	*RADIATOR SUPPORT PANEL TOP	Not Necessary	334.00 FL	*- FL
38	1	*FRT HEADLAMP PANEL LH	Repair	160.00 FL	*- FL
39	1	*RADIATOR	Not Necessary	1,424.00 FL	*- FL
40	1	*RADIATOR COOLANT	Not Necessary	164.00 FL	*- FL
41	1	*RADIATOR TOP BRACKET LH	Not Necessary	124.00 FL	*- FL
42	1	*RADIATOR TOP BRACKET RH	Not Necessary	124.00 FL	*- FL
43	1	*RADIATOR TOP MOUNTING	Not Necessary	18.00 FL	*- FL
44	1	*RADIATOR BRACKET LOWER LH	Not Necessary	162.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*RADIATOR BRACKET LOWER RH	Not Necessary	162.00 FL	*- FL
46	1	*A/C CONDENSER	Not Necessary	730.00 FL	*- FL
47	1	*A/C CONDENSER AIR GUIDE TOP CENTRE	Not Necessary	158.00 FL	*- FL
48	1	*A/C CONDENSER AIR GUIDE LH	Not Necessary	138.00 FL	*- FL
49	1	*INTERCOOLER, TURBO CHARGER	Not Necessary	1,060.00 FL	*- FL
50	1	*FRT WIPER WASHER TANK	Deformed	182.00 FL	*182.00 FL
51	1	*FRT WIPER WASHER TANK PUMP	Not Necessary	214.00 FL	*- FL
52	1	*FRT WIPER WASHER TANK NECK	Not Necessary	158.00 FL	*- FL
53	1	*FRT HORN LH	Cracked	327.00 FL	*327.00 FL
54	1	*A/C CONDENSER ELECTRONIC AIR GUIDE	Deformed	514.00 FL	*514.00 FL
55	1	*FRT NUMBER PLATE	Necessary	65.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>19,075.50</b>	<b>10,137.50</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	1,901.05	1,010.75
<b>Total Parts (S\$)</b>	<b>17,174.45</b>	<b>9,126.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	3,250.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA,FRT BONNET,FRT BUMPER,FRT SUPPORT PANEL,FRT FENDER LH,FRT FENDER RH,FRT DOOR LH	New	3,300.00	1,650.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	240.00	30.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR,VACUUM,REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	-
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	260.00	-
6	REMOVE AND RESEAL FRONT OFF PEAK,LICENSE PLATE	New	650.00	120.00
7	TO REFOCUS HEADLAMP	New	180.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,480.00</b>	<b>3,780.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;