

ASS. REC. BY:

REF: CS/MSG18005370 / Gvd3er Special Instruction:

Survivor
Merimen

From (Person):

GQ
Joslin Lim

ASSIGNMENT (Office)

of

MSG

Date/Time: 20/03/2018 @ 8:33am

Estimated Cost:

Bill to:

(1) / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDM 2655G

Insured:

at Workshop m/s

Regent Motors

Tel. 64777 409 / 92782711

of

305 Alexandra Road # 02-01

Policy No:

B27862037 svp

Claim No:

547910

Sum Insured:

Excess:

\$ 700.00

Make of Veh:

D.O.A. 28/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:36am @ 22/3/18

Person Contacted:

GQ

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SDM 2655G - X

26/3/18

Revert by merimen

27/3/18

Authorise repair: Inform repairer to proceed repair not more than \$20K

30/5/18

Final fig \$ 15,531.25 confirmed by email (Recd 6517.25, 30/5)

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005370/Gvd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-03-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SDM 2655G	
Policy No. B27862037SVP	Coverage (\$)		0.00	
Claim No. 547910	Excess (\$)		700.00	
Assign From MERIMEN (JOSLIM LIM)	Assign Date		22/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 28/01/2018	Inspection Date		22/03/2018	
Survey held at	REGENT MOTORS PTE LTD 305 ALEXANDRA ROAD SINGAPORE 159942			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		22 Mar 2018 08:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YEO LIK SENG, ID: S1525971Z, Tel: +6596370414		
Vehicle Reg. No.:	SDM2655G	Date of Loss:	28/01/2018 11:00 - :59
Claim Type:	OD / 547910	Policy/Cover Note No.:	B27862037SVP (Comprehensive) Coverage: 03/03/2017 - 02/03/2018
		Excess:	S\$700.00
Repairer:	Regent Motors (HQ) 305 Alexandra Road, #02-01 Vantage Automotive Centre, 159942 Alexandra - Tel: 64777331		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/03/2018]		
Driver/Custodian:	YEO LIK KIAH (62 / Male), NRIC: S1139293H, Tel: +6597860902		
Adj Asg. Remarks:	Please survey and revert. Vehicle in workshop.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SDM2655G (547910)**

OD

Jan 28 2018 11:00AM

[YEO LIK SENG]

Regent Motors

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 30/05/2018 11:02 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15531.25) - SDM2655G - Claim Handler: Joslin Lim

Approved:15531.25.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 25 May 2018

Preliminary Advice

Vehicle No	: SDM2655G	Accident Date	: 28/01/2018
Make	: FORD MONDEO	Policy No.	: B27862037SVP
Assignment Date	: 22/03/2018	Excess	: S\$700.00
Date of Inspection	: 23/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: REGENT MOTORS (HQ) 305 ALEXANDRA ROAD, #02-01 VANTAGE AUTOMOTIVE CENTRE SINGAPORE 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,048.50	(incl.supplementary \$26)
Revised Amount	:S\$	15,531.25	(incl.supplementary \$26)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	15,531.25	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	94,000.00	
COE / PARF Rebate	:S\$	72,681.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	21,319.00	

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, March 27, 2018 6:27 PM
To: 'Mohamed Shabir Abdul Hamid'
Cc: SUR; Natarajan Kavidha Rajan
Subject: SDM 2655G-DOA: 28/1/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDM 2655G (excess \$700/-)**. Please note that, **the vehicle repair on Part by Part not more than \$20k.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SDM2655G (547910)**

OD

Jan 28 2018 11:00AM

[YEO LIK SENG]

Regent Motors

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/03/2018 08:47 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15925.50) - SDM2655G - Claim Handler: Joslin Lim

Approved:15925.50:Checked items of \$2490.75 to be verified

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 26 Mar 2018

Preliminary Advice

Vehicle No	: SDM2655G	Accident Date	: 28/01/2018
Make	: FORD MONDEO	Policy No.	: B27862037SVP
Assignment Date	: 22/03/2018	Excess	: S\$700.00
Date of Inspection	: 23/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: REGENT MOTORS (HQ) 305 ALEXANDRA ROAD, #02-01 VANTAGE AUTOMOTIVE CENTRE SINGAPORE 159942		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,022.50
Revised Amount	:S\$	15,925.50
Check Items (Estimated)	:S\$	2,490.75
Total	:S\$	18,416.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	72,681.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,319.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Janice Lee (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, March 26, 2018 4:29 PM
To: Mohamed Shabir Abdul Hamid
Cc: SUR; Natarajan Kavidha Rajan
Subject: RE: SDM 2655G-DOA: 28/1/2018

Dear Shabir,

Will get approval from MSIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamed Shabir Abdul Hamid [mailto:shabir.abdul.hamid@simedarby.com.sg]
Sent: Monday, 26 March 2018 4:24 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Natarajan Kavidha Rajan <natarajan.k.rajan@simedarby.com.sg>
Subject: RE: SDM 2655G-DOA: 28/1/2018

Dear Veron,

Please increase to 20k for the repair cost.

I strongly believe we can undertake on a part by part basis.

Do note, that for this case, there may be recovery/ subrogation.

Thank you

Regards,
Mohamed Shabir
Operations Executive
AutoFrance (PEUGEOT) / Regent Motors (FORD)
C/O Vantage Automotive Limited
DID: 6477 7375 HP: 9278 2711

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, March 26, 2018 11:45 AM
To: Mohamed Shabir Abdul Hamid <shabir.abdul.hamid@simedarby.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SDM 2655G-DOA: 28/1/2018

Dear Shabir,

Please check vehicle able to repair at part by part not exceeding \$18K .

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5971Z
Vehicle Details	
Vehicle No.:	SDM2655G
Vehicle to be Exported:	No
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	FORD
Vehicle Model:	MONDEO TITANIUM 2.0 A/T GTDI 240PS S/R
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	EA03123
Chassis No.:	WF0DXXWPCDEA03123
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$28,161.00
Original Registration Date:	03 Mar 2015
First Registration Date:	03 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$31,426.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2025
PARF Rebate Amount:	\$23,569.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$49,112.00
Total Rebate Amount:	\$72,681.00

The information contained herein is correct as at 26 Mar 2018

OK

MVAL18013719 / Vantage Automotive Limited - HQ
ENTRY DATE & TIME: 29/01/2018 11:11
SUBMITTED BY: Mohamed Shabir Bin Abdul Hamid

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 11:11
Date Of Accident	28/01/2018 11:50
Exact Location Of Accident	PIE TOWARDS EXIT 32
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM2655G
Insured/Policyholder	
Name Of Registered Owner	YEO LIK SENG
NRIC No	S1525971Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96370414
Alternative Phone No	Office-96370414

Vehicle Particulars

Manufacturer	FORD
Model	MONDEO-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B 27862037 SVP
Cover Note Number	

Driver

Name of Driver	YEO LIK KIAH
NRIC No	S1139293H
Date Of Birth	13/05/1955
Occupation	INDOOR
Date Of Driving Pass	09/05/1975
Driving Experience	42 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97860902

Fax Number
 Contact Number
 EMail Address EDWARDYEO1228@GMAIL.COM
 Address BLK 254 BUKIT BATOK EAST AVENUE 4 #12-221
 Postcode 650254
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SIBLING
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 Name: : TEO GEOK KHIM
 Gender: : Female
 Passenger 2 Name: : YEO WEI LON
 Gender: : Male
 Passenger 3 Name: : TEO EE BOO
 Gender: : Male

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: SD CARD WITH TRAFFIC POLICE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBK7228H
 Vehicle Make/Model/Colour
 Details Of Properties

3/26/2018

E-FILE

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBK7228H

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBK7228H

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Mashobir
NRIC/FIN No.:

VERBODEN te kopiëren of verspreiden

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

around 1140hrs, I turn out from Jurong Town hall filter lane towards Exit 32. There were a few cars in front of me stopped. I stopped, Suddenly I heard a knock. I came down to check and found the rider lying face down on the left side. I called the ambulance, 2 ambulance were at the scene with the police.

my vehicle was later towed to police compound.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Person's Signature

Name: MOSHOBIR

NRIC/FIN No.:

SARSAR, Version 1.0/Rev 1.0

Sketch Plan #3



SINGAPORE POLICE FORCE
ACKNOWLEDGEMENT SLIP

Ref: Report No: _____

1. SS Ken Lee / AP: 8522 917 8
(Recipient's Name, NRIC or Passport No. / Rank and No.)

of TPA
(Address / Police Station / NPC / NPP)

hereby acknowledge receipt of the below mentioned items of:

- 1 1 x 64 GB Toshiba SD Card.
- 2 _____
- 3 _____
- 4 _____
- 5 _____
- 6 _____
- 7 _____
- 8 _____
- 9 _____
- 10 _____

from YEO LIK KIAN / 2113 929361
(Name, NRIC or Passport No. / Rank and No.)

of Blk 254 BT Road Ave 4 #12-221 S(650254).
(Address / Police Station / NPC / NPP)

on 28/1/18 at 1956.
(Date) (Time)

Witnessed by / * Handed over by:
(* Delete if applicable)

Received by:

[Signature]
(Signature)
YEO LIK KIAN
(Name, NRIC or Passport No. / Rank and No.)
2113 929361

[Signature]
(Signature)
SS Ken Lee
(Name, NRIC or Passport No. / Rank and No.)

Other Remarks: _____

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BG 3610
Date Estimated : 21/03/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Yeo Lik Seng
606 Senja Road
#26-55

Singapore 670606

- ACCOUNT -

24748

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

DESCRIPTION

VALUE

SUNDRIES	✓ 30	150.00
ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)	✓ /	120.00
TO REMOVE AND REFIX REAR REVERSE SENSOR (NETT)	✓ /	120.00
TO REMOVE AN DREFIX REAR REVERSE CAMERA (NETT)	✓ /	150.00
TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER (NETT)	NN X	70.00
TOWING CHARGES (NETT)	✓ /	120.00
TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL	✓ 60	180.00
SEALANT FOR BODY PANELS (NETT) @ \$90.00 PER PANELS	✓ 30	270.00
TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIRS (NETT)	✓ /	500.00
SEALANT FOR REAR WINDSCREEN (NETT)	✓ /	60.00
INNER SEAL FOR REAR WINDSCREEN (NETT)	✓ /	50.00
TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN (NETT)	✓ /	350.00
TO REMOVE AND REFIX REAR Q QUARTER GLASS TO FACILITATE REPAIRS (NETT)	✓ /	260.00
SEALANT FOR QUARTER GLASS (NETT)	✓ /	60.00
INNER SEAL FOR QUARTER GLASS (NETT)	✓ /	50.00
TO REMOVE AND REFIX REAR SPARE TYRE COMPARTMENT, TIRMS BAORDS TO FACILITATE REPAIRS (NETT)	✓ /	450.00
TO REMOVE AND REFIX FUEL TANK INCLUDING CHECK FOR LEAKS TO FACILITATE REPAIRS (NETT)	✓ /	280.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3610
Date Estimated : 21/03/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

DESCRIPTION

VALUE

TO TRANSFER REAR BOOT MECHANIS LOCKS, TRIMS TO FACILITATE REPAIRS (NET)

280.00

TO REMOVE AND REFIX REAR SPEAKER / RADIO PANEL TO FACILITATE REPAIRS (NETT)

280.00

TO REPAIR, REPALCE REAR BUMPER REAR BOOT, REINFORCEMENT, REAR END PANEL, REAR LH FENDER, TO REPAIR LH ROCKER PANEL, BOO LID HINGE AND ALL OTHER AFFECTED AREAS

3,360.00

TO SPRAY PAINT REAR BOOT, BOOT LID HINGER, REAR BUMPER REAR END PANEL, REAR LH FENDER LH ROCKER PANEL AND ALL OTHER AFFECTED AREAS

3,640.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES (NETT)

280.00

Total Labour 1: 11,080.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS73F40110EB	DOOR-LUGG. COMP Blue ? x net SUC	1	1,955.00	25.00	1,466.25
DS73F438A00B	WEATHERSTRIP, RR BONNET ? x SUC	1	170.00	25.00	127.50
DS73F423A40B	PANEL ASSY - LWR BACK FINISHER re	1	1,284.00	25.00	963.00
BT16R310A58A	RR LIC.PLATE INSULATOR net	1	62.00	25.00	46.50
DS7317K835KA	BUMPER ASSY - REAR, PRIMED re	1	1,750.00	25.00	1,312.50
DS7317E899BC	RR BUMPER ISOLATOR <BB> ? x SUC	1	95.00	25.00	71.25
DG9317970DC	RR REINFORCEMENT ? x SUC	1	582.00	25.00	436.50
DS7317B861BC	BRACKET - BUMPER MOUNTING ? x SUC	1	120.00	25.00	90.00
DS7317E911ME	RR MOULDING cut	1	580.00	25.00	435.00
DS7317A894MD	RR BUMPER - EXTENSION, PRIMED re	1	560.00	25.00	420.00
DS7317G771BA	INSERT, LH (MUFFLER W/DUAL EXHAUST) cut	1	285.00	25.00	213.75
DS7317F767JC5RR	BRACKET - BUMPER MOUNTING, LH ? x SUC	1	45.00	25.00	33.75
DS7317A882BF	RR BRACKET - BUMPER MTG, LH ? x SUC	1	107.00	25.00	80.25
DS7317E851BG	RR BPR SIDE MTG BRACKET LH <BB> ? x re	1	109.00	25.00	81.75
DS73F40320RA	PANEL ASSY BACK re	1	190.00	25.00	142.50
DS73F40320SA	PANEL ASSY BACK re	1	190.00	25.00	142.50
DS73F278A93C	PANEL - QUARTER - OUTER LH net	1	1,435.00	25.00	1,076.25
DS73F42004BK	GLASS, REAR net	1	956.00	25.00	717.00
DS73F29701GA	GLASS - QUARTER WINDOW, LHR net	1	481.00	25.00	360.75

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3610
Date Estimated : 21/03/2018
Prepared By : Mohamed Shabir Abdul Hamid

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDM2655G	WF0DXXWPCDEA03123	03/03/2015	Mon 2.0L 4dr	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS73F253A10A	RR WEATHERSTRIP ON BODY,RH/LH J	1	138.00	25.00	103.50
DS73402A16AD	EMBLEM, FORD OVAL, REAR	1	69.00	25.00	51.75
DS7343156AA	NAME PLATE, ECOBOOST	1	59.00	25.00	44.25
DS7342528BA	NAME PLATE, MONDEO BADGE	1	30.00	25.00	22.50
EM2T15K859AA	SENSOR PARKING AID SYS.RUBY RED TC 5DST	2	85.00	25.00	127.50
DG9T15K868HGRR	JUMPER WIRE ASSY - PARKING AID	1	180.00	25.00	135.00
DS7313405DJ	LAMP ASSY - LHR OUTER	1	1,348.00	25.00	1,011.00
DS7313A603KD	LAMP ASSY - LHR INNER	1	1,408.00	25.00	1,056.00
DS73515C0BA	REFLECTOR ASSY, LH	1	82.00	25.00	61.50
6M2A13550AC	LAMP-LIC.PLATE	2	75.00	25.00	112.50
Total Parts :					10,942.50

8 Days.
Not Authorized.
before paint photos.

Excess \$700

23/3/18

Gmo@Qian

21/3/18

And Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after body painting
- To display damaged panel during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Sup: secondary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

22,048.50

Customer Service Officer

Contact

Labour 1	:	11,080.00
Parts	:	10,942.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,541.58
Grand Total	:	23,564.08

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Co. Regs. No. 53055563L GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 119942Service Booking: 6477 7399
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300**SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. BG 152822	Date IN 25/04/2018 Payment Term 30 Days From Invoice Customer Service Advisor Mohamed Shabir Abdul Hamid	Invoice Number Invoice Date Invoice By Mohamed Shabir Abdul Hamid	Page No. 1 of 2
--------------------------------------	--	---	------------------------

CUSTOMER INFORMATION	INVOICE TO 24748
Yeo Lik Seng 806 Serja Road #25-55 Singapore 670608	MSIG Insurance (Singapore) Pte Ltd 18 Raffles Quay #24-01 Hong Leong Building Singapore 048581

REGISTRATION No. SDM2655G	CHASSIS No. WF0DXXWPCDEA03123	STOCK No. 14644	REGISTRATION DATE 03/03/2015	MODEL Mon 2.0L 4dr	MILEAGE 0
-------------------------------------	---	---------------------------	--	------------------------------	---------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	SUNDRIES	1	0.00	30.00
	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING (NETT)	1	0.00	120.00
	TO REMOVE AND REFIX REAR REVERSE SENSOR (NETT)	1	0.00	120.00
	TO REMOVE AN DREFIX REAR REVERSE CAMERA (NETT)	1	0.00	150.00
	TOWING CHARGES (NETT)	1	0.00	120.00
	TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL	1	0.00	60.00
	SEALANT FOR BODY PANELS (NETT) @ \$90.00 PER PANELS	1	0.00	90.00
	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIRS (NETT)	1	0.00	500.00
	SEALANT FOR REAR WINDSCREEN (NETT)	1	0.00	60.00
	INNER SEAL FOR REAR WINDSCREEN (NETT)	1	0.00	50.00
	TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN (NETT)	1	0.00	350.00
	TO REMOVE AND REFIX REAR Q QUARTER GLASS TO FACILITATE REPAIRS (NETT)	1	0.00	260.00
	SEALANT FOR QUARTER GLASS (NETT)	1	0.00	60.00
	INNER SEAL FOR QUARTER GLASS (NETT)	1	0.00	50.00
	TO REMOVE AND REFIX REAR SPARE TYRE COMPARTMENT, TIRMS BAORDS TO FACILITATE REPAIRS (NETT)	1	0.00	450.00
	TO REMOVE AND REFIX FUEL TANK INCLUDING CHECK FOR LEAKS TO FACILITATE REPAIRS (NETT)	1	0.00	280.00
	TO TRANSFER REAR BOOT MECHANIS LOCKS, TRIMS TO FACILITATE REPAIRS (NET)	1	0.00	280.00
	TO REPAIR, REPALCE REAR BUMPER REAR BOOT, REINFORCEMENT, REAR END PANEL, REAR LH FENDER, TO REPAIR LH ROCKER PANEL, BOO LID HINGE AND ALL OTHER AFFECTED AREAS	1	10.00	2,520.00
	TO SPRAY PAINT REAR BOOT, BOOT LID HINGER, REAR BUMPER REAR END PANEL, REAR LH FENDER LH ROCKER PANEL AND ALL OTHER AFFECTED AREAS	1	10.00	1,764.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES (NETT)	1	0.00	280.00
Sub-Total :				7,594.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Company Regs. No. S3055563L GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 139942Service Bookings: 6477 7399
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8388
Fax: 6477 7388**SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. BG 152822	Date IN 25/04/2018	Invoice Number	Page No. 2 of 2
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Mohamed Shabir Abdul Hamid	Invoice By Mohamed Shabir Abdul Hamid	

CODE	DESCRIPTION	UNITS	DISC %	NETT
BT16R310A5BAA	RR LJC PLATE INSULATOR	1	25.00	46.50
DS731340SDJ	LAMP ASSY - LHR OUTER	1	25.00	1,011.00
DS7313A603KD	LAMP ASSY - LHR INNER	1	25.00	1,056.00
DS7317A894MDXWAA	RR BUMPER - EXTENSION, PRIMED	1	25.00	420.00
DS7317E911ME5UAW	RR MOULDING	1	25.00	435.00
DS7317G771BA	INSERT, LH (MUFFLER W/DUAL EXHAUST)	1	25.00	213.75
DS7317K835KAXWAA	BUMPER ASSY - REAR, PRIMED	1	25.00	1,312.50
DS73402A16AD	EMBLEM, FORD OVAL, REAR	1	25.00	51.75
DS7342528BA	NAME PLATE, MONDEO BADGE	1	25.00	22.50
DS7343156AA	NAME PLATE, ECOBOOST	1	25.00	44.25
DS73515C08A	REFLECTOR ASSY, LH	1	25.00	61.50
DS73F423A40BMXWAA	PANEL ASSY - LWR BACK FINISHER	1	25.00	963.00
EM2T15K859AA5DST	SENSOR PARKING AID SYS, RUBY RED TC	2	25.00	127.50
DS73F278A93CA	PANEL-QTR-OUTER LH	1	25.00	1,076.25
DS73F29701GA	GLASS - QUARTER WINDOW, LHR	1	25.00	360.75
DS73F42004BK	GLASS, REAR	1	25.00	717.00
BMS123726AC	TAPE-DECORATIVE	1	25.00	18.00
Sub-Total :				7,937.25

Attending GSO : Mohamed Shabir Abdul Hamid
Should you require further explanation, please reach me at

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	15,531.25
Labour Charges	7,594.00	Less Insurance Excess	S\$	700.00
Parts Charges	7,937.25	GST @ 7%	S\$	1,038.19
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	15,869.44
		Less Deposit/Voucher	S\$	0.00

Computer generated invoice. No signature is required.

Amount Payable**S\$ 15,869.44**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

Raised By Technician	Approved By CSA	Acknowledge By Parts Assistant	Resurvey by	BO Parts: Yes / No ETA: _____
-------------------------	--------------------	-----------------------------------	-------------	--------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 30 May 2018 11:50 AM
To: 'Mohamed Shabir Abdul Hamid'
Cc: SUR; Natarajan Kavidha Rajan; Wong Guo Xiang; Bodyshop
Subject: RE: SDM 2655G-DOA: 28/1/2018

Dear Shabir,

Confirmed repair cost \$ 15,531.25 before EXCESS \$700 & GST @ 8 Repair days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamed Shabir Abdul Hamid [mailto:shabir.abdul.hamid@simedarby.com.sg]
Sent: Wednesday, 23 May 2018 8:16 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Natarajan Kavidha Rajan <natarajan.k.rajan@simedarby.com.sg>; Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>; Bodyshop <bodyshop@simedarby.com.sg>
Subject: RE: SDM 2655G-DOA: 28/1/2018

Dear Veron,

Attached pre invoice, before paint photos, supplementary list and after paint photos

Repair cost \$ 15,531.25 before EXCESS & GST

Repair days 8

Will appreciate your early reply on this case.

Please confirm

Regards,
Mohamed Shabir
Operations Executive
AutoFrance (**PEUGEOT**) / Regent Motors (**FORD**)
C/O **Vantage Automotive Limited**
DID: 6477 7375 HP: 9278 2711

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, May 04, 2018 2:33 PM

To: Mohamed Shabir Abdul Hamid <shabir.abdul.hamid@simedarby.com.sg>; Wong Guo Xiang <wong.guo.xiang@simedarby.com.sg>

Cc: SUR <sur@lkkauto.com>; Natarajan Kavidha Rajan <natarajan.k.rajan@simedarby.com.sg>

Subject: RE: SDM 2655G-DOA: 28/1/2018

Dear Shabir/Guo Xiang,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)

Sent: Tuesday, 27 March 2018 6:27 PM

To: Mohamed Shabir Abdul Hamid <shabir.abdul.hamid@simedarby.com.sg>

Cc: SUR <sur@lkkauto.com>; Natarajan Kavidha Rajan <natarajan.k.rajan@simedarby.com.sg>

Subject: SDM 2655G-DOA: 28/1/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDM 2655G (excess \$700/-)**. Please note that, the vehicle repair on Part by Part not more than \$20k.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		22 Mar 2018 08:33 Edit Adj Rpt	S\$15,531.25 Edit Estimates	S\$15,531.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YEO LIK SENG , ID: S15259712, Tel: +6596370414									
Vehicle Reg. No.: SDM2655G		Date of Loss: 28/01/2018 11:00 - :59 [34 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 547910		Policy/Cover. Note No.: B27862037SVP (Comprehensive) Coverage: 03/03/2017 - 02/03/2018							
		Excess: S\$700.00							
Repairer: Regent Motors (HQ) 305 Alexandra Road, #02-01 Vantage Automotive Centre, 159942 Alexandra - Tel: 64777331									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/04/2018]									
Driver/Custodian: YEO LIK KIAH (62 / Male), NRIC: S1139293H, Tel: +6597860902									
Adj Asp. Remarks: Please survey and revert. Vehicle in workshop.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (30/05/2018): Alert - Adj Mandate Approved (S\$15531.25) - SDM2655G - Claim Handler: Joslin Lim - MSIG_SG (27/03/2018): Alert - Adj Mandate Approved (S\$15925.50) - SDM2655G - Claim Handler: Joslin Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDM2655G (547910)

OD

Jan 28 2018 11:00AM

[YEO LIK SENG]

Regent Motors

Upload Documents Upload Photos Compose New Letter		View View in Browser v		
Assessment Reports		1 per page v ☒		
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	29/01/18 11:21	Accident Statement	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 17:03	Adjuster Immediate Advice	1 Load HTM	
2	25/05/18 10:15	Adjuster Immediate Advice	1 Load HTM	
Photos/Images		3 per page v ☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 11:30	General View	1 Load JPG	☒
2	26/03/18 11:30	General View	1 Load JPG	☒
3	26/03/18 11:30	General View	1 Load JPG	☒
4	26/03/18 11:30	General View	1 Load JPG	☒
5	26/03/18 11:30	General View	1 Load JPG	☒
6	26/03/18 11:31	General View	1 Load JPG	☒
7	26/03/18 11:31	General View	1 Load JPG	☒
8	26/03/18 11:31	General View	1 Load JPG	☒
9	26/03/18 11:31	General View	1 Load JPG	☒
10	26/03/18 11:31	General View	1 Load JPG	☒
11	26/03/18 11:31	General View	1 Load JPG	☒
12	26/03/18 11:31	General View	1 Load JPG	☒
13	26/03/18 11:31	General View	1 Load JPG	☒
14	26/03/18 11:31	General View	1 Load JPG	☒
15	26/03/18 11:31	General View	1 Load JPG	☒
16	26/03/18 11:31	General View	1 Load JPG	☒
17	26/03/18 11:31	General View	1 Load JPG	☒
18	26/03/18 11:31	General View	1 Load JPG	☒
19	26/03/18 11:31	General View	1 Load JPG	☒
20	26/03/18 11:31	General View	1 Load JPG	☒
21	26/03/18 11:31	General View	1 Load JPG	☒
22	26/03/18 11:31	General View	1 Load JPG	☒
23	26/03/18 11:31	General View	1 Load JPG	☒
24	26/03/18 11:31	General View	1 Load JPG	☒
25	26/03/18 11:31	General View	1 Load JPG	☒
26	26/03/18 11:31	General View	1 Load JPG	☒
27	26/03/18 11:31	General View	1 Load JPG	☒
28	26/03/18 11:31	General View	1 Load JPG	☒
29	26/03/18 11:31	General View	1 Load JPG	☒
30	26/03/18 11:31	General View	1 Load JPG	☒
31	26/03/18 11:31	General View	1 Load JPG	☒
32	26/03/18 11:31	General View	1 Load JPG	☒
33	25/05/18 10:01	Reinspection Photo	1 Load JPG	

Assessment Reports				1 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
					☒
34	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
35	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
36	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
37	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
38	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
39	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
40	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
41	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
42	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
43	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
44	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
45	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
46	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
47	25/05/18 10:01	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/03/18 08:28	Regent Motor email + estimate + Enquire on PARF/COE + DL + OI IC + DL	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/03/18 11:31	MARK ESTIMATE	1	Load PDF	
2	25/05/18 10:08	1ST MARK ESTIMATE	1	Load PDF	
3	25/05/18 10:08	SUPPLEMENTARY	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
1	29/01/18 11:21	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
1	29/01/18 11:20	Accident Photo	1	Load JPG	☒
2	29/01/18 11:20	Accident Photo	1	Load JPG	☒
3	29/01/18 11:20	Accident Photo	1	Load JPG	☒
4	29/01/18 11:20	Accident Photo	1	Load JPG	☒
5	29/01/18 11:20	Accident Photo	1	Load JPG	☒
6	29/01/18 11:20	Accident Photo	1	Load JPG	☒
7	29/01/18 11:20	Accident Photo	1	Load JPG	☒
8	29/01/18 11:20	Accident Photo	1	Load JPG	☒
9	29/01/18 11:20	Accident Photo	1	Load JPG	☒
10	29/01/18 11:20	Accident Photo	1	Load JPG	☒
11	29/01/18 11:20	Accident Photo	1	Load JPG	☒
12	29/01/18 11:20	Accident Photo	1	Load JPG	☒
13	29/01/18 11:20	Accident Photo	1	Load JPG	☒
14	29/01/18 11:20	Accident Photo	1	Load JPG	☒
15	29/01/18 11:20	Accident Photo	1	Load JPG	☒
16	29/01/18 11:20	Accident Photo	1	Load JPG	☒
17	29/01/18 11:20	Accident Photo	1	Load JPG	☒
18	29/01/18 11:20	Accident Photo	1	Load JPG	☒
19	29/01/18 11:20	Accident Photo	1	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
20	29/01/18 11:20	Accident Photo		Load JPG	☒
21	29/01/18 11:20	Accident Photo		Load JPG	☒
22	29/01/18 11:20	Accident Photo		Load JPG	☒
23	29/01/18 11:20	Accident Photo		Load JPG	☒
24	29/01/18 11:20	Accident Photo		Load JPG	☒
25	29/01/18 11:20	Accident Photo		Load JPG	☒
26	29/01/18 11:20	Accident Photo		Load JPG	☒
27	29/01/18 11:20	Accident Photo		Load JPG	☒
28	29/01/18 11:20	Accident Photo		Load JPG	☒
29	29/01/18 11:20	Accident Photo		Load JPG	☒
30	29/01/18 11:20	Accident Photo		Load JPG	☒
31	29/01/18 11:20	Accident Photo		Load JPG	☒
32	29/01/18 11:20	Accident Photo		Load JPG	☒
33	29/01/18 11:20	Accident Photo		Load JPG	☒
34	29/01/18 11:20	Accident Photo		Load JPG	☒
35	29/01/18 11:20	Accident Photo		Load JPG	☒
36	29/01/18 11:20	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
1	29/01/18 11:18	Sketch Plan		Load TIF	
2	29/01/18 11:18	Sketch Plan #2		Load TIF	
3	29/01/18 11:18	Sketch Plan #3		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005370/GVD3E2

Date: 04/06/2018

REFERENCE

Insured/Claimant:	YEO LIK SENG	Policy No:	B27862037SVP	Claim No:	547910
Date of Loss:	28/01/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM2655G	Engine No:	EA03123
Make & Model:	FORD MONDEO, 2.0 (A)	Chassis No:	WF0DXXWPCDEA03123
Reg. Date:	03/03/2015 (Man. Year: 2014)	Odometer:	94366 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	S\$94,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,118.50	7,967.25	3,151.25	28.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,930.00	7,564.00	3,366.00	30.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,048.50	15,531.25	6,517.25	29.56
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	21,348.50	14,831.25	6,517.25	30.53
+ GST 7.00/7.00% (S\$)	1,494.40	1,038.19	456.21	30.53
Nett Amount (S\$)	22,842.90	15,869.44	6,973.46	30.53

INSPECTION

Date of Assignment: 22/03/2018
Date Inspected: 23/03/2018 Inspected At:

Regent Motors (HQ)
305 Alexandra Road, #02-01 Vantage
Automotive Centre
Singapore 159942

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
Parts:	143	FORD MONDEO 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDM2655G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*30.00 FS
2	1		*DOOR-LUGG COMP	Serviceable	1,466.25 F	*- F
3	1		*WEATHERSTRIP, RR BONNET	Serviceable	127.50 F	*- F
4	1		*PANEL ASSY, LWR BACK FINISHER	Deformed	963.00 F	*963.00 F
5	1		*RR LIC PLATE INSULATOR	Necessary	46.50 F	*46.50 F
6	1		*BUMPER ASSY- REAR, PRIMED	Deformed	1,312.50 F	*1,312.50 F
7	1		*RR BUMPER ISOLATOR <BB>	Serviceable	71.25 F	*- F
8	1		*RR REINFORCEMENT	Serviceable	436.50 F	*- F
9	1		*BRACKET - BUMPER MOUNTING	Serviceable	90.00 F	*- F
10	1		*RR MOULDING	Cut	435.00 F	*435.00 F
11	1		*RR BUMPER - EXTENSION, PRIMED	Deformed	420.00 F	*420.00 F
12	1		*INSERT (MUFFLER W/DUAL EXHAUST)	Cut	213.75 F	*213.75 F
13	1		*BRACKET - BUMPER MOUNTING, LH	Serviceable	33.75 F	*- F
14	1		*RR BRACKET - BUMPER MTG, LH	Serviceable	80.25 F	*- F
15	1		*RR BPR MTG BRACKET LH <BB>	Repair	81.75 F	*- F
16	1		*PANEL ASSY BACK	Repair	142.50 F	*- F
17	1		*PANEL ASSY BACK	Repair	142.50 F	*- F
18	1		*PANEL - QUARTER - OUTER LH	Buckled	1,076.25 F	*1,076.25 F
19	1		*GLASS, REAR	Necessary	717.00 F	*717.00 F
20	1		*GLASS - QUARTER WINDOW, LHR	Necessary	360.75 F	*360.75 F
21	1		*RR WEATHERSTRIP ON BODY, RH / LH	Serviceable	103.50 F	*- F
22	1		*EMBLEM, FORD OVAL, REAR	Necessary	51.75 F	*51.75 F
23	1		*NAME PLATE, ECOBOOST	Necessary	44.25 F	*44.25 F
24	1		*NAME PLATE, MONDEO BADGE	Necessary	22.50 F	*22.50 F
25	2		*SENSOR PARKING AID SYS, RUBY RED TC	Damaged	127.50 F	*127.50 F
26	1		*RR BUMPER WIRE ASSY, PARKING AID	Not Necessary	135.00 F	*- F
27	1		*LAMP ASSY - LHR OUTER	Cracked	1,011.00 F	*1,011.00 F
28	1		*LAMP ASSY - LHR INNER	Cracked	1,056.00 F	*1,056.00 F
29	1		*REFLECTOR ASSY, LH	Cracked	61.50 F	*61.50 F
30	2		*LAMP - LIC PLATE	Not Necessary	112.50 F	*- F
31	1		*TAPE - DECORATIVE	Necessary	26.00 F	*18.00 F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,118.50 7,967.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	New	120.00	120.00
2	TO REMOVE AND REFIX REAR REVERSE SENSOR	New	120.00	120.00
3	TO REMOVE AND REFIX REAR REVERSE CAMERA	New	150.00	150.00
4	TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER	New	70.00	0.00
5	TOWING CHARGES	New	120.00	120.00
6	TUFF KOTE - BODY CAVITY PRESERVATION (NETT) @ \$60.00 PER PANEL	New	180.00	60.00
7	SEALANT FOR BODY PANEL (NETT) @ \$90.00 PER PANELS	New	270.00	90.00
8	TO REMOVE AND REFIX REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	500.00
9	SEALANT FOR REAR WINDSCREEN	New	60.00	60.00
10	INNER SEAL FOR REAR WINDSCREEN	New	50.00	50.00
11	TO SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR WINDSCREEN	New	350.00	350.00
12	TO REMOVE AND REFIX REAR Q QUARTER GLASS TO FACILITATE REPAIRS	New	260.00	260.00
13	SEALANT FOR QUARTER GLASS	New	60.00	60.00
14	INNER SEAL FOR QUARTER GLASS	New	50.00	50.00
15	TO REMOVE AND REFIX FUEL TANK INCLUDING CHECK FOR LEAKS TO FACILITATE REPAIRS	New	280.00	280.00
16	TO TRANSFER REAR BOOT MECHANIS LOCKS, TRIMS TO FACILITATE REPAIRS	New	280.00	280.00
17	TO REMOVE AND REFIX REAR SPEAKER / RADIO PANEL TP FACILITATE REPAIRS	New	280.00	0.00
18	TO REPAIR, REPLACE REAR BUMPER REAR BOOT, REINFORCEMENT, REAR END PANEL, REAR LH FENDER, TO REPAIR LH ROCKER PANEL, BOOT LID HINGE AND ALL OTHER AFFECTED AREAS	New	3,360.00	2,520.00
19	TO SPRAY PAINT REAR BOOT, BOOT LID HINGER, REAR BUMPER REAR END PANEL, REAR LH FENDER LH ROCKER PANEL AND ALL OTHER AFFECTED AREAS	New	3,640.00	1,764.00
20	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES	New	280.00	280.00
21	TO REMOVE AND REFIX REAR SPARE TYRE COMPARTMENT, TRIMS BOARDS TO FACILITATE REPAIRS	New	450.00	450.00
Gross Labour Cost (\$\$)			10,930.00	7,564.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >