



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR TANG HAN FATT BLK 247 YISHUN AVE 9 #11-181 SINGAPORE 760247 Contact No Mobile: 90097998	Cust No/Name	/MR TANG HAN FATT
	Reg No/Reg Date	SLW9888H / 11/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MJ5756011
	Engine No	G4FGHH688189
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	20/03/2018/ 20:39		465 / Tay Jian Ye	25275

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT BUMPER , FRT RH FENDER.				1100 1650.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER, FRT RH FENDER				840 1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 200.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION				? 80.00
M SUNDRY SUNDRIES				20 50.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	00.00	? 84.00
M COVER-FR BUMPER	1.00	633.00	00.00	de 633.00
M DUCT ASSY-AIR CURTAIN,RH	1.00	6.00	00.00	? 6.00
M AIR DUCT-FR BUMPER,RH	1.00	33.00	00.00	? 33.00
M RESERVOIR & PUMP ASSY-WASHER	1.00	125.00	00.00	? 125.00
M LAMP ASSY-HEAD,RH	1.00	1523.00	00.00	ant 1523.00
M PANEL-FENDER,RH	1.00	396.00	00.00	bb 396.00
M GUARD ASSY-FRONT WHEEL,RH	1.00	95.00	00.00	? 95.00

SURVEYOR NAME: Tay Jian YeSURVEYOR SIGNATURE: [Signature]DATE: 26/3/18 @ 1520REMARKS: 'W' Resurvey before paint
Sw @ 1 hour. 4 daysLKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be resurveyed and is subject to final approval by the repairer's company

Authorized signatory and company stamp

Nett 6,185.00
7% GST on 6185.00 432.95
Total Payable 6,617.95

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.