

15/03/2018

INS. CASE OWNER:

NATURE

CC 4 / III 1800 5383, R1443

LKK:  
IDAC:

Surveyor:

RASUL

DOI:

ASSIGNMENT  
09/04/18

Date / Time:

21/7/18  
21/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHD 2164A

Claim No. : H0218030672

Name of Insured : CPE

Policy No. : M120015

Insured Tel No. : HP:

Make / Model : HUNDMY1

Excess Sec II :SS D.O.A : 21/7/18

Place of Accident : 411 Ulu Karang Rd Tms Upp  
Thomson Rd by St 65

Is driver the owner? (YES / NO) Nature of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age : JASWANT 51M

Insured Liability : % Final ? Yes / No

Driver Tel No. : (VL: YES / NO)

SET 92804



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Performance



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
21/7/18	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	vic
	After call Itr to OI:	
22/03/18	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup):	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: P/P SS 3,190.80 (3 days) Reduction: 44 % Email Call

FINAL SETTLEMENT Date/Time: 08/08/18 Confirm with: CAROLINE Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:

Repair Cost: (w/loss) SS 3,725.16 COPY SENT

Loss of Rental (LOR): SS - ( days) 1) Claim status: Normal/Reject/Private Settle

Loss of Use (LOU): SS 300.00 (100 x 3 days) 2) Report Format:

Loss of Income (LOI): SS - (5 x days) 3) Survey fee: 4300.00

LOR only [ ] LOU only [ ] LOR + LOU [ ] LOR + LOI [ ] (Tick only one)

GIALTA Search: SS -

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost: SS -

Total: SS 4,035.16 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 4,035.16 Name 1: PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.) SS - Name 2: -

Payee 3: (Strike if N.A.) SS - Name 3: -





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R. GST Reg. No. 19-9607198-R.

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18005383/hb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 22-03-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3164A	Veh. Inspected	SKT 9380H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/03/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# Performance Motors Limited

A member of the Slim Darby Group  
Co. Reg. No. 197451519W GST Reg. No M2-0020081-X



395, Alexandra Road  
Slim Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747779

289, Kampong Arang Road  
East Coast Centre  
Singapore 478190  
Tel: 63190888 (AfterSales)  
Fax: 63449773

319, Alexandra Road  
Slim Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64798601 (AfterSales)  
64798624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

22 MAR 2018

Estimate No. : b1 46342 Page No. : 1 of 2  
Date Estimated : 22/03/2018  
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Choong Chan Yong  
8C Clifton Vale

singapore 359680

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0

DESCRIPTION

To replace rear bumper, rear bumper lower and all attachments cause by accident

VALUE  
~~850-2,580.00~~

Painting on rear bumper assembly

~~934-1,028.00~~

To check electrical wiring systems at the rear section for proper function.

~~150-177.00~~

Sundries. *N/A*

~~80-40-89.00~~

Total Labour 1: 3,845.00

DESCRIPTION

RR BUMPER CARRIER ECE  
REAR BUMPER CENTRE GUIDE  
COVER  
RR BUMPER LH SIDE GUIDE  
RR BUMPER RH SIDE GUIDE  
TRIM PANEL BUMPER REAR BOTTOM (M)  
TRIM PANEL BUMPER REAR BOTTOM (ZWEI)  
REAR BUMPER PANEL PRIMED (M/PDC)  
SET MOUNTS PDC SENSOR REAR (M)  
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
1	432.90	432.90x
1	55.40	55.40x
1	61.00	61.00x
1	48.10	48.10x
1	48.10	48.10x
1	212.50	212.50x
1	212.50	212.50x
1	1,264.30	1,264.30x
1	62.95	62.95x
4	5.05	20.20x

*sub* }  
*cut* }  
*m reported* }  
*DE* }  
*sub* }

Total Parts : 2,417.95

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401119W GST Reg. No. WC-0020081-X



337, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

290, Kampong Arang Road  
East Coast Centre  
Singapore 438190  
Tel: 63190888 (AfterSales)  
Fax: 63449773

317, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190538 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64794601 (AfterSales)  
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 46342  
Date Estimated : 22/03/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Claims OD / 3rd Party / Uninsured Driver / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time: 02/04/18 @ 14:15 Excess Of \_\_\_\_\_  
Surveyor's Name: RAME Sign \_\_\_\_\_  
Surveyor's Tel: 90010068 Authorized Yes / No \_\_\_\_\_  
Authorized Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes / No  
Surveyor's E-mail \_\_\_\_\_  
No. of Working Days Required: 3 days

Labour 1	:	3,845.00
Parts	:	2,417.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	438.41
<b>Grand Total</b>	:	<b>6,701.36</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

6,701.36

# Performance Motors Limited

A member of the Sims Derby Group  
Co. Reg No. 197401559W, GST Reg. No. M0-0020081-X



## FINAL REPORT

Estimate No. : b1 46342  
Date Estimated : 22/03/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Choong Chan Yong  
8C Clifton Vale

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

singapore 359680

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
TRIM PANEL BUMPER REAR BOTTOM (M)	212.50	1.00		212.50
REAR BUMPER PANEL PRIMED (M/PDC)	1,264.30	1.00		1,264.30

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,476.80
Total Labour & Parts :	3,490.80
Deduction for Excess :	
Total Repair Costs less Excess:	3,490.80 ✓
GST @7%:	244.36
Grand Total :	3,735.16

# Performance Motors Limited

A member of the Stone Dairy Group  
Co. Reg. No. 197401599W GST Reg. No. M0-0020081-X



## FINAL REPORT

Estimate No. : b1 46342  
Date Estimated : 22/03/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Choong Chan Yong  
8C Clifton Vale

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

singapore 359680

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	4281A GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
TRIM PANEL BUMPER REAR BOTTOM (M)	212.50	1.00		212.50
REAR BUMPER PANEL PRIMED (M/PDC)	1,264.30	1.00		1,264.30

### # SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,476.80
Total Labour & Parts :	3,490.80
Deduction for Excess :	
Total Repair Costs less Excess:	3,490.80
GST @7%:	244.36
Grand Total :	3,735.16

## Vic (LKKAuto)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 18 May, 2018 5:40 PM  
**To:** Rasul (LKKAuto); Vic (LKKAuto)  
**Subject:** FINAL REPORT / SKT9380H  
**Attachments:** Final Report SKT9380H.pdf

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00  
Total Parts : 1,476.80  
Total Labour & Parts : 3,490.80

Repair days: 3

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Print Received Message

This mail is associated with :

**\*SKT9380H (MCT18030672)  
[SHD3164A]**

TP

CHOONG CHAN YONG

Mar 21 2018 2:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 07/08/2018 11:18 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4035.16) - SKT9380H - Claim Handler: NATALIE LEE

Approved:4035.16.

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197431189W GST Reg. No. M2-0020081-X

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190190 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

188, Kangkong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

113, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190138 (AfterSales)  
63190133/530 (Motorrad)  
Fax. 64796011 (AfterSales)  
64796034 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

1257484

22 MAR 2018

Estimate No. : b1 46342  
Date Estimated : 22/03/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Choong Chan Yong  
8C Clifton Vale

singapore 359680

## - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0

## DESCRIPTION

To replace rear bumper, rear bumper lower and all  
attachments cause by accident

850 ~~2,500.00~~

Finishing on rear bumper assembly

934 ~~1,028.00~~

Check electrical wiring systems at the rear section  
for proper function.

150 ~~177.00~~

ries.

40 ~~88.00~~

Total Labour 1: 3,845.00

## DESCRIPTION

BUMPER CARRIER ECE

QTY PRIC VALUE

REAR BUMPER CENTRE GUIDE

1 432.90 ? 432.90

BUMPER LOWER

1 55.40 ? 55.40

BUMPER LH SIDE GUIDE

1 61.00 ? 61.00

BUMPER RH SIDE GUIDE

1 48.10 ? 48.10

BUMPER PANEL BUMPER REAR BOTTOM (M)

1 48.10 ? 48.10

BUMPER PANEL BUMPER REAR BOTTOM (ZWEI)

1 212.50 ? 212.50

BUMPER PANEL PRIMED (M/PDC)

1 212.50 ? 212.50

MOUNTS PDC SENSOR REAR (M)

1 1,264.30 ? 1,264.30

COUPLING RING PDC TORQUE CONVERTE

1 62.95 ? 62.95

4 5.05 ? 20.20

Total Parts : 2,417.95



(vic)

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref :

Our Ref :

Date : 26 July 2018

Subject : **ACCIDENT INVOLVING VEHICLES SKT9380H & SHD3164A ON 21.03.2018**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	: S\$ 3735.16
Loss of use	: S\$ 300.00 (S\$ 100.00 x 3 days )
Total	: S\$ 4035.16

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-2699)

[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales  
6319 0527  
Fax 6479 6624

280  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.  
197401569W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg).

Yours sincerely

Teng Wai Khan  
Customer Service Manager, Body & Paint

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKT 9380H & SHD 3164A ON 21/3/18.

I, Choong Chan Yong owner of Vehicle Registration No. SKT 9380H hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: \_\_\_\_\_ (Date)

NRIC No.:

In the presence of:

Name: \_\_\_\_\_ (Date)

NRIC No.:

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MOT18030672  
Claimant Ref: SKT9380H

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,735.16 (repair cost), S\$ 300.00 (loss of use/~~rental~~), S\$ — (search fee), vehicle no. SKT9380H that was damaged pursuant to the accident which occurred on 21/03/18 (date) at YIO CHU KANG ROAD (location) involving vehicle no. SHD5164A (insured vehicle). This is pursuant to the inspection conducted on 09/04/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHOONG CHAN YONG ("the third party claimant") of vehicle no. SKT9380H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKT9380H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,035.16 to PERFORMANCE MOTORS LIMITED

Dated this 08 day of 08 20 18

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Wong Yit Loong  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Signed by Wong Yit Loong (with chop)

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



MOR

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

19907196R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No MI-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

290, Kampong Arang Road  
East Coast Centre  
Singapore 438188  
Tel. 63190888 (AfterSales)  
Fax. 63449771

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796001 (AfterSales)  
64796024 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1257484</b>	Page No. : <b>1 of 2</b>
Date IN : <b>09/04/2018</b>	Invoice Number : <b>1987305 / WSB</b>
Cust. Svc. Advisor: <b>Kevin Leong Wai Kit</b>	Invoice Date : <b>17/07/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

**- CUSTOMER INFORMATION -**

Mr Choong Chan Yong  
8C Clifton Vale

singapore 359680

**- INVOICE TO - 219**

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

REGN. NO. <b>SKT9380H</b>	CHASSIS NO. <b>GA69392</b>	REGN. DATE <b>26/06/2015</b>	MODEL <b>428IA GC</b>	MILEAGE <b>31029</b>
------------------------------	-------------------------------	---------------------------------	--------------------------	-------------------------

**--- LABOUR 1 ---**

To replace rear bumper and bottom piece including to remove and install body parts in order to carry out painting job.	850.00	<b>NETT</b>
To respray rear bumper.	934.00	
To check electrical wiring systems at the rear section for proper function.	150.00	
Sundries.	80.00	
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT. DATE OF ACCIDENT : 21.3.2018. 3RD PARTY CAR : SHD3164A. YOUR REF NO : NIL.	0.00	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 9.4.2018 AT 2.15 PM. AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON 26.3.2018 VIA E-MAIL. PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00	
<b>Total Labour 1:</b>	<b>2,014.00</b>	

**--- PARTS ---**

	Qty	Retail Price	NETT
TRIM PANEL BUMPER REAR BOTTOM (M)	1	212.50	212.50
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,264.30	1,264.30
<b>Total Parts :</b>			<b>1,476.80</b>

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M3-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel. 63190190 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1257484</b>	Page No. : <b>2 of 2</b>
Date IN : <b>09/04/2018</b>	Invoice Number : <b>1987305 / WSB</b>
Cust. Svc. Advisor: <b>Kevin Leong Wai Kit</b>	Invoice Date : <b>17/07/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>1,934.00</b>	Total Labour & Parts Charges : <b>S\$ 3,490.80</b>
Parts Charges : <b>1,476.80</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 3,490.80</b>
	GST @ 7% : <b>S\$ 244.36</b>
	Invoice Total Amount Include GST : <b>S\$ 3,735.16</b>

Computer generated invoice. No signature is required.	Amount Payable Include GST : <b>S\$ 3,735.16</b>
-------------------------------------------------------	--------------------------------------------------

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018 <a href="#">Edit Reg</a>		22 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,490.80</b> <a href="#">Edit Estimates</a>	<b>S\$3,490.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	CHOONG CHAN YONG, ID: S1293673G								
Vehicle Reg. No.:	SKT9380H	Date of Loss:	21/03/2018 14:00 - :59 [32 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18030672	Policy/Cover Note No.:	MCOM0016						
Vehicle Reg. No. (Insured):	SHD3164A	Policy No. (Claimant):	CN827273						
Excess:									
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>III_SG (07/08/2018): Alert - Adj Mandate Approved (S\$4035.16) - SKT9380H - Claim Handler: NATALIE LEE</li> <li>III_SG (23/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SKT9380H - Claim Handler: NATALIE LEE</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKT9380H (MCT18030672)  
[SHD3164A]  
TP  
CHOONG CHAN YONG  
Mar 21 2018 2:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View	
							View in Browser	
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	13/07/18 14:16	<b>Odometer Reading</b>		Load JPG	<input checked="" type="checkbox"/>			
2	13/07/18 14:16	<b>Chassis Number</b>		Load JPG	<input checked="" type="checkbox"/>			
3	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
4	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
5	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
6	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
7	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
8	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
9	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
10	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
11	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
12	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
13	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
14	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
15	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
16	13/07/18 14:16	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>			
<b>Documentation</b>							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	22/03/18 15:35	<b>TP ESTIMATE</b>		Load TIF				
2	22/03/18 15:35	<b>TP GIA REPORT</b>		Load PDF				
3	12/04/18 17:40	<b>TP ESTIMATE- MARKED</b>		Load PDF				
4	01/08/18 14:34	<b>WORKSHOP INVOICE</b>		Load PDF				
5	01/08/18 14:34	<b>LOD</b>		Load PDF				
6	14/08/18 16:23	<b>DISCHARGE VOUCHER</b>		Load PDF				
7	14/08/18 16:23	<b>AUTHORISATION TO ACT FORM</b>		Load PDF				
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	23/03/18 08:43	<b>Singapore Accident Statement</b>		Load PDF				

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To:  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18005383/R1HB3Q2

Date: 14/08/2018

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016  
 Claimant Vehicle No: SKT9380H Insured Vehicle No: SHD3164A  
 Date of Loss: 21/03/2018 Nature of Claim: TP Claim No: MCT18030672

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKT9380H  
 Make & Model: BMW 428i, 2.0 Coupe (A) Engine No: B2280979N20B20A  
 Reg. Date: 26/06/2015 (Man. Year: 2014) Chassis No: WBA4A52010GA69392  
 Colour: Blue Odometer: 31029 km  
 Engine Capacity: 1997 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,442.55	1,556.80	885.75	36.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,207.55</b>	<b>3,490.80</b>	<b>2,716.75</b>	<b>43.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>434.53</b>	<b>244.36</b>	<b>190.17</b>	<b>43.76</b>
<b>Nett Amount (S\$)</b>	<b>6,642.08</b>	<b>3,735.16</b>	<b>2,906.92</b>	<b>43.77</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		<b>300.00</b>		
	<b>Nett Liability (S\$)</b>	<b>4,035.16</b>		

## INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 09/04/2018 Inspected At:

Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby  
 Performance Centre  
 Singapore 159941

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
<b>Parts:</b> M1-COUPE	BMW 428i 2.0 Coupe (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKT9380H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RR BUMPER CARRIER ECE	Serviceable	432.90 FS	*- FS
3	1		*COVER	Serviceable	61.00 FS	*- FS
4	1		*RR BUMPER LH SIDE GUIDE	Serviceable	48.10 FS	*- FS
5	1		*RR BUMPER RH SIDE GUIDE	Serviceable	48.10 FS	*- FS
6	1		*TRIM PANEL BUMPER REAR BOTTOM (M)	Cut	212.50 FS	*212.50 FS
7	1		*TRIM PANEL BUMPER REAR BOTTOM (ZWEI)	Not Necessary	212.50 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Deformed	1,264.30 FS	*1,264.30 FS
9	1		*SET MOUNTS PDC SENSOR REAR (M)	Serviceable	62.95 FS	*- FS
10	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS
<b>Total Parts (S\$)</b>					<b>2,442.55</b>	<b>1,556.80</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,REAR BUMPER LOWER AND ALL ATTACHMENTS CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
			<hr/>	
<b>Gross Labour Cost (S\$)</b>			<b>3,765.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >