

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

22 MAR 2018

Estimate No. : b1 46342	Page No. : 1 of 2
Date Estimated : 22/03/2018	
Prepared By : Kevin Leong Wai Kit	

<p>- ESTIMATE REPAIR FOR - Choong Chan Yong 8C Clifton Vale singapore 359680</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0

DESCRIPTION	VALUE
To replace rear bumper, rear bumper lower and all attachments cause by accident	850 2,580.00
Painting on rear bumper assembly	934 1,038.00
To check electrical wiring systems at the rear section for proper function.	150 177.00
Sundries.	40 80.00
Total Labour 1:	3,845.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER ECE	1	432.90	? 432.90
REAR BUMPER CENTRE GUIDE COVER	1	55.40	? 55.40
RR BUMPER LH SIDE GUIDE	1	61.00	? 61.00
RR BUMPER RH SIDE GUIDE	1	48.10	? 48.10
TRIM PANEL BUMPER REAR BOTTOM (M)	1	48.10	? 48.10
TRIM PANEL BUMPER REAR BOTTOM (ZWEI)	1	212.50	cut / 212.50
REAR BUMPER PANEL PRIMED (M/PDC)	1	212.50	repeated X 212.50
SET MOUNTS PDC SENSOR REAR (M)	1	1,264.30	DE 1,264.30
DECOUPLING RING PDC TORQUE CONVERTE	1	62.95	? 62.95
	4	5.05	? 20.20
Total Parts :			2,417.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46342	Page No. :	2 of 2
Date Estimated	: 22/03/2018		
Prepared By	: Kevin Leong Wai Kit		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9380H	GA69392	26/06/2015	428IA GC	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 02/04/18 P 1415 Excess S\$ _____

Surveyor's Name RAME Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,845.00
Parts	:	2,417.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	438.41
Grand Total	:	6,701.36

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **