



## FINAL REPORT

Estimate No. : **b1 46289**  
Date Estimated : 20/03/2018  
Prepared By : Chua Kee Sin

Page No. :

**REPAIR FOR -**  
Cheryl Chen Qiaomin  
1007 Lower Delta Road  
#05-03

**- ACCOUNT - 303**  
MS First Capital Insurance Limited  
6 Raffles Quay  
#21-00  
Singapore 048580

Singapore 099310

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLP7738H	5H46317	07/06/2017	216d G TOURER	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dents caused by the accident		850.00		850.00
To spray paint front bumper		934.00		934.00
To supply front emboss number plate.		83.00		83.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
GRILLE BUMPER MIDDLE CLOSED (PDC)	96.20	1.00		96.20
# LH FINISHER (LUXURY LINE) *	52.55	1.00		52.55
# RH FINISHER (LUXURY LINE) *	52.55	1.00		52.55
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
# LICENCE PLATE HOLDER *	68.95	1.00		68.95
FRT LH GRILLE (LUXURY)	86.05	1.00		86.05
FRT RH GRILLE (LUXURY)	86.05	1.00		86.05
PLAQUE 82MM	69.50	1.00		69.50

### # SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,353.85
Total Labour & Parts :	3,450.85
Deduction for Excess :	
Total Repair Costs less Excess:	3,450.85
GST @7%:	241.56
Grand Total :	3,692.41