

INS. CASE OWNER:

CC 4 RSM
AXA1800

5396

LKK:
IDAC:

Survivor:

Kenneth

DOI:

ASSIGNMENT

7/7/18

Date / Time :

2/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SKU 717A

Name of Insured :

Yong YEE Fook

Insured Tel No. :

HP:

8428842

Excess Sec II :\$S

D.O.A :

14/7/18

Is driver the owner?

(YES / NO)

Nature of Accident :

ME 1

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SUR 52778

INSRS:
WSP:
Tel :
Liability :
RMKS:

Optima

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
23/7/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	280320.8 P CH 2/9/18
	After call ltr to OI:	
280320.8 @ 3-37pm	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE	Date/Time: 7/7/18	Sent By: Jm
28/02/19	- AXA APPROVED REPAIR WORKS.	
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: 181	\$S 4,700.20 (6 days)	Reduction: 18 %
FINAL SETTLEMENT	Date/Time: 10/4/19	Confirm with: SHARON
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: 27
Repair Cost (w/ tax)	\$S 5032.42	
Loss of Rental (LOR) (w/ tax)	\$S 749.00 (7 days) x 100 + 6.50	
Loss of Use (LOU):	\$S - (S x days)	
Loss of Income (LOI):	\$S - (S x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	\$S -	
Medical:	\$S -	
Disbursement:	\$S - (e.g. Tow/ Independent)	
Legal Cost	\$S -	
Total:	\$S 5,781.42	Global Sum \$S: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S 5,781.42	Name 1: OPTIMA WORKS PTE LTD
Payee 2: (Strike if N.A.)	\$S -	Name 2: -
Payee 3: (Strike if N.A.)	\$S -	Name 3: -

ASS. REC. BY:

REF:

ADA/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 52778

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

c.c.

1496

Colour

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

011746

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gm 6.1002801

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

19/3/18

D.O.I.

21/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/3

R/L parts to Carman

31/3/18

Confirm 2-B.2 #4703.20 with 6 working days

(R/L) #4703.04
(18.1)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18005396/Kkb3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 22-03-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 717A	Veh. Inspected	SLR 5277Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/03/2018	Inspection Date	21/03/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Kw

618

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: AXA

Vehicle No: SLR5277Z

Third Party Veh No: SKU717A

Model: HONDA GRACE 1.5 LX CVT

Date of Accident: 19/03/2018

Chassis: GM61002801

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	REAR BOOT LID		B1 \$594.50	✓
1	REAR BOOT LID LOGO EMBLEM		re \$23.10	✓
2	REAR BOOT LID LOGO EMBLEM CLIP	\$5.80	re \$11.60	✓
1	REAR BOOT LID GRACE EMBLEM		re \$53.60	✓
1	REAR BOOT LID REFLECTOR LAMP LH	\$306.70	re \$36.80	✓
1	REAR BOOT LID HINGE LH		re \$67.90	X
12	REAR BOOT LID INNER UPHOLSTERY TRIM CLIP	\$5.90	re \$70.80	X
1	REAR BOOT LID MECHANISM LOCK		D11 \$199.50	7✓
1	REAR BOOT LID WEATHERSTRIP		re \$99.60	✓
1	REAR TAILLAMP LH		re \$481.10	✓
1	REAR TAILLAMP INNER PANEL LH		B1 \$105.40	7✓
1	REAR BUMPER		re \$663.70	✓
2	REAR BUMPER SIDE RETAINER LH + RH	also D11 \$27.50	\$55.00	4+
10	REAR BUMPER CLIP	\$3.90	re \$39.00	✓
1	REAR END PANEL		re \$423.90	✓
1	REAR END PANEL INNER TOP GARNISH		D11 \$96.60	✓
4	REAR END PANEL INNER TOP GARNISH CLIP	\$5.90	re \$23.60	✓
1	REAR WELL PANEL INNER TOP TOOL SPONGE		return \$180.50	✓
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD		return \$286.60	7✓
SUB TOTAL			\$3,512.80	3616.50
Less 20%			\$702.56	723.30
PARTS TOTAL			\$2,810.24	2893.20

Not Withain
1.B.1
Return B4 parts
6 days

84703.20

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR		re \$560.00
1	REAR WELL PANEL INSULATOR MAT		re \$150.00
S/N TOTAL			\$710.00

2005m
7X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: AXA

Vehicle No: SLR5277Z

Third Party Veh No: SKU717A

Model: HONDA GRACE 1.5 LX CVT

Date of Accident: 19/03/2018

Chassis: GM61002801

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$800.00	700
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00	720
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	50
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	~ \$280.00	X
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$220.00	80

LABOUR TOTAL \$2,220.00 1240

WINSON

TOTAL

\$5,740.24

P - 2893.20

S/N - 200.00

L - 1890.00

plp \$4983.20

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: AXA

Vehicle No: SLR5277Z

Third Party Veh No: SKU717A

Model: HONDA GRACE 1.5 LX CVT

Date of Accident: 19/03/2018

Chassis: GM61002801

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BOOT LID		<i>B1</i> \$594.50
1	REAR BOOT LID LOGO EMBLEM		<i>re</i> \$23.10
2	REAR BOOT LID LOGO EMBLEM CLIP	\$5.80	<i>re</i> \$11.60
1	REAR BOOT LID GRACE EMBLEM		<i>re</i> \$53.60
1	REAR BOOT LID REFLECTOR LAMP LH	\$407.60 <i>gm</i>	\$36.80
1	REAR BOOT LID HINGE LH		<i>re</i> \$67.90
12	REAR BOOT LID INNER UPHOLSTERY TRIM CLIP	\$5.90	<i>re</i> \$70.80
1	REAR BOOT LID MECHANISM LOCK		\$199.50
1	REAR BOOT LID WEATHERSTRIP		<i>re</i> \$99.60
1	REAR TAILLAMP LH		<i>re</i> \$481.10
1	REAR TAILLAMP INNER PANEL LH		\$105.40
1	REAR BUMPER		<i>B1</i> \$663.70
2	REAR BUMPER SIDE RETAINER LH + RH	<i>re</i> \$27.50	\$55.00
10	REAR BUMPER CLIP	\$3.90	<i>re</i> \$39.00
1	REAR END PANEL		<i>B1</i> \$423.90
1	REAR END PANEL INNER TOP GARNISH		<i>re</i> \$96.60
4	REAR END PANEL INNER TOP GARNISH CLIP	\$5.90	<i>re</i> \$23.60
1	REAR WELL PANEL INNER TOP TOOL SPONGE		<i>re</i> \$180.50
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD		\$286.60

SUB TOTAL	\$3,512.80
Less 20%	-\$702.56
PARTS TOTAL	\$2,810.24

*Not to be used
1.B.1
Runway B4 park
6 days*

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR		<i>re</i> \$560.00
1	REAR WELL PANEL INSULATOR MAT		\$150.00
		S/N TOTAL	\$710.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

*2000m
7*

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: AXA

Vehicle No: SLR5277Z

Third Party Veh No: SKU717A

Model: HONDA GRACE 1.5 LX CVT

Date of Accident: 19/03/2018

Chassis: GM61002801

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$800.00	7001
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00	7201
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	501
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$280.00	?
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$220.00	801

LABOUR TOTAL	\$2,220.00
--------------	------------

WINSON	TOTAL	\$5,740.24
--------	--------------	-------------------



Service Request Details

Claim

S8M00BAU

Reference

None 

Loss Date

March 19, 2018

Request Date

March 21, 2018

Due Date

March 28, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

21-03-2018 @ 1:35pm

Riza veh in

Kenneth.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLR5277Z

Make

TPVD

Service Address

...

Primary Contact/Insured

YONG YEE FOOK

6 SUFFOLK WALK, #17-08, 307464, Singapore

85222852

ALBERTYYF@GMAIL.COM

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

 S8M00BAU- Mandate approval

Type

 Question

Message

Hi Vic, pls proceed. pls upload photos of parts that are replace after repair completion. Tks

[Reply](#)



S8M00BAU- Mandate approval

Type

🔔 Question

Message

Hi Viviau, pls propose @ \$5100 to \$5200 (global-all in). tks

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKU 717A (Insd veh)	Model:	HONDA
	SLR 5277Z (TP veh)		GRACE 1.5LX CVT
Date of Accident:	19/03/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	6,142.06
Final Repair Cost	:	\$	5,032.42
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	749.00 7 days
LTA / GIA Search Fee	:	\$	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	5,781.42

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown			
1)	OPTIMA WERKZ PTE LTD	:	\$ 5,781.42

NUR SHAQILAH BTE ABDOL
WAHAB

09/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Claim	S8M00BAU
Reference	CC4/ASM18005396/Khb3s2
Loss Date	March 19, 2018
Report Date	Mar 20, 2018 12:00:00 AM
Request Date	July 3, 2018
Due Date	March 21, 2019

Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SLR5277Z

Make

TPVD

Model

GRACE/WHITE

Service Address

...

Primary Contact/Insured

YONG YEE FOOK

6 SUFFOLK WALK, #17-08, 307464, Singapore 85222852

ALBERTYYF@GMAIL.COM

Claim Handler

HO Winnie

656804833

winnie.ho@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 5, 2018
Immediate Advice- SLR 5277Z.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 2, 2018

Claim	S8MD0BAU
Reference	CC4/ASM18005396/Khb3sz 
Loss Date	March 19, 2018
Report Date	Mar 20, 2018 12:00:00 AM
Request Date	July 3, 2018
Due Date	March 21, 2019
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
VISHNU BATHAM Shekhar	3/21/18 11:44 AM	4703.2	4703.2	Open	Share	Clone

Vehicle Information

Incident Vehicle Registration #

SLR5277Z

Make

TPVD

Model

GRACE/WHITE

Service Address

...

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More

Primary Contact/Insured

YONG YEE FOOK

6 SUFFOLK WALK, #17-08, 307464, Singapore 85222852

ALBERTYYF@GMAIL.COM

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Vehicle & Driver Details

Vehicle Registration#	SLR5277Z	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	08/17/2017
Mileage	11746	Age of Vehicle	0
Driver Details			
CATEGORY	POLICY INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2017	Driver Name	WONG TECK YEAN
Make	TPVD	Date of Birth	December 31, 1899
Model	GRACE/WHITE	Age	119
Type		Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	GM61002801	Driving Experience	0
Engine No	11584073541	Driver License #	
Engine Capacity	1496 cc	License Type	
Sum Insured	0		

Detailed Assessment

Inspection Date *	03/21/2018	Condition of Vehicle at time of survey	
Total Loss	Yes No	General condition	Good
Towing Charges	0	Steering (Serviceable)	Yes No
Voluntary Excess	0	Footbrake (Serviceable)	Yes No
Compulsory Excess	0	Handbrake (Serviceable)	Yes No
Young/Inexperienced/Unarmed Driver Excess	0	Engine Modification	Yes No
Other Excess		Pre-accident condition	Good

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	185/60R15	Rear Tyre Size	185/60R15
Front left side	YOKOHAMA 9mm	Rear left side	YOKOHAMA 9mm
Front right side	YOKOHAMA 9mm	Rear right side	YOKOHAMA 9mm

SERVICE REQUESTS MESSAGES CLAIMS

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

Archive

Cancel

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRN	DISCOUNT%	SALVAGE%	PART PRICE(Net)	ACTION (PARTS)	REMOVE
		1	1			REAR BOOT LID			Bent	594.5		20		475.6	Reviewing	
		2	1			REAR BOOT LID EMBLEM			Necessary	23.1		20		18.48	Reviewing	
		3	2			REAR BOOT LID LOGO EMBLEM CLIP			Necessary	5.8		20		9.28	Reviewing	
		4	1			REAR BOOT LID GRACE EMBLEM			Necessary	53.6		20		42.88	Reviewing	
		5	1			REAR BOOT LID REFLECTOR LAMP LH			Cracked	306.7		20		245.36	Reviewing	
		6	1			REAR BOOT LID HINGE LH			Repair	0		20		0	Reviewing	
		7	12			REAR BOOT LID INNER UPHOLSTERY TRIM CLIP			Serviceable	0		20		0	Reviewing	
		8	1			REAR BOOT LID MECHANISM LOCK			Damaged	199.5		20		159.6	Reviewing	
		9	1			REAR BOOT LID WEATHERSTRIP			Dented	99.6		20		79.48	Reviewing	
		10	1			REAR TAIL LAMP LH			Cut	481.1		20		384.88	Reviewing	

 SERVICE REQUESTS MESSAGES CLAIMS

	PART NAME	LABOUR HRS	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	720	0	0	Reviewing		
	TO TUFF KOTE / ANTI- RUST.	60	0	0	Reviewing		
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR.	50	0	0	Reviewing		
	TO MOUNT VEHICLE ONTO 3D COMPUTERISED CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	0	0	0	Reviewing		
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPARTMENT TO FACILITATE REPAIR.	80	0	0	Reviewing		

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		6	
	2	REAR BUMPER REVERSE SENSOR	Reviewing	200	DENTED	
	3	REAR WELL PANEL INSULATOR MAT	Reviewing	0	NOT NECESSARY	

- HOME
- SERVICE REQUESTS
- MESSAGES
- CLAIMS

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount		\$4,703.20				Claim Amount	\$4,703.20	
CATEGORY		ESTIMATE				REVISED AMOUNT		
Spare Parts		\$2,893.20				\$2,893.20		
Labour		\$1,610.00				\$1,610.00		
Miscellaneous		\$200.00				\$200.00		

Submit for Review