OPTIMA WERKZ PTE LTD

Tel: +65 6472 1313 Fax: +65 6472 2112 Head office : 6 Kung Chong Road Singapore 159143 Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

20 March 2018

Third Party Insurer:

AXA

Vehicle No:

SLR5277Z

Third Party Veh No:

SKU717A

Model:

HONDA GRACE 1.5 LX CVT

Date of Accident:

19/03/2018

Chassis:

GM61002801

ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOU	NT S\$
1	REAR BOOT LID			Bi	\$594.50
1	REAR BOOT LID LOGO EMBLEM			ne	\$23.10
2	REAR BOOT LID LOGO EMBLEM CLIP		\$5.80	ng	\$11.60
1	REAR BOOT LID GRACE EMBLEM			M	\$53.60
1	REAR BOOT LID REFLECTOR LAMP LH		F0+#	-60 cm	\$36.80
1	REAR BOOT LID HINGE LH			1	\$67.90
12	REAR BOOT LID INNER UPHOLSTERY TRIM CLIP		\$5.90	an	\$70.80
1	REAR BOOT LID MECHANISM LOCK				\$199.50
1	REAR BOOT LID WEATHERSTRIP			Ru	\$99.60
1	REAR TAILLAMP LH			a	\$481.10
1	REAR TAILLAMP INNER PANEL LH				\$105.40
1	REAR BUMPER			Ry	\$663.70
2	REAR BUMPER SIDE RETAINER LH + RH	Alsnig	\$27.50		\$55.00
10	REAR BUMPER CLIP		\$3.90	na	\$39.00
1	REAR END PANEL			B	\$423.90
1	REAR END PANEL INNER TOP GARNISH			niy	\$96.60
4	REAR END PANEL INNER TOP GARNISH CLIP		\$5.90	na	\$23.60
1	REAR WELL PANEL INNER TOP TOOL SPONGE		V	Eferm	\$180.50
1	REAR WELL PANEL INNER TOP UPHOLSTERY BOARD				\$286.60
	Nim 1 1	SUB TOTA	\L	\$	3,512.80
	Nor Norhair		Less 20%		-\$702.56
	2 1.3.1	PARTS TO	TAL	\$	2,810.24

Renny BEpary

QTY	SPECIAL NETT	UNIT S\$	AMOU	AMOUNT S\$	
1	REAR BUMPER REVERSE SENSOR		ne	\$560.00	
1	REAR WELL PANEL INSULATOR MAT_LKK Auto Consultants hence no	tify		\$150.00	
	the Repairer of the following: To resurvey before/after spray pales/	N TOTAL		\$710.00	

2000m

To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel: +65 6472 1313 Fax: +65 6472 2112 Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

20 March 2018

Vehicle No: SLR5277Z

Model: Chassis: HONDA GRACE 1.5 LX CVT

GM61002801

Third Party Insurer:

Third Party Veh No:

Date of Accident:

AXA SKU717A

19/03/2018

ESTIMATE

WINSON	TOTAL	\$5.740.24	
	LABOUR TOTAL	\$2,220.00	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER AT PARTS COMPONENT TO FACILITATE REPAIR	\$220.00	801	
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPEC	\$280.00	?	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	501	
TO TUFF KOTE / ANTI-RUST		\$60.00	_
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PO	\$800.00	720	
LABOUR CHARGES: TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT	PORTION	\$800.00	700