

ASS. REC. BY:

REF

CS/CT118005400/Kqd3 n2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person)

Irene Tay

of

CTI

Date/Time

22/3/18 @ 9:21am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LU 5483D

Insured:

G8B 7027T

at Workshop in/s

K. Kim Hin Auto

Tel:

64527018

of

160 Sin Ming Drive # 02-20

Policy No:

5046487969

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/03/2018

CA / REV / REP. / REV 24 HRS

lwp'

08052018 @ 1:30pm

H.O.D. Endorsement:

Date/Time:

2:25pm @ 22/3/18

Person Contacted:

8 human

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

8LU 5483 D-x

G8B 7027 T-x

24/12 11 Lp @ 22001 Cciform (Red @ 1692.88, 43%)

REF: CTL

Maiman

ASSIGNMENT

From:

Date:

08052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLU 54830

at Workshop m/s

K Kim Hin Auto

of

160 Sin Ming Drive #02-20

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

1:30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU 54830

Tr Regn:

10 15

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

63514

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1102072

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

191311P

D.O.I.

81518

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/5 File per to Customer

RECEIVED 27 DEC 2018

Date/Time, File Pass to?



Preli. Report

1) 12/12/18



Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S + RS. SI

Photos

Others

Report Format:

Lump Sum / I.B.1 (\$)

2000

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Mar 2018 11:13 Sendback Est	21 Mar 2018 11:56 \$53,892.88	22 Mar 2018 09:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NIL, Co. Reg. No.: 0		
Main Claimant:	ALBERTYEO TRANSPORT, Co. Reg. No.: 53318912L		
Vehicle Reg. No.:	SLU5483D	Date of Loss:	19/03/2018 18:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 12/09/2017 - 11/09/2018
Vehicle Reg. No. (Insured):	GBB7027T	Policy No. (Claimant):	5096487969
		Excess:	S\$0.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]		
Adj Asg. Remarks:	EST \$4165.38 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

5860
Appt
(LKK)

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'd	Status
Main	21 Mar 2018 11:13		21 Mar 2018 11:56 S\$3,892.88			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	NIL, Co. Reg. No.: 0		
Main Claimant:	ALBERTYEO TRANSPORT, Co. Reg. No.: 53318912L		
Vehicle Reg. No.:	SLU5483D	Date of Loss:	19/03/2018 18:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 12/09/2017 - 11/09/2018
Vehicle Reg. No. (Insured):	GBB7027T	Policy No. (Claimant):	5096487969
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8912L
Vehicle Details	
Vehicle No.:	SLU5483D
Vehicle to be Exported:	No
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4022073
Chassis No.:	RU11102072
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,057.00
Original Registration Date:	16 Oct 2015
First Registration Date:	16 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$9,057.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Oct 2025
PARF Rebate Amount:	\$6,792.00
Intended COE Rebate Details	
COE Expiry Date:	15 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$42,382.00
Total Rebate Amount:	\$49,174.00

The information contained herein is correct as at 20 Mar 2018

OK



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
NIL

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/03/2018
Vehicle Reg. No.:	SLU5483D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	YEO HOON TENG		

Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	16/10/2015
Vehicle Colour:	WHITE		
Engine No:	L15B4022073	Chassis No:	RU11102072
Odometer:	0 KM		

Not Not hash

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	6 ✓

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
------------------------------	------------------------------

Remarks:	VEHICLE IS NOT IN YET, WE WILL ARRANGE FOR SURVEY ONCE READY. KINDLY ADVISE LIABILITY. THANK YOU.
----------	---

Present Location:	K KIM HIN AUTO PTE LTD (HQ)
-------------------	-----------------------------

COST OF CLAIMS

	Amount
Parts	2,362.88
Miscellaneous Items	0.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,892.88
+ GST 7.00% (S\$)	272.50
Nett Amount (S\$)	4,165.38

This claim is handled by: WONG SHU MAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2018)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU5483D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*N/S REAR FENDER	0.00	0.00	<i>As</i> *884.40 F	✓
2	1		*N/S REAR FENDER WHEEL ARCH GARNISH	0.00	0.00	<i>As</i> *150.00 F	✓
3	1		*REAR BUMPER-TOP	<i>Not LT</i> 0.00	0.00	*463.70 F	✓
4	1		*REAR BUMPER-SIDE	0.00	0.00	<i>Sm</i> *153.00 F	X
5	1		*N/S REAR BUMPER SIDE RETAINER	0.00	0.00	<i>Sm</i> *22.00 F	X
6	10		*REAR BUMPER CLIPS	0.00	0.00	<i>As</i> *32.00 F	✓
7	1		*N/S REAR TYRE	0.00	0.00	<i>Sm</i> *180.00 F	X
8	1		*N/S REAR SHOCK ABSORBER	0.00	0.00	<i>Sm</i> *330.00 F	X
9	1		*N/S REAR WHEEL BEARING	0.00	0.00	<i>As</i> *263.50 F	X
10	1		*N/S REAR SPORT RIM	0	0.00	<i>As</i> *380.00 FS	✓
						Sub Total (\$\$)	2,858.60
						- Add. Disc. on L,N Items 20.00% (\$\$)	495.72
						Total Parts (\$\$)	2,362.88

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	600 680.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	100 120.00
3	TO APPLY UNDERSEALING.	New	30.00 ✓
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	400 480.00
5	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	80.00 60
6	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	20 140.00 X
Gross Labour Cost (S\$)			1,530.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18005400/KQD3N2

Date: 27/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLU5483D	Insured Vehicle No :	GBB7027T
Date of Loss:	19/03/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5483D	Engine No:	L15B4022073
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11102072
Reg. Date:	16/10/2015 (Man. Year: 2015)	Odometer:	63514 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,362.88	1,604.08	758.80	32.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,190.00	340.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,892.88	2,794.08	1,098.80	28.23
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	3,892.88	2,200.00	1,692.88	43.49
+ GST 7.00/7.00% (S\$)	272.50	154.00	118.50	43.49
Nett Amount (S\$)	4,165.38	2,354.00	1,811.38	43.49

INSPECTION

Date of Assignment:	22/03/2018	Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	08/05/2018	Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
			160 Sin Ming Drive #02-20, Sin Ming
			AutoCity
			Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLU5483D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S REAR FENDER	Bent	884.40 F	*884.40 FL
2	1		*N/S REAR FENDER WHEEL ARCH GARNISH	Dented	150.00 F	*150.00 FL
3	1		*REAR BUMPER-TOP	Dented/Cut	463.70 F	*463.70 FL
4	1		*REAR BUMPER-SIDE	Serviceable	153.00 F	*- FL
5	1		*N/S REAR BUMPER SIDE RETAINER	Serviceable	22.00 F	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	32.00 F	*32.00 FL
7	1		*N/S REAR TYRE	Serviceable	180.00 F	*- FL
8	1		*N/S REAR SHOCK ABSORBER	Serviceable	330.00 F	*- FL
9	1		*N/S REAR WHEEL BEARING	Not Necessary	263.50 F	*- FL
10	1		*N/S REAR SPORT RIM	Dented	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,858.60	1,910.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	306.02
+ Margin on L,N Items -20.00/0.00% (\$\$)	-495.72	0.00
Total Parts (\$\$)	2,362.88	1,604.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	680.00	600.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	100.00
3	TO APPLY UNDERSEALING.	New	30.00	30.00
4	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	480.00	400.00
5	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	80.00	60.00
6	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	140.00	-
Gross Labour Cost (S\$)			1,530.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >