

ASS. REC. BY:

REF:

CS/CTI18005405 / Urd3

Special Instruction:

Survivor:
Menmen

Marius

ASSIGNMENT (Office)

From (Person):

Adeline Chng

of

CTI

Date/Time:

22/3/18 @ 10:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JPR 4249

Insured:

SLC3399Y

at Workshop m/s

Precise Auto

Tel:

6745 7367

of

11kaki Bukit Ave 6 # 02-34 / 36

Policy No:

DMPCSN3082831700

Claim No:

SNM18D0143102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/03/2018

CA / REV / REP. / REV 24 HRS

lup

23/03/2018

H.O.D. Endorsement:

Date/Time:

2:20pm @ 22/3/18

Person Contacted:

Yan Hoe

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

JPR 4249 - X

SLC3399Y - X

REF: CTI

ASSIGNMENT

From: Date: 23/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JPR 4249

at Workshop m/s

Precise Auto

of 1 Kaki Bkt Ave 6 # 02-34/36

Insured:

Policy No.

Claims No.


Sum Insured:

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

G/A / PR Seen: Consistent? : Yes or No

Est Repairs: 5 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS / wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: JPR 4249 Yr Regn: 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Proton Exora D.C. 1561

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 235000 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PL1F26YD REF 12280x

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / A/Rim / STD A/Rim or

Tyre Size: F: 205/55-16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/3/18 D.O.I. 23/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

log card?

11/6/18 confirmed m/s \$3500 with yan hong (Red 3011.70, 4810)

RECEIVED 12 JUN 2018

Date/Time: File Pass to?

☐

: Preli. Report

()

☐

: Final Report

Date/Time: File Return to?

20 12/6 - typist

Report Format: merimen

Lump Sum / I.B.I: \$ 3500/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech Insp \$☐ Washing \$

Survey Fee:

Transportation

1. S - R \$

2. Private

3. Other

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118005405/Uvd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 3399Y	Veh. Inspected	JPR 4249
Policy No.	DMPCSN3082831700	Coverage (\$)	0.00
Claim No.	SNM18D01431C02	Excess (\$)	0.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	22/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/03/2018	Inspection Date
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2018		22 Mar 2018 10:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:		KATHERINA SIM PEI MING		[Created by insurer]	
Main Claimant:		YEONG CHEE KHOON			
Vehicle Reg. No.:		JPR4249	Date of Loss:	18/03/2018 12:00 - :59	
Claim Type:		TP / SNM18D01431C02	Policy/Cover Note No.:	DMPCSN3082831700	
Vehicle Reg. No. (Insured):		SLC3399Y	Policy No. (Claimant):		
			Excess:	S\$0.00	
Repairer:		Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367			
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2018]			
Adj Asg. Remarks:		-TP HAD APPOINTED MARCUS CHUA TO DO SURVEY - RIAZ PERSON IN CHARGE : HUI LING			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

RIA Z
 L.L.C
ADVOCATES AND SOLICITORS
 COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

19/03/2018

Our Ref: JPR 4249 (V) PRECISE

Your Ref: SLC 3399Y

 RIAZ QAYYUM (LLB HONS) NUS
 (DIRECTOR)

 TAN KOK SIANG (LLB HONS) LON
 (ASSOCIATE)

TO: China Taiping Insurance Co. (Singapore) Pte Ltd
 3 Anson Road
 #16-00, Springleaf Tower
 Singapore 079909
 Attn: Motor Claims Department

 ABDUL HALIM BIN ROSALAN (LLB HONS) UTAR
 (ASSOCIATE)

 MUHD RIDHWAN ABDUL RAHMAN (LLB HONS) KES
 (ASSOCIATE)

FAX 6224 7375

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on 18 March 2018 at about 1215 hours along Woodlands Centre Road involving our client's vehicle registration number JPR 4249 and vehicle registration number SLC 3399Y driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Vehicle makes & model: PROTON EXORA 1.6

Please be informed that the said vehicle can be inspected at:

Name of workshop : PRECISE AUTO SERVICE

Address : 1 Kaki Bukit Avenue 6
 #02-34/36 Autobay @ Kaki Bukit
 S (417883)

Telephone no. : 6745 7367 Fax no.: 6841 3390

Please let us hear from you by the stipulated time.

Yours faithfully

Riaz

cc. Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
 (Name & signature)

Date & time of inspection

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN:

JPR4249

No. Siri: **5561200**
IDNUEJYX

Nama Pemunya
Berkaitan

YEONG CHEE SEONG

780102065253
[NAL]

Alamat

**NO3 JALAN PERMAS 12/1 BANDAR BARU PERMAS JAYA
81750 JOHOR BAHRU JOHOR**

No. Enjin	S4PHTV0204	B O M B G K	-
No. Cais	PL1FZ6YDREF122804	B T T	-
Buatan	PROTON	Berat Kerb	-
Nama Model	EXORA FL 1.6L CVT	B.T.M.	-
Keupayaan Enjin	1561 S.P.	B.G.1	-
Bahan Bakar	PETROL	B.G.2	-
Warna	PERAK	B.G.3	-
Kelas Kegunaan	PERSendirian-MOTOKAR INDIVIDU	B.G.4	-
Jenis Badan	MOTOKAR PELBAGAI UTILITI	B.G.5	-
Tahun Dibuat	2013	B.G.6	-
Tarikh Pendaftaran	10/10/2013	B.G.7	-
Status Pemunya	PERSendirian	B.G.8	-
Mustan Tempat		B.G.9	-
Duduk	7	B.G.10	-
Kadar Lesen		B.G.11	-
Kenderaan Motor	5 bulan RM45.00	12 bulan RM90.00	B.G.12 -

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri **JABATAN PENGANGKUTAN JALAN**

UNTUK KEGUNAAN PEJAWAT

PENGANGKUTAN TEMPATAN

HAJIBELIN DITUNTUT OLEH: PUBLIC BANK BERHAD NO SIRI: H05/52004/10

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butiran-butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh memperbaharui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berjalan.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran miliau telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baharu.
7. Jika elarnet, anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.



SINGAPORE POLICE FORCE



T/20180318/2053

1 of 3

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20180318/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2018 15:26		Vide Report No.:		Station Diary No.: 13	
Informant's Particulars					
Name of Informant: Yeong Chee Khoon			Address:		
ID Type / ID No.: NEW MALAYSIAN IC / 750227085823			Contact No.: Home/Office:		Mobile: 82064743
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 43	Date of Birth: 27/02/1975	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 18/03/2018 12:15	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS CENTRE ROAD				
Along Woodlands Crossing in front Woodlands Checkpoint				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JPR4249	Car	PROTON	Exora 1.6 Turbo		Seriously Damaged	1
SLC3399Y	Car	HONDA	VEZEL		No Damage	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180318/2053

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20180318/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 CHUA CHANG YU

Signature Of Interpreter:

Not applicable

Signature Of Informant:

Date/Time:

18/03/2018 15:26

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Classification Of Case:



SINGAPORE
POLICE FORCE

Authentication Stamp

NP168

SIGNATURE

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

Accident Date : 18-03-2018

29-05-18

OUR REF : JPR 4249/T/18

YEONG CHEE SIONG

01-05 Blk Bandar Puteri Seri Bayan

Jalan Bayan 11 Taman Kota Puteri

81750 Masai, Johor.

ESTIMATE BILL ON VEH. NO. : JPR 4249

MODEL : PROTON EXORA

CHASSIS NO. : PL1FZ6YDREF122804

LIST ITEM

Tail Gate		70/bmt	620.00	✓
Tail Gate Absorber	2pcs @ 85.00	11	170.00	✗
Tail Gate Lock		tw/1gm	85.00	✓
Tail Gate Striker		11	31.00	✗
Tail Gate Weather Stripe		twl	160.00	✓
Tail Gate Inner Trim Board		rel/trim	210.00	✓
Tail Gate Inner Trim Board Clips	10pcs @ 4.50	ner	45.00	✓
Tail Gate Stopper	2pcs @ 18.00	11	36.00	✗
Tail Gate Emblum "CFE"		ner	41.00	✓
Tail Gate Emblum "Exora"		ner	45.00	✓
Tail Gate Emblum "Bold"		ner	39.00	✓
Rear Windscreen Glass Inner Seal		ner	38.00	✓
Rear Windscreen Glass Clips	14pcs @ 3.00	11	42.00	✗
Rear Bumper Fascia		70/x	490.00	✓
Rear Bumper Side Retainer	2pcs @ 45.00	ber	90.00	✓
Rear Bumper Lower Bracket	2pcs @ 38.00	ber	76.00	✓

Marcus.

Date in/out : 18/03/18 to 28/03/18

5 by.

not allowed
after
4/5 @ 3500/-
take photo to after cap
23/3/18

Rear Bumper Clips	8pcs @ 3.00	24.00	✓
Rear Bumper Tow Cover		29.00	X
Rear Bumper Reinforcement		290.00	✓
Rear Bumper Beam		120.00	X
Rear End Panel - Outer		380.00	✓
Rear End Panel - Inner		310.00	X
Rear End Panel Top Trim		95.00	✓
Rear End Panel Top Trim Clips	4pcs @ 3.00	12.00	X
Spare Tyre Bracket		89.00	X
Spare Tyre Adjusting Screw		46.00	X
		3,613.00	
Less Discount 10%:		361.30	
		3,251.70	

SPECIAL NETT ITEM

Rear Windscreen Glass Sealant	60.00	40
Reverse Sensor With Control Unit	380.00	200

LABOUR CHARGE

Towing.	80.00	X
To Check Wiring System.	80.00	30
To Tuff Coat Affected Areas.	180.00	60
To Remove & Refix Interior Upholstery.	150.00	80
To Remove & Refix Reverse Sensor.	150.00	50
To Remove & Refix Rear Windscreen Glass.	180.00	120
To Respray Affected Areas.	1,250.00	800
To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.	950.00	600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

TOTAL :
GST 7% :
AMOUNT DUE :

6,711.70
469.82
7,181.52

4435.2

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2018		22 Mar 2018 10:23 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KATHERINA SIM PEI MING, ID: -								
Main Claimant:	YEONG CHEE KHOON								
Vehicle Reg. No.:	JPR4249	Date of Loss:	18/03/2018 12:00 - :59 [53 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01431C02	Policy/Cover Note No.:	DMPCSN3082831700						
Vehicle Reg. No. (Insured):	SLC3399Y	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/04/2018]								
Adj Asg. Remarks:	-TP HAD APPOINTED MARCUS CHUA TO DO SURVEY - RIAZ PERSON IN CHARGE : HUIJING								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JPR4249 (SNM18D01431C02)**
[SLC3399Y]
TP
YEONG CHEE KHOON
Mar 18 2018 12:00PM
[KATHERINA SIM PEI MING]
Precise Auto Service

Upload Documents	Upload Photos	Compose New Letter	View View in Browser v
Photos/Images			3 per page v ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	12/06/18 10:12	General View	 Load PDF
2	12/06/18 10:12	Reinspection Photo	 Load PDF
Documentation			1 per page v ☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	22/03/18 10:10	TP NOTIFICATION	 Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118005405/UVD3Q2

Date: 13/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3082831700

Claimant Vehicle
No : JPR4249Insured Vehicle
No : SLC3399Y

Date of Loss: 18/03/2018

Nature of Claim: TP

Claim
No: SNM18D01431C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JPR4249

Make & Model: PROTON EXORA, 1.6 (M)

Reg. Date: 10/10/2013 (Man. Year: 2013)

Colour: Silver

Engine Capacity: 1561 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: S4PBT0204

Chassis No: PL1FZ6YDREF122804

Odometer: 235088 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,691.70	2,695.20	996.50	26.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,740.00	1,280.00	42.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,711.70	4,435.20	2,276.50	33.92
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	6,711.70	3,500.00	3,211.70	47.85
+ GST 7.00/7.00% (S\$)	469.82	245.00	224.82	47.85
Nett Amount (S\$)	7,181.52	3,745.00	3,436.52	47.85

INSPECTION

Date of Assignment: 22/03/2018

Date Inspected: 23/03/2018 Inspected At:

Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts: M1-MPV	PROTON EXORA 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for JPR4249)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented / Bent	620.00 FL	*620.00 FL
2	2		*TAIL GATE ABSORBER	Not Necessary	170.00 FL	*- FL
3	1		*TAIL GATE LOCK	Twisted / Jammed	85.00 FL	*85.00 FL
4	1		*TAIL GATE STRIKER	Not Necessary	31.00 FL	*- FL
5	1		*TAIL GATE WEATHER STRIP	Twisted	160.00 FL	*160.00 FL
6	1		*TAIL GATE INNER TRIM BOARD	Deformed / Torn	210.00 FL	*210.00 FL
7	10		*TAIL GATE INNER TRIM BOARD CLIPS	Necessary	45.00 FL	*45.00 FL
8	2		*TAIL GATE STOPPER	Not Necessary	36.00 FL	*- FL
9	1		*TAIL GATE EMBLEM CFE	Necessary	41.00 FL	*41.00 FL
10	1		*TAIL GATE EMBLEM EXORA	Necessary	45.00 FL	*45.00 FL
11	1		*TAIL GATE EMBLEM BOLD	Necessary	39.00 FL	*39.00 FL
12	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	38.00 FL	*38.00 FL
13	14		*REAR WINDSCREEN GLASS CLIPS	Not Necessary	42.00 FL	*- FL
14	1		*REAR BUMPER FASCIA	Dented / Deformed	490.00 FL	*490.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Bent	90.00 FL	*90.00 FL
16	2		*REAR BUMPER LOWER BRACKET	Bent	76.00 FL	*76.00 FL
17	8		*REAR BUMPER CLIPS	Necessary	24.00 FL	*24.00 FL
18	1		*REAR BUMPER TOW COVER	Not Necessary	29.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	290.00 FL	*290.00 FL
20	1		*REAR BUMPER BEAM	Repair	120.00 FL	*- FL
21	1		*REAR END PANLE -OUTER	Badly Dented	380.00 FL	*380.00 FL
22	1		*REAR END PANEL -INNER	Repair	310.00 FL	*- FL
23	1		*REAR END PANEL TOP TRIM	Twisted	95.00 FL	*95.00 FL
24	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	12.00 FL	*- FL
25	1		*SPARE TYRE BRACKET	Repair	89.00 FL	*- FL
26	1		*SPARE TYRE ADJUSTING SCREW	Not Necessary	46.00 FL	*- FL
27	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
28	1		*REVERSE SENSOR WITH CONTROL UNIT	Shorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,053.00	2,968.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	361.30	272.80
Total Parts (\$\$)	3,691.70	2,695.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	150.00	80.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
6	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO RESPRAY AFFECTED AREAS	New	1,250.00	800.00
8	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	950.00	600.00
Gross Labour Cost (\$\$)			3,020.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >