

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR-%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		10	1			FRT FENDER INNER SHIELD (RH)			Deformed	40				40
☐		11	8			FRT FENDER INNER SHIELD CLIP			Necessary	1.5				12
☐		12	1			FRT FENDER INNER PANEL (RH)			Repair	0				0
☐		13	1			FRT SHOCK ABSORBER (RH)			Bent	145				145
☐		14	1			FRT SHOCK ABSORBER TOP MOUNTING (RH)			Necessary	50				50
☐		15	1			FRT SHOCK ABSORBER SPRING (RH)			Serviceable	0				0
☐		16	1			FRT KNUCKLE ARM (RH)			Bent	270				270
☐		17	1			FRT LOWER ARM (RH)			Bent	158				158
☐		18	1			FRT WHEEL HUB & BEARING (RH)			Bent	155				155
☐		19	1			FRT TIE ROD (RH)			Cracked	50				50
☐		20	1			FRT TIE ROD END (RH)			Bent	30				30
☐		21	1			FRT WHEEL HOUSE (RH)			Serviceable	0				0
☐		22	1			FRT SUPPORT PANEL COMPLETE			Cracked	280				280

Detailed Assessment

Inspection Date *

03/23/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/70R16

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/70R16

FNOL INFORMATI... 20, AIRPORT BOULEVARD, SATS
INFLIGHT CATERING CENTRE 1, 819659,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF ...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF ...

CATEGORY

Identification #

FNOL INFORMATI...

S1467335J

CATEGORY	Make	
POLICY INFORMAT...	HYUNDAI H1 STAREX 2.5 CRDI MT	
ASSESSMENT INFO...	HYUNDAI	
CATEGORY	Model	
POLICY INFORMAT...	HYUXXX	
ASSESSMENT INFO...	H1 STAREX 2.5 CRDI MT ABS AIRBAG :	
CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		
CATEGORY	Chassis No	
POLICY INFORMAT...	KMFWBX7KLEU672708	
CATEGORY	Driving Experience	

CATEGORY	Date of Birth	
FNOL INFORMATI...	June 24, 1961	
POST SURVEY INF...	mm/dd/yyyy	
CATEGORY	Age	
FNOL INFORMATI...	57	
POST SURVEY INF...		
CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		
CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		
CATEGORY	Driving Experience	

Accelerated
workshop survey

Claim Handler

WANG Peter

peter.wang@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

Additional Instructions

Wkshop: Sng Ah Tee Excess: \$500 To get DL copy. Pending midnight investigation. Survey WP.

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	7/27/18 10:25 AM	3731	3731	Open	Share	Clone
User Portal	7/4/18 9:45 AM	5883	5883	Approved	Share	Clone
WANG Peter	3/22/18 10:26 AM			Open	Share	Clone

Accelerated
workshop survey

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

Wkshop: Sng Ah Tee Excess: \$500 To get DL
copy. Pending midnight investigation. Survey WP.

Document SubType

Upload Documents

NAME	TYPE	SUB- TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
SUPPLEMENTARY.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	July 20, 2018
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	July 20, 2018