

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

Our Ref: S8M00B6S

Date : 22/3/2018

ATTN:THE MOTOR CLAIMS DEPT

AXA INSURANCE PTE LTD

8 SHENTON WAY

AXA TOWER #B1-01

SINGAPORE 068811

ESTIMATE COST OF REPAIR

Vehicle Reg No.	GBD5725P	Model / Year	HYUNDAI.H1 STAREX
Date of Accident	17-Mar-18	Policy No.	P1742715
Type of Claim	OD AXA	Prepared By	JOYCE
Survey By		Chassis No.	KMFWBX7KLEU672708

S/NO	Description	Qty	Cost	Price	Amount
1	FRT BUMPER	1	\$	200.00	\$ 200.00 <i>de</i>
2	FRT BUMPER SIDE RETAINER RH	1	\$	15.00	\$ 15.00 <i>new</i>
3	FRT BUMPER CLIP	10	\$	2.50	\$ 25.00 <i>new</i>
4	FRT BUMPER SPONGE	1	\$	55.00	\$ 55.00 <i>?</i>
5	FRT BUMPER LOWER	1	\$	180.00	\$ 180.00 <i>wt</i>
6	FRT FOGLAMP (RH)	1	\$	85.00	\$ 85.00 <i>?</i>
7	FRT HEADLAMP(RH)	1	\$	280.00	\$ 280.00 <i>wt</i>
8	FRT HEADLAMP LWR BRACKET(RH)	1	\$	12.00	\$ 12.00 <i>?</i>
9	FRT FENDER(RH)	1	\$	170.00	\$ 170.00 <i>bt</i>
10	FRT FENDER INNERSHIELD(RH)	1	\$	40.00	\$ 40.00 <i>de</i>
11	FRT FENDER INNERSHIELD CLIP	8	\$	2.50	\$ 20.00 <i>wa</i>
12	FRT FENDER INNER PANEL(RH)	1	\$	820.00	\$ 820.00 <i>Rp</i>
13	FRT SHOCKABSORBER(RH)	1	\$	145.00	\$ 145.00 <i>bt</i>
14	FRT SHOCKABSORBER TOP MOUNTING(RH)	1	\$	50.00	\$ 50.00 <i>wa</i>
15	FRT SHOCKABSOBER SPRING(RH)	1	\$	280.00	\$ 280.00 <i>?</i>
16	FRT KNUCKLE ARM(RH)	1	\$	270.00	\$ 270.00 <i>bt</i>
17	FRT LOWER ARM(RH)	1	\$	158.00	\$ 158.00 <i>bt</i>
18	FRT WHEEL HUB & BEARING(RH)	1	\$	155.00	\$ 155.00 <i>bt</i>
19	FRT TIE ROD(RH)	1	\$	50.00	\$ 50.00 <i>an</i>
20	FRT TIE ROD END(RH)	1	\$	30.00	\$ 30.00 <i>bt</i>
21	FRT WHEEL HOUSE(RH)	1	\$	780.00	\$ 780.00 <i>?</i>
22	FRT SUPPORT PANEL COMPLETE	1	\$	280.00	\$ 280.00 <i>?</i>
23	FRT CROSSMEMBER	1	\$	450.00	\$ 450.00 <i>?</i>

\$ 4,550.00

TO REPAIR & REPLACE UNDERCARRIAGE

\$ 350.00 *150.00*

TO CHECK WIRING

\$ 50.00 *30.*

TO DO WHEEL ALIGHMENT

\$ 80.00 *✓*

TO KNOCK,FRT DOOR(RH),WELD,REMOVE & FIX ABOVE

\$ 1,500.00 *600*

TO PUTTY & RESPRAY PAINTING ON FRT BUMPER

\$ 1,300.00 *700.*

FRT SUPPORT PANEL,FRT DOOR(RH),FRT FENDER(RH)

FRT FENDER INNER PANEL FRT WHEEL HOUSING

WORK DONE IN THE FOLLOWING AREAS

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

TOTAL \$ 7,830.00

Tanpin 97495449

Exp 500

Newest Not Advised

Ready before paint

6-7 days

sure kluat.com