

FASTECH AUTO PTE LTD

1 KAKI BUKIT AVENUE 6
#01-46/48/50, AUTOBAY,
SINGAPORE 417883

VEHICLE NO: SKK 8088G

no of Authorisation
2/5 = 4300
4 day
22/3/18

QTY	PARTICULAR	AMOUNT
1PCS	REAR BUMPER <i>682.00</i>	<i>Receipt</i> \$1,455.10 ✓
1PCS	REAR BUMPER SIDE RETAINER N/S	<i>Sub</i> \$68.10 ✓
1SET	REAR BUMPER CLIPS	<i>nu</i> \$50.00 ✓
1PCS	REAR FENDER N/S <i>1029.00</i>	<i>Soly ID</i> \$1,488.10 ✓
1PCS	REAR FENDER INNER TRIM BOARD N/S	<i>11</i> \$845.10 X
1PCS	REAR FENDER UNEDRCOVER N/S	<i>to in</i> \$299.30 ✓
1SET	REAR FENDER UNDERSOVER CLIPS N/S	<i>nu</i> \$50.00 ✓
1PCS	REAR FENDER WHEEL HOUSING PANEL N/S	<i>n</i> \$899.10 X
1PCS	REAR FENDER GLASS MOULDING N/S	<i>nu</i> \$88.20 ✓
1PCS	FUEL LIP N/S	<i>n</i> \$145.10 X
1PCS	REAR SPLASH SHIELD N/S	<i>to in</i> \$102.30 ✓
1PCS	REAR SHOCK ABSORBER N/S	<i>4w</i> \$298.50 ✓
1PCS	REAR WHEEL HUB BEARING N/S	<i>Page</i> \$645.10 ✓
1PCS	REAR AXLE BEAM ASSY	<i>8w</i> \$2,655.10 X
1PCS	REAR AIR VENT N/S	<i>4w</i> \$84.50 ✓
		\$9,173.60
		<i>25%</i>
		<i>3400.2</i>
		<i>2550.15</i>
1PCS	S.NETT	<i>22/3/18</i> \$800.00 600
1PCS	REAR SPORT RIM N/S	<i>8w</i> \$200.00 X
1PCS	REAR TYRE N/S	<i>nu</i> \$50.00 30
1PCS	REAR FENDER GLASS SEALANT	<i>nu</i> \$800.00 500
1SET	REAR FENDER SOUND PROOFING INSULATOR	
	TO CHECK WIRING	\$50.00 20
	TO DISMENTLE & REFIX REVERSE SENSOR	\$80.00 50
	TO DISMENTLE & REFIX FUEL TANK	\$100.00 60
	TO DISMENTLE & REFIX SEAT, CUSHION UPHOLTERY	\$180.00 80
	TO CONDUCT WHEEL ALIGNMENT	\$100.00 60
	TO SPRAY RUST PROOFING	\$80.00 30
	TO DISMENTLE & REPLACING REAR UNDERCARRIAGE	\$380.00 120
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,200.00 680
	TO PUTTY & SPRAY PAINTING	\$1,500.00 600

TOTAL \$14,693.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: