

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018831
Speed Arrive

Page 1 of 2
Your ref. TP-YN 5321X AXA
Job No. 69332
Our ref. 18.03.32
Payment
Date 21/3/2018

Attn

Vehicle No SJK 289H
Vehicle Model : BMW 318i
Accident on ... 20/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	1,220.00		def ✓ 1,220.00
1.00	Pc	Rear parking sensor RH, centre	265.00		shot ✓ 265.00
1.00	Pc	Rear bumper reinforcement	465.00		mn x 465.00
1.00	Pc	Rear end panel	640.00		R x 640.00
1.00	Pc	Rear tail lamp LH	375.00		mp x 375.00
1.00	Pc	Rear BMW logo emblem	80.00		nc ✓ 80.00
1.00	Pc	Rear 318i emblem	70.00		nc ✓ 70.00
Special nett item:					
1.00	Pc	Rear number plate	35.00		bf ✓ 35.00
Labour & Misc:					
1.00		Tuff coat	80.00		30 80.00
1.00		To straighten rear body including cutting and welding, to knock dents on rear boot lid	1,000.00		800 1,000.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018831
Speed Arrive

Page 2 of 2
Your ref. TP-YN 5321X AXA
Job No. 69332
Our ref. 18.03.32
Payment
Date 21/3/2018

Attn

Vehicle No SJK 289H
Vehicle Model : BMW 318i
Accident on ... 20/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		and renew of parts			
1.00		To spray paint	700.00	600	700.00

W/A Anthon
P/P Repair

LKK Auto Consultants hence notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insured Company

Acknowledged by Repairer: _____
Signature: _____
Date: _____

26/3/2018
W/A Anthon

Sub-Total 4,930.00
GST 7.00% 345.10
Total SS 5,275.10

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

SUPPLEMENTARY ESTIMATE

EST. No EST0018831
Speed Arrive

Page 1 of 1
Your ref. TP-YN 5321X AXA
Job No. 69332
Our ref 18.03 32
Payment
Date 26/3/2018

Attn

Vehicle No ... SJK 289H
Vehicle Model : BMW 318i
Accident on ... 20/3/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item:					
SUPPLEMENTARY ITEM:					
1.00	Pc	Rear boot lid lock	280.00		<i>Del</i> 280.00 ✓

Sub-Total 280.00
GST 7.00% 19.60
Total S\$ 299.60

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."