



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811
ATTN.: MOTOR CLAIMS
FAX:

NAME: Ms Lim Chyng Ying
ADDRESS: 326 ANG MO KIO AVENUE 3
#06-1992
Singapore 560326
TEL: 97388003

WIP: 13617
EXCESS:
DATE: 19-Mar-18

VEH NO: SLL1376D
CHASSIS NO: JM6BM42A8G0346086
MODEL: MAZDA3 1.5L

DATE IN:
MILEAGE:
DATE REG.: 15-Feb-17

CONTACT PERSON:
TYPE OF CLAIM: 3RD PARTY CLAIM
POLICY NO.:

JESS 6395 7874

NATURE OF WORKS

NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	\$ 1,074.80
2	RETAINER(RHS), REAR BUMPER	1	MBHN1-50-2H1A	\$ 36.10
3	BRACKET(RHS), REAR BUMPER	1	MBHN9-51-067B	\$ 45.60
4	REFLECTOR RHS	1	MD350-51-5M0E	\$ 50.40
5	SENSOR,ULTRASONIC (SIDE)	1	MKD47-67-UC1 53	\$ 193.90
6	RETAINER SIDE, SENSOR	1	MKD47-67-UC5A53	\$ 17.30
7	TAPE PROTECTOR, SENSOR	3	MGS1D-50-EM1A	\$ 24.30
8	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 11.20
9	CLIP, REAR BUMPER	2	MGJ21-50-049	\$ 6.40
10	RIVET, REAR BUMPER	4	MBBM4-50-355	\$ 16.80
11	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80
12	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00
13	GASKET(LHS), TAILLAMP	1	MBHN1-51-163	\$ 20.90
14	GASKET(RHS), TAILLAMP	1	MBHN1-51-153	\$ 20.90
15	FASTENER, TAILLAMP	2	MKD53-51-146B	\$ 7.80
16	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	\$ 29.80
17	GUARD(RHS), STONE	1	MBHS2-50-4P2	\$ 17.30
18	RHS REAR DOOR	1	MBJY0-72-02XF	\$ 999.40
19	FASTENER, REAR DOOR	1	MBHN9-72-762	\$ 4.40
20	FASTENER, REAR DOOR	1	MGD7A-50-EA1	\$ 3.00
21	PIN-CATCH, REAR DOOR	1	MBN8F-72-917	\$ 10.40
22	CLIP, REAR DOOR	1	MGS1D-58-315A	\$ 2.20
23	GROMMET, REAR DOOR	4	MBF67-51-261	\$ 8.80
24	GROMMET, REAR DOOR	1	M9991-00-503	\$ 3.60
25	GROMMET, REAR DOOR	7	MGJ6A-58-975	\$ 19.60
26	CLIP, DOOR GARNISH	5	MKD53-50-M38	\$ 58.50
27	GROMMET, DOOR SPEAKER	4	MGJ6A-58-975	\$ 11.20
28	WHEEL,DISC (RHR)	1	M9965-D0-6560	\$ 1,101.70
TOTAL PARTS				\$ 3,809.10

		LESS 10%		\$ 380.91
		TOTAL PARTS COST		\$ 3,428.19
Labour Description				
1		TO REPLACE REAR BUMPER AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	750	\$ 2,640.00
2	MZ-SP-SSIDE4	TO RESPRAY REAR BUMPER, REAR FENDER AND REAR DOOR.	1890	\$ 2,520.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	117X	\$ 250.00
4	MZ-BR-REVEN	TO TRANSFER REVERSE SENSORS.	200	\$ 660.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	117X	\$ 660.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
8	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
TOTAL LABOUR			\$ -	\$ 7,430.00
TOTAL PARTS			\$ -	\$ 3,428.19
TOTAL			\$ -	\$ 10,858.19
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	\$ -
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
SUPPLEMENTARY ESTIMATE COST OF REPAIRS



AXA INSURANCE SINGAPORE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Lim Chyng Ying ADDRESS : 326 ANG MO KIO AVENUE 3 #06-1992 Singapore 560326 TEL : 97388003		WIP : 13617 EXCESS : DATE: 19-Mar-18	
VEH NO :	SLL1376D	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BM42A8G0346086	MILEAGE :		TYPE OF CLAIM :	3RD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	15-Feb-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
	TOTAL PARTS				\$ -
	LESS 10%				\$ -
	TOTAL PARTS COST				\$ -
Labour Description					
1	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. <i>ADD</i>		NETT	\$ 120.00
2	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. <i>250</i>		NETT	\$ 560.00
TOTAL LABOUR				\$ -	\$ 680.00
TOTAL PARTS				\$ -	\$ -
TOTAL				\$ -	\$ 680.00
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



AXA INSURANCE SINGAPORE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN. : MOTOR CLAIMS FAX :		NAME : Ms Lim Chyng Ying ADDRESS : 326 ANG MO KIO AVENUE 3 #06-1992 Singapore 560326 TEL : 97388003		WIP : 13617 EXCESS : DATE: 19-Mar-18	
VEH NO :	SLL1376D	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BM42A8G0346086	MILEAGE :		TYPE OF CLAIM :	3RD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	15-Feb-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	\$ 1,074.80	\$ 1,074.80
2	RETAINER(RHS), REAR BUMPER	1	MBHN1-50-2H1A	\$ 36.10	\$ 36.10
3	BRACKET(RHS), REAR BUMPER	1	MBHN9-51-067B	\$ 45.60	\$ 45.60
4	REFLECTOR RHS	1	MD350-51-5M0E		\$ 50.40
5	SENSOR,ULTRASONIC (SIDE)	1	MKD47-67-UC1 53		\$ 193.90
6	RETAINER SIDE, SENSOR	1	MKD47-67-UC5A53		\$ 17.30
7	TAPE PROTECTOR, SENSOR	3	MGS1D-50-EM1A		\$ 24.30
8	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 11.20	\$ 11.20
9	CLIP, REAR BUMPER	2	MGJ21-50-049	\$ 6.40	\$ 6.40
10	RIVET, REAR BUMPER	4	MBBM4-50-355	\$ 16.80	\$ 16.80
11	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
12	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
13	GASKET(LHS), TAILLAMP	1	MBHN1-51-163	\$ 20.90	\$ 20.90
14	GASKET(RHS), TAILLAMP	1	MBHN1-51-153	\$ 20.90	\$ 20.90
15	FASTENER, TAILLAMP	2	MKD53-51-146B	\$ 7.80	\$ 7.80
16	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	\$ 29.80	\$ 29.80
17	GUARD(RHS), STONE	1	MBHS2-50-4P2	\$ 17.30	\$ 17.30
18	RHS REAR DOOR	1	MBJY0-72-02XF		\$ 999.40
19	FASTENER, REAR DOOR	1	MBHN9-72-762		\$ 4.40
20	FASTENER, REAR DOOR	1	MGD7A-50-EA1		\$ 3.00
21	PIN-CATCH, REAR DOOR	1	MBN8F-72-917		\$ 10.40
22	CLIP, REAR DOOR	1	MGS1D-58-315A		\$ 2.20
23	GROMMET, REAR DOOR	4	MBF67-51-261		\$ 8.80
24	GROMMET, REAR DOOR	1	M9991-00-503		\$ 3.60
25	GROMMET, REAR DOOR	7	MGJ6A-58-975		\$ 19.60
26	CLIP, DOOR GARNISH	5	MKD53-50-M38		\$ 58.50
27	GROMMET, DOOR SPEAKER	4	MGJ6A-58-975		\$ 11.20
28	WHEEL,DISC (RHR)	1	M9965-D0-6560	\$ 1,101.70	\$ 1,101.70
TOTAL PARTS				\$ 2,402.10	\$ 3,809.10
LESS 10%				\$ 240.21	\$ 380.91

		TOTAL PARTS COST	\$ 2,161.89	\$ 3,428.19
Labour Description				
1		TO REPLACE REAR BUMPER AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 750.00	\$ 2,640.00
2	MZ-SP-SSIDE4	TO RESPRAY REAR BUMPER, REAR FENDER AND REAR DOOR.	\$ 1,890.00	\$ 2,520.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 200.00	\$ 660.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.		\$ 660.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
8	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
9	SUPP	TO MOUNT SPORT RIM & CONDUCT WHEEL BALANCING	\$ 80.00	\$ 120.00
10	SUPP	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	\$ 250.00	\$ 560.00
			TOTAL LABOUR	\$ 3,460.00 \$ 8,110.00
			TOTAL PARTS	\$ 2,161.89 \$ 3,428.19
			TOTAL	\$ 5,621.89 \$ 11,538.19
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 5,621.89
			GST 7%	\$ 393.53 \$ -
			GRAND TOTAL	\$ 6,015.42 \$ -

REMARKS:

6 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)