

3/22/2018

Estimate Report



Main Office : No. 22, Jalan Kiang, Singapore 159419
Tel: 6476 3333 Fax: 6271 6891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/05/06/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/03/2018
Vehicle Reg. No.:	SKS2100B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Vehicle Reg. Date:	31/03/2015
Vehicle Colour:	WHITE	Chassis No:	ZSU600040133
Engine No:	3ZRB528759		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %	Nett Item Discount:	10.00 %
Total Loss?	NO		
Est. Duration of Repair (day)	16		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	7,796.00
Miscellaneous Items	10.00
Labour	2,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,466.00
+ GST 7.00% (S\$)	732.62
Nett Amount (S\$)	11,198.62

This claim is handled by: SAMUEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tayfun 97495749
WP
23/3/18 e 1715
Lumpsum
Repair after repair
Today
Sinc@ LKK auto con

3/22/2018

Estimate Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Mar 2018)

Parts: N/A TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKS2100B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE	25.00	0.00	*620.00 FL <i>ab</i>
2	10		*FRONT GRILLE CLIPS	25.00	0.00	*50.00 FL <i>na</i>
3	1		*BONNET CHROME MOULDING	25.00	0.00	*363.00 FL <i>at</i>
4	1		*FRONT BUMPER	25.00	0.00	*1,650.00 FL <i>Rx</i>
5	1		*FRONT BUMPER SPONGE - CHECK	25.00	0.00	-
6	1		*FRONT BUMPER SPONGE LH - CHECK	25.00	0.00	-
7	1		*FRONT BUMPER SPONGE RH - CHECK	25.00	0.00	-
8	2		*FRONT BUMPER TOW COVER	25.00	0.00	*140.00 FL <i>Ry</i>
9	1		*FRONT BUMPER LOWER GRILLE	25.00	0.00	*288.00 FL <i>?</i>
10	1		*FRONT BUMPER LIP - CHECK	25.00	0.00	-
11	15		*FRONT BUMPER CLIPS	25.00	0.00	*75.00 FL <i>na</i>
12	1		*FRONT BUMPER RETAINER LH	25.00	0.00	*60.00 FL <i>X</i>
13	1		*FRONT BUMPER RETAINER RH	25.00	0.00	*60.00 FL <i>X</i>
14	2		*REAR WINDSCREEN MOULDING	25.00	0.00	*220.00 FL <i>na</i>
15	1		*TAILGATE	25.00	0.00	*2,550.00 FL <i>bt</i>
16	1		*TAILGATE EMBLEM (HARRIER)	25.00	0.00	*130.00 FL <i>de</i>
17	1		*REAR BUMPER	25.00	0.00	*1,580.00 FL <i>de</i>
18	1		*REAR BUMPER LIP	25.00	0.00	*550.00 FL <i>de</i>
19	1		*REAR BUMPER REFLECTOR RH	25.00	0.00	*110.00 FL <i>X</i>
20	1		*REAR BUMPER RETAINER LH	25.00	0.00	*102.00 FL <i>X</i>
21	1		*REAR BUMPER RETAINER RH	25.00	0.00	*102.00 FL <i>na</i>
22	1		*REAR BUMPER SPONGE	25.00	0.00	*158.00 FL <i>?</i>
23	10		*REAR BUMPER CLIPS	25.00	0.00	*50.00 FL <i>na</i>
24	1		*REAR END PANEL - TBA	25.00	0.00	-
25	1		*REAR END PANEL TOP GARNISH	25.00	0.00	*510.00 FL <i>?</i>
26	1		*REAR FLOOR PANEL SPONGE - CHECK	25.00	0.00	-
27	1		*REAR LAMP OUTER RH	25.00	0.00	*540.00 FL <i>?</i>
28	1		*TAILLAMP PANEL BRACKET RH - CHECK	25.00	0.00	-
29	1		*FRONT NUMBER PLATE	0	0.00	*40.00 FS <i>bt</i>
30	1		*TOWING CHARGE	0	0.00	*85.00 FS <i>? Receipt</i>
31	1		*WINDSCREEN REAR SEALANT	0	0.00	*40.00 FS <i>na</i>
32	1		*REAR REVERSE SENSOR	0	0.00	*200.00 FS <i>na</i>

F=Franchise part, S=SpNetL, L=ListItemDisc.

Sub Total (\$\$) 10,273.00

- List Item Discount on L Items (\$\$) 2,477.00

Total Parts (\$\$) 7,796.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

3/22/2018

Estimate Report

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CUT/WELD REAR END PANEL, TO KNOCK AND STRAIGHTEN REAR FLOOR PANEL, REAR CHASSIS LH & RH, FRONT SUPPORT PANEL, BONNET, REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. TO REALIGN ALL CONNECTION	New	1,050.00
2	TO SPRAY PAINT ON TAILGATE, REAR BUMPER, REAR END PANEL, BONNET, FRONT BUMPER	New	1,050.00
3	TO REMOVE AND REPLACE WINDSCREEN REAR AND CHECK WATER LEAKAGE	New	120.00
4	TO REMOVE AND REFIX REAR REVERSE SENSOR, REAR CAMERA AND CHECK VIEW FUNCTION	New	60.00
5	TO REMOVE AND REFIX TAILGATE LOCK MECHANISM AND CHECK LOCKING SYSTEM	New	80.00
6	TO REMOVE AND REPLACE REAR LUGGAGE COMPARTMENT TRIM AND SPARE WHEEL, IN ORDER TO CUT OFF REAR END PANEL	New	100.00
7	TO APPLY SEAL ON WELDING JOINT	New	80.00
8	TO APPLY RUST PROOF ON AFFECTED AREAS	New	120.00
Gross Labour Cost (\$\$)			2,660.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >