

ASS. REC. BY:

REF: CS/FCI18005427/Uqbnz

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person): CWS Serena Lee of FCI Date/Time: 24/3/2018 12.48pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 5616J Insured: SHC 8329P

at Workshop m/s Chin Meng Tel: 9191 2829

of Blk 1 Kaki Bukit Ave 6 #01-40

Policy No: Claim No: D18002295MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 17/03/2018

CA / REV / REP. / REV 24 HRS 'DP' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 5616J - x
	SHC 8329P - CS/FCI17019548/Tlbnz DA: 091017
22/3/18 @ 4.58pm	revised to Serena Lee by email.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005427/Uqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8329P	Veh. Inspected	SLQ 5616J
Policy No.		Coverage (\$)	0.00
Claim No.	D18002295MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	23/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/03/2018	Inspection Date	23/03/2018
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	20-03-2018	Our Ref No. D18002295MFSH
Accident Date	17-03-2018	Claim Type. Third Party
Insured Vehicle	SHC8329P	Third Party Vehicle. SLQ5616J
Survey Location	1 KAKI BUKIT AVE 6 #01-40 AUTOBAY@KAKI BUKIT	
Contact Person.	QUEK KIM SENG	
Contact No.	67474810/ 91912829	Fax No. 67455018
Survey Type	DIRECT SETTLEMENT: EST. COR - \$7,556.80 (SJE)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHIN MENG MOTORS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 27 March 2018 4:58 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002295MFSH/1
Attachments: CSFCI18005427Uqb.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLQ 5616J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Saturday, 24 March 2018 2:00 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002295MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Saturday, 24 March, 2018 12:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002295MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002295MFSH

Date: 27 March 2018

Our Ref: CS/FCI18005427/Uqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 5616J .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/03/2018 at the premises of M/s CHIN MENG . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,556.80</u> .
Revised Estimate Amount	: S\$ <u>4,082.50</u> .
“Check” Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 2749F

Vehicle Details

Vehicle No.: SLQ5616J
 Vehicle to be Exported: No
 Intended De-registration Date: 23 Mar 2018
 Vehicle Make: B.M.W.
 Vehicle Model: X1 SDRIVE18I AT LED NAV
 Primary Colour: White
 Manufacturing Year: 2017
 Engine No.: F032H462B38A15A
 Chassis No.: WBAHS120605J97305
 Maximum Power Output: 100.0 kW (134 bhp)
 Open Market Value: \$31,845.00
 Original Registration Date: 14 Jul 2017
 First Registration Date: 14 Jul 2017
 Transfer Count: 0
 Actual ARF Paid: \$31,583.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 13 Jul 2027
 PARF Rebate Amount: \$23,687.00

Intended COE Rebate Details

COE Expiry Date: 13 Jul 2027
 COE Category: E - Open - all except motorcycle
 COE Period(Years): 10
 QP Paid: \$48,001.00
 COE Rebate Amount: \$44,196.00
Total Rebate Amount: \$67,883.00

The information contained herein is correct as at 23 Mar 2018

OK

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
 Tel: 6747-4810 Fax: 6745-5018
 cmmotors@singnet.com.sg
 Our Ref: EST092/18/TP
 Your Ref: TP claim against SHC8329J

ESTIMATE

21-Mar-18

First Capital Insurance Ltd
 36 Robinson Road
 #16-01 City House
 Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to BMW X1 no: SLQ5616J

Date of accident: 17-03-2018

1 pc Rear bumper	Deep cut	SS 1,250.00	/
1 pc Rear bumper retainer top L/h	11	85.00	/
1 pc Rear bumper retainer lower L/h	rec	95.00	/
2 pcs Rear bumper brackets @\$185.90	11	371.80	x
8 pcs Rear bumper clips @\$5.00	rec	40.00	/
1 pc Rear bumper lip	cut	395.00	/
1 pc Rear L/h arch garnish	cut	210.00	/
1 pc Rear L/h rim	cut	1,480.00	/
1 pc Rear L/h knuckle arm	11	1,450.00	x
1 pc Rear L/h knuckle bearing	11	220.00	x
1 pc Rear L/h lower arm	11	380.00	x
1 pc Rear L/h tyre (S/Nett)	cut LP 220 = 1765.N	350.00	PO%
		<u>6,326.80</u>	

Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.
- To respray affected part.
- To remove and refit rear undercarriages
- To undergo wheel alignment
- To check wirings.

	350.00	280
	500.00	250
11	250.00	x
	100.00	60
	30.00	20
SS	<u>7,556.80</u>	

not Allowed
 L/h
 n/s #3200/2
 3 dy.

23/3/18
 Take photo after repair

7-3470
 52
3296.5
 4082.5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005427/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8329P	Veh. Inspected	SLQ 5616J
Policy No.		Coverage (\$)	0.00
Claim No.	D18002295MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	24/03/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W X1 (A)	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAHS120605J97305	Colour	WHITE
Odometer	15013	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	PIRELLI	8 mm
L/H Front Tyre	225/50 R18	PIRELLI	8 mm
R/H Rear Tyre	225/50 R18	PIRELLI	8 mm
L/H Rear Tyre	225/50 R18	PIRELLI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/03/2018	Inspection Date	24/03/2018
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 5616J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEEP CUT	1,250.00	1,250.00
1	REAR BUMPER RETAINER TOP L/H	NOT NECESSARY	85.00	-
1	REAR BUMPER RETAINER LOWER L/H	NECESSARY	95.00	95.00
2	REAR BUMPER BRACKETS @\$185.90	NOT NECESSARY	371.80	-
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR BUMPER LIP	CUT	395.00	395.00
1	REAR L/H ARCH GARNISH	CUT	210.00	210.00
1	REAR L/H RIM	CUT	1,480.00	1,480.00
1	REAR L/H KNUCKLE ARM	NOT NECESSARY	1,450.00	-
1	REAR L/H KNUCKLE BEARING	NOT NECESSARY	220.00	-
1	REAR L/H LOWER ARM	NOT NECESSARY	380.00	-
	LESS 5% DISCOUNT		-	-173.50
			5,976.80	3,296.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR L/H TYRE (\$220.00)(80%)(LOCAL PURCHASE)(SN)	CUT	350.00	176.00
			350.00	176.00
<u>LABOUR</u>				
	TO PANEL BEATING,WELDING,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC.		350.00	280.00
	TO RESPRAY AFFECTED PART.		500.00	250.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGES.	NOT NECESSARY	250.00	-
	TO UNDERGO WHEEL ALIGNMENT.		100.00	60.00
	TO CHECK WIRINGS.		30.00	20.00
	-		-	-
	-		-	-
	-		-	-
			1,230.00	610.00
GRAND TOTAL			7,556.80	4,082.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00
---	--	--	----------

Report Ref No. CS/FC118005427/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.