PDITUAS

TAN BAN WENG 6 SIN MING ROAD #04-10 Singapore, 575585 Singapore

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No.

CV026732

Quote No.

SER/QUO/1800494

QuoteDate Salesperson 22/03/18 Eric Tan

Page

1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

SKP9198P

License No.

Engine Code

Model Description

GOLF A7 1.4 TSI (DSG)RECAT

WVWZZZAUZEW401815 Labor Type

Mileage 16,229

Initial Registration

26/09/14 Engine No. CXS 202437 Service Advisor Tang Shu Shi

Sales Advisor Fric Tan

Model Code 5G13GZ

No.

P B&P MACP LABOUR P B&P MACP PAINT

P B&P MECH

Description

LABOUR SPRAY PAINT

CHECK WIRE HARNESS, ECU, S

Nett

Sum Labor

Qty. UoM **Unit Price**

2 UNIT

2 UNIT 1 Time Un 840/1,680.00

8001-1,600.00 280.00 N

3,560.00

Amount

Sum Labor	Sum Labor	
Total SGD	Total SGD	
7% GST	3,560.00	249.20
Total SGD Incl.	Total SGD Incl. GST	

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify

- the Repairer of the following: . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- BBN: - Acc.-No ..:

23/03/2018 @ 1200 mi Not Admil 7/P 3 days.

Sin PhAO offer you

Payments to: