

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3259K

MAKE :

MODEL : HYUNDAI i40

DATE 20/3/2018 14:53

AIG/LKK
LEFT REAR

PP

FZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Clips			\$ 22.00
	Rocker Panel Outer Garnish (LH)			\$ 483.60
	Rear Wheel Hup-Cap (LH)			\$ 150.70
	SUB TOTAL			\$ 1,259.90
	LESS 20%			\$ 251.98
	DISCOUNTED TOTAL			\$ 1,007.92
	Rear Door Comfortdelgro & Apps Sticker (LH)			\$ 80.00
				\$ 80.00
	Labour Charge			
	Panel Beating- Repair Rear Fender			\$ 500.00
	Spray Painting Charge-Bumper/Fender/Door/Rocker Panel			\$ 1,000.00
	Tuff Kote			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,750.00
	ESTIMATE TOTAL			\$ 2,837.92

R
R
R

Nett

R

3w

640 De

X

60

R&S

Hp 90010018

5 days

P/P

22/03/18 @ 0930

Reg after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.