

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Mar-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8457 H

1 pc	Front o/s door	\$	791.00	Ry
1 pc	Front o/s door hinge upper	\$	33.00	Xf
1 pc	Front o/s door hinge lower	\$	33.00	X Ry
1 pc	Rear o/s door	\$	765.00	bt
1 pc	Rear o/s door hinge upper	\$	33.00	Ry
1 pc	Rear o/s door hinge lower	\$	33.00	Ry
		\$	1,688.00	
		Less 10%	\$	168.80
			\$	1,519.20

S/NETT

1 set	o/s door sticker	\$	100.00	ent ✓
	Sundry	\$	50.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	120.00	X
	To dismantle / refit the front o/s door & rear o/s door inner component into new shell door	\$	300.00	60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, rear o/s door	\$	700.00	400
	To putty and spray painting on front o/s door, rear o/s door,	\$	400.00	✓
	To apply rustproofing on the repaired and replaced panels.	\$	200.00	40
		\$	3,389.20	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES. LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749
wp'
22/3/18 @ 0930
Lumpsum
Repair upon repair
4 days.
sur@lkkauto.com