

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9818H**AAD1803-182***Not Notified
11 Sep @ 255d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9818H

VF1ABL15AUC277342

RENAULT

LATITUDE

21.3.2018

(1)

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41 151.41
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>Div</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADAIOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
TOTAL		\$	16,191.51
10%		\$	1,619.15
		\$	14,572.36

Trans-cab Auto Services Pte Ltd

AAD1803-182

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9818H

Specical Nett

1SET	BUMPER CLIP FRT	\$	nn	66.00	
1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	sn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	sn	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60.00
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15.00
TOTAL		\$		438.00	
TOTAL PARTS		\$		15,010.36	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	700
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	150

Trans-cab Auto Services Pte Ltd**AAD1803-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9818H

To transfer of front fender fittings, attachment
and perform water seepage test. \$ *nn* 380.00 X

To vacuum, replace, refix and recharge air
condenser \$ *nn* 380.00 X

To replace, refix and top up coolant for radiator \$ *nn* 170.00 X

To vacuum, replace, refix and recharge Air
Intercooler \$ *nn* 170.00 X

TOTAL \$ 8,710.00

Over All Total \$ 23,720.36

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: