

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5657L**AAD1803-180***Not Notified
11 Sep \$5300k*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5657L

VF1ABL15AUC279750

RENAULT

LATITUDE

20.3.2018

17**PART****LIST**

1	HEADLAMP LH	\$	1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	152.15 X
1	FENDER PANEL FRT LH	\$	783.83 X
1	WHEELARCH FRT LH	\$	278.84 X
1	FENDER BRACKET LOWER LH	\$	15.79 X
1	FENDER INSULATOR LH	\$	130.84 X
1	DOOR PANEL FRT LH	\$	2,844.66 ✓
1	DOOR HINGE UPPER LH L70Y	\$	261.28
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK FRT LH	\$	194.77
1	DOOR LOCK FRT LH	\$	908.75
1	DOOR CATCH FRT LH	\$	131.23
1	DOOR HANDLE OUTER FRT LH	\$	477.76
1	DOOR HANDLE COVER FRT LH	\$	13.22
1	DOOR HANDLE MODULE FRT LH	\$	133.60
1	DOOR REGULATOR FRT LH	\$	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97
1	DOOR PANEL REAR LH L70Y	\$	2,844.66 ✓
1	DOOR GUIDE REAR LH L70Y	\$	176.82
1	DOOR HINGE UPPER LH L70Y	\$	274.50
1	DOOR HINGE LOWER L70Y	\$	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	203.06
1	DOOR LOCK REAR LH L70Y	\$	908.75
1	DOOR HANDLE OUTER REAR LH L70Y	\$	126.49
1	DOOR HANDLE CAP REAR LH L70Y	\$	35.52
1	DOOR HANDLE COVER REAR LH L70Y	\$	13.22
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.60
1	DOOR REGULATOR REAR LH L70Y	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	893.75

Trans-cab Auto Services Pte Ltd**AAD1803-180**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5657L

1	DOOR FINISHER REAR LH L70Y	\$	S ₂ 423.10
1	DOOR MOULDING REAR LH L70Y	\$	S ₂ 176.82
1	DOOR CASING REAR LH L70Y	\$	S ₂ 1,509.06
1	DOOR WATER SHIELD REAR LH L70Y	\$	S ₂ 30.39
1	DOOR CASING CLIP	\$	~ 12.63
1	DOOR CASING LIGHT L70Y	\$	S ₂ 48.74
1	DOOR FINISHER INNER REAR LH L70Y	\$	S ₂ 323.44
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	S ₂ 46.97
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	S ₂ 20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	S ₂ 20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	S ₂ 20.33
1	DOOR GRAB HANDLE REAR LH L70Y	\$	S ₂ 210.96
1	DOOR BLIND REAR LH L70Y	\$	S ₂ 741.80
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	S ₂ 410.66
1	DOOR SEAL REAR LH L70Y	\$	S ₂ 162.02
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	S ₂ 229.31
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	S ₂ 334.69
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	S ₂ 115.64
1	FENDER PANEL REAR LH	\$	~ 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	S ₂ 671.45
1	WHEELARCH REAR LH	\$	S ₂ 543.47
1	BUMPER COVER REAR	\$	~ 1,108.46
1	BUMPER LOWER REAR	\$	S ₂ 768.84
1	BUMPER BRACKET CTR REAR	\$	S ₂ 113.47
1	BUMEP R RETAINER LH REAR	\$	S ₂ 44.99
1	BUMPER BEAM REAR	\$	~ 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	~ 225.95
1	DOOR MIRROR ASSY LH	\$	S ₂ 1,483.40
1	TAILLAMP LH	\$	S ₂ 552.55

\$	30,706.79
----	------------------

10% \$	3,070.68
--------	-----------------

\$	27,636.11
----	------------------

Specical Nett

1SET	BUMPER CLIP FRT	\$	~ 66.00 X
1	BUMPER BRACKET CLIP FRT LH	\$	~ 12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	~ 10.50 X

Trans-cab Auto Services Pte Ltd**AAD1803-180**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5657L

1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00 X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00 X
1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50 X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00 6052
1	FRONT DOOR STICKER 'Chassis'	\$	nn 50.00 1552
1	REAR DOOR STICKER '6555 3333'	\$	nn 80.00 6052

TOTAL	\$	518.00
--------------	-----------	---------------

TOTAL PARTS	\$	28,154.11
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 500
Putty and spray painting of the affected portion.	\$	3,000.00 660
To rust-proofing of the affected areas.	\$	170.00 60
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1803-180**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5657L

To transfer of Door fittings, attachment and perform water seepage test.	\$	380.00 <i>1291</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00 X

TOTAL	\$	9,470.00
--------------	-----------	-----------------

Over All Total	\$	37,624.11
-----------------------	-----------	------------------

PART BY PART (REPAIR DAY)~~10 DAYS~~*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: