

LEONG AUTO PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

*Not witherw
L1 Sy @ 7
Paving After Pain
3 days*

ESTIMATE

Date: 22/3/2018
DOA: 20/3/2018

Vehicle No: SLA4478G
Make & Model: Honda Fit

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Front L/H Fender	\$ 430.10	X
2	1	Front L/H Fender Inner Shield	\$ 69.30	X
3	1	Front L/H Fender Quarter Garnish	\$ 73.20	X
4	1	Front L/H Fender Inner Air Guide	\$ 108.50	X
5	1	Front L/H Head Lamp	\$ 626.00	?
6	1	Front L/H Wheel Hub	\$ 160.20	?
7	1	Front L/H Wheel Hub Bearing	\$ 109.40	?
8	1	Front L/H Shock Absorber	\$ 502.60	?
9	1	Front L/H Lower Arm	\$ 254.60	?
10	1	Front Bumper Assy	\$ 722.00	✓
11	2	Front Bumper Retainer	\$ 71.70	X
12	1	Front Grille	\$ 147.20	X
13	1	Front Grille Logo Emblem	\$ 60.70	X
		Acknowledged by Repairer	\$ 3,335.50	
		Less 20%	\$ 667.10	
			\$ 2,668.40	
		Special Nett Items		
1		Sundries	\$ 50.00	X
2	1 set	Front L/H Fender Inner Shield Clips	\$ 50.00	X
3	1 set	Front L/H Head Lamp Clips	\$ 50.00	?
4	1 set	Front Bumper Clips	\$ 50.00	✓
5	1	Front L/H Rim	\$ 750.00	25000
6	1	Front L/H Tyre	\$ 500.00	X
			\$ 1,450.00	
		Total Parts	\$ 4,118.40	
S/N		Labour Description	Amount	Amount
1		Labour for panel beating, cut, weld, and replace damaged parts.	\$ 1,200.00	2000
2		To putty and spray painting damaged portion.	\$ 600.00	2000
3		To check wiring, lights and electrical parts for malfunction	\$ 50.00	150
4		To perform 4 wheel alignment and balancing.	\$ 120.00	600
5		To apply anti rust proofing to affected area.	\$ 180.00	X
6		To remove and install inner garnish and trim to facilitate the repair.	\$ 280.00	X
7		To remove undercarriage to facilitate repairs	\$ 380.00	?
		Total labour :	\$ 2,810.00	
		Total parts :	\$ 4,118.40	
		Total labour :	\$ 2,810.00	
		Total repair cost : (Before GST)	\$ 6,928.40	