

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SGU3869Y	Excess.	NIL
Policy No.	5054204504-05	Coverage.	Comprehensive
Claiming Against.	YK1038G	QBE	
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Perodua Kelisa
Engine No.	B67A51C
Chassis No.	PM2L701S002142689
Odometer	
Engine CC.	989
Year Of Reg.	2007
Colour.	Orange
Parf/COE Rebate.	\$ 21,601.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 7/2/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front bumper	\$ 160.00 ✓
1	Front bumper side retainer LH ✓	\$ 40.00 ✓
1	Front bumper side retainer RH ✓	\$ 40.00 ✓
1	Front bumper lamp LH ✗	\$ 28.00 ✗
1	Front bumper lamp RH ✗	\$ 28.00 ✗
1	Front bumper beam ?	\$ 135.00 ?
1	Front grille ✓	\$ 110.00 ✓
1	Front grille logo ✓	\$ 50.00 ✓
1	Bonnet ✓	\$ 210.00 ✓
1	Bonnet hinges LH ✓	\$ 33.00 ✗
1	Bonnet hinges RH ✗	\$ 33.00 ✗
1	Bonnet lock ✓	\$ 73.00 ✓
1	Bonnet lock catch ✗	\$ 25.00 ✗
1	Front brace panel ?	\$ 43.00 ?
1	Front headlamp LH ✓	\$ 90.00 ✓
1	Front headlamp RH ✓	\$ 90.00 ✓
1	Front headlamp panel LH R ✓	\$ 85.00 ✓
1	Front headlamp panel RH R ✓	\$ 85.00 ✓
1	Front support panel P. ✓	\$ 70.00 ?
1	Front fender RH ✗	\$ 125.00 ✗
		\$ 1,553.00
1	Front bumper clips (1 set) ✓	\$ 35.00 ✓
1	Front number plate ✓	\$ 35.00 ✓
1	Bonnet insulator ✗	
	S/N	\$ 70.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 80.00 <i>\$40</i>
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 50.00 <i>\$20</i>
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 950.00 <i>\$600</i>
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 850.00 <i>\$400</i>
	<i>4 days repair</i> LABOUR	\$ 1,930.00
	Sub Total.	\$ 3,553.00
	Add 15%	\$ 532.95
		\$ 4,085.95
	7% GST	\$ 286.02
	Grand Total	<u>\$ 4,371.97</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.