

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SGU3869Y	Excess.	NIL
Policy No.	5054204504-05	Coverage.	Comprehensive
Claiming Against.	YK1038G	QBE	
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Perodua Kelisa
Engine No.	B67A51C
Chassis No.	PM2L701S002142689
Odometer	
Engine CC.	989
Year Of Reg.	2007
Colour.	Orange
Parf/COE Rebate.	\$ 21,601.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 7/2/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

Remarks

**A) THE SURVEY WAS CONDUCTED ON A "LUMPSUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.**

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front bumper	\$ 160.00
1	Front bumper side retainer LH	\$ 40.00
1	Front bumper side retainer RH	\$ 40.00
1	Front bumper lamp LH	\$ 28.00
1	Front bumper lamp RH	\$ 28.00
1	Front bumper beam	\$ 135.00
1	Front grille	\$ 110.00
1	Front grille logo	\$ 50.00
1	Bonnet	\$ 210.00
1	Bonnet hinges LH	\$ 33.00
1	Bonnet hinges RH	\$ 33.00
1	Bonnet lock	\$ 73.00
1	Bonnet lock catch	\$ 25.00
1	Front brace panel	\$ 43.00
1	Front headlamp LH	\$ 90.00
1	Front headlamp RH	\$ 90.00
1	Front headlamp panel LH	\$ 85.00
1	Front headlamp panel RH	\$ 85.00
1	Front support panel	\$ 70.00
1	Front fender RH	\$ 125.00
		\$ 1,553.00
1	Front bumper clips (1 set)	\$ 35.00
1	Front number plate	\$ 35.00
1	Bonnet insulator	
	S/N	\$ 70.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 80.00
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 50.00
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 950.00
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 850.00
	LABOUR	<u>\$ 1,930.00</u>
	Sub Total.	\$ 3,553.00
	Add 15%	\$ 532.95
		\$ 4,085.95
	7% GST	<u>\$ 286.02</u>
	Grand Total	<u><u>\$ 4,371.97</u></u>

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.