

ASS. REC. BY:

REF: CS/MSG18005452/K/d302

Special Instruction:

Surveyor
Mehmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSIG

Date/Time:

23/3/18 03:15pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH GOB

Insured:

GT 264S

at Workshop in/s

Optima Werkz

Tel:

6484 9919

of

9A Serangoon North Ave S

Policy No:

P28933 425 MKC

Claim No:

552609

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wup'

H.O.D. Endorsement:

Date/Time:

3:24pm @ 23/3/18

Person Contacted:

Riza

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH GOB - X

GT 264S - X

5/4/18

@ 11:36 a.m. revised to Jasmine Lok Kheng Wei via mehermen.

Part by Part \$ 17,205.40! Cred: 872, 4.87%

ASS. REC. BY:

REF: MS61

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

6

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/25

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SG14 60BYr Regn: 10, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Porsche Boxsterc.c. 2687Colour: In Silver

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 136584

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPOZZZ98Z5U70252Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim orTyre Size: F: 235/35ZR19R: 265/35ZR19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 6 mmL/Bal. 5 mmL/Bal. 6 mmD.O.A. 14/3/18D.O.I. 23/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/3

Re pass to Customer

RECEIVED 23 NOV 2018

26/11/2018

Date/Time, File Pass to?

1) 26/11/2018

Date/Time, File Return to?

2) _____



: Prel. Report



: Final Report

Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee: 300

Transportation: _____

S + RS. \$ _____

Photos _____

Others 10

TOTAL

310Report Format: TDLump Sum / I.B.I. (\$) 17205.40

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Mar 2018		23 Mar 2018 15:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FONG TAT MOTOR CO PTE LTD, Co. Reg. No.: NA		
Main Claimant:	LIU HSIN SHAN, ID: S2761654B		
Vehicle Reg. No.:	SGH60B	Date of Loss:	14/03/2018 09:00 - :59
Claim Type:	TP / 552609	Policy/Cover Note No.:	P28933425MKC (TP, Fire & Theft) Coverage: 10/04/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	GT264S	Policy No. (Claimant):	
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/03/2018]		
Driver/Custodian (Insured):	CHEANG GIOK CHUAN (52 / Male), NRIC: S1681783Z		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005452/Ktd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 264S	Veh. Inspected	SGH 60B	
Policy No.	P28933425MKC	Coverage (\$)	0.00	
Claim No.	552609	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/03/2018	Inspection Date	23/03/2018	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: GT264S	Accident Date	: 14/03/2018
TP Vehicle No	: SGH60B	Assignment Date	: 23/03/2018
Make	: PORSCHE BOXSTER	Est. Duration of Repair	: 4 days
Date of Inspection	: 23/03/2018		
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,933.40
Revised Amount	:S\$	13,403.40
Check Items (Estimated)	:S\$	1,885.00
Total	:S\$	15,288.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

<u>PAY</u>	<u>UNPAID</u>
2220.00	750.00
660.00	30.00
64.00	540.00
4200.00	330.00
480.00	
4050.00	
900.00	
390.00	
80.00	
72.00	
90.00	
120.00	

[illegible]

<u>PAY</u>	<u>UNPAID</u>
600.00	400.00
600.00	150.00
30.00	70.00
	280.00
	120.00

1650.00

25.00

1020.00

14976.00
13326.00
1650.00

205.00
180.00
25.00

2250.00
1230.00
1020.00

1230.00 LABOUR (PAY)

13403.40

750.00
30.00
540.00
330.00

}

CHECK ITEM

1885.00

TOTAL = 15288.40 (PAY ITEM + CHECK ITEM)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/03/2018 15:47
Date Of Accident	14/03/2018 09:30
Exact Location Of Accident	FONG TAT BUILDING 3 KALLANG WAY 2A 347493 OPEN CP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGH60B
Insured/Policyholder	
Name Of Registered Owner	LIU HSIN SHAN
NRIC No	S2761654B
Email Address	SAMLIU199@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97115977
Alternative Phone No	OFFICE-97115977
Vehicle Particulars	
Manufacturer	PORSCHE
Model	BOXSTER 2.7 TIP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI17V05529
Cover Note Number	N.A.
Driver	
Name of Driver	LIU HSIN SHAN
NRIC No	S2761654B
Date Of Birth	09/01/1966
Occupation	INDOOR
Date Of Driving Pass	22/10/2009
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97115977
Fax Number	
Contact Number	OFFICE-97115977
EMail Address	SAMLIU199@GMAIL.COM

Address	260 JOO CHIAT PLACE #04-04
Postcode	427941
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE PARKED STATIONARY AT OPEN CP OF FONGTAT BUILDING. THIS MORNING, THE SECURITY GUARD CAME OVER TO ME AND TOLD ME SOMEONE COLLIDED ONTO MY FRONT RIGHT PORTION. SO I DECIDED TO CAME DOWN AND CHECK. MY FRONT RIGHT PORTION IS BROKEN. SECURITY GUARD ABLE TO GAVE ME THIRD PARTY DRIVER DETAILS. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT264S
Vehicle Make/Model/Colour	TOYOTA/ DYNA/ SILVER
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEANG GIOK CHUAN
NRIC/Passport Number	S1681783Z
Contact Number	90195006
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

3:23 pm

14/3/18


VERIFIED BY AJAX MARS
REPORTING OFFICER
THOMAS NG CHIN CHUN

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

MY VEHICLE PARKED STATIONARY AT OPEN CP OF FONGTAT BUILDING. THIS MORNING, THE SECURITY GUARD CAME OVER TO ME AND TOLD ME SOMEONE COLLIDED ONTO MY FRONT RIGHT PORTION. SO I DECIDED TO CAME DOWN AND CHECK. MY FRONT RIGHT PORTION IS BROKEN. SECURITY GUARD ABLE TO GAVE ME THIRD PARTY DRIVER DETAILS. NO INJURIES INVOLVED.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No. Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
NG CHIN CHUN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

14 March 2018 at 3:36 PM

Date/Time:

14 March 2018 at 3:36 PM

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: MSIG

Vehicle No: SGH60B

Third Party Veh No: GT2645

Model: PORSCHE BOXSTER 2.7 TIP

Date of Accident: 14/03/2018

Chassis: WPOZZZ98Z5U702520

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	FRONT FENDER RH		<i>Rs</i> \$2,220.00	✓
1	FRONT FENDER INNER SHIELD 'FRONT'		<i>CM</i> \$660.00	✓
8	FRONT FENDER INNER SHIELD CLIP	\$8.00	<i>Rs</i> \$64.00	✓
1	FRONT HEADLAMP RH		<i>Rs</i> \$4,200.00	✓
1	FRONT HEADLAMP LOWER BRACKET RH		<i>Rs</i> \$750.00	✓
1	FRONT HEADLAMP NOZZLE RH		<i>Rs</i> \$480.00	✓
1	FRONT BUMPER		<i>CM</i> \$4,050.00	✓
1	FRONT BUMPER FOG LAMP RH		<i>MSIG</i> \$900.00	✓
1	FRONT BUMPER LOWER SIDE GRILLE RH		<i>Rs</i> \$390.00	✓
10	FRONT BUMPER CLIP	\$8.00	<i>Rs</i> \$80.00	✓
8	FRONT BUMPER RIVET	\$9.00	<i>Rs</i> \$72.00	✓
1	FRONT BUMPER SIDE RETAINER RH		<i>Rs</i> \$90.00	✓
1	FRONT BUMPER SIGNAL LAMP RH		<i>CM</i> \$120.00	✓
1	FRONT BUMPER CENTRE RETAINER		<i>Rs</i> \$30.00	✓
1	FRONT AIRCON CONDENSER AIR GUIDE RH		<i>CM</i> \$540.00	✓
1	FRONT AIRCON CONDENSER BRACKET		<i>Rs</i> \$330.00	✓
SUB TOTAL			\$14,976.00	\$14,946.00
Less 10%			-\$1,497.60	\$14,946.00
PARTS TOTAL			\$13,478.40	\$13,451.40

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$	
1	FRONT FENDER ARTING STICKER RH		<i>Rs</i> \$180.00	✓
1	FRONT BUMPER NUMBER PLATE		<i>Rs</i> \$25.00	x
S/N TOTAL			\$205.00	\$180.00

*Not within
1.3.1
Review by pain
6 days*

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143 Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: MSIG

Vehicle No: SGH60B

Third Party Veh No: GT264S

Model: PORSCHE BOXSTER 2.7 TIP

Date of Accident: 14/03/2018

Chassis: WPOZZZ98Z5U702520

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	600
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$750.00	600
TO CHECK WIRING, WITH WATER LEAKAGE TEST	\$100.00	300
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	? 1800
TO DISMANTLE & REINSTALL AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	\$120.00	? 1000
	LABOUR TOTAL	\$2,250.00 \$1630.00
WINSON	TOTAL	\$15,933.40 1510

18017.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 06 April 2018

Third Party Insurer: MSIG

Vehicle No: SGH60B

Third Party Veh No: GT2645

Model: PORSCHE BOXSTER 2.7 TIP

Date of Accident: 14/03/2018

Chassis: WPOZZZ98Z5U702520

SUPPLEMENTARY

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT RADIATOR AIR GUIDE RH		<i>CM</i> \$570.00 ✓
1	FRONT RADIATOR BRACKET RH		<i>DIR</i> \$310.00 ✓
1	FRONT RADIATOR RH		<i>Rn</i> \$1,280.00 ✓
SUB TOTAL			\$2,160.00
LESS 10%			\$216.00
PARTS TOTAL			\$1,944.00

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	RADIATOR COOLANT		<i>Rn</i> \$80.00 ✓ <i>5012n</i>
S/N TOTAL			\$80.00

LABOUR CHARGES:

TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST

\$120.00 ✓ *801*

LABOUR TOTAL \$120.00

WINSON

TOTAL \$2,144.00

P - \$ 13451.40

SN - \$ 180.00

L - \$ 1630.00

SP - \$ 1944.00

SGN - \$ 80.00

SL - \$ 120.00

\$17405.40 P/P

17 ~~025~~ 40
205

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 20 March 2018

Third Party Insurer: MSIG

Vehicle No: SGH60B

Third Party Veh No: GT264S

Model: PORSCHE BOXSTER 2.7 TIP

Date of Accident: 14/03/2018

Chassis: WPOZZZ98Z5U702520

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT FENDER RH		<i>R</i> \$2,220.00
1	FRONT FENDER INNER SHIELD 'FRONT'		<i>CM</i> \$660.00
8	FRONT FENDER INNER SHIELD CLIP	\$8.00	<i>RM</i> \$64.00
1	FRONT HEADLAMP RH		<i>RM</i> \$4,200.00
1	FRONT HEADLAMP LOWER BRACKET RH		\$750.00
1	FRONT HEADLAMP NOZZLE RH		<i>RM</i> \$480.00
1	FRONT BUMPER		<i>CM</i> \$4,050.00
1	FRONT BUMPER FOG LAMP RH		<i>RM</i> \$900.00
1	FRONT BUMPER LOWER SIDE GRILLE RH		<i>RM</i> \$390.00
10	FRONT BUMPER CLIP	\$8.00	<i>RM</i> \$80.00
8	FRONT BUMPER RIVET	\$9.00	<i>RM</i> \$72.00
1	FRONT BUMPER SIDE RETAINER RH		<i>RM</i> \$90.00
1	FRONT BUMPER SIGNAL LAMP RH		<i>CM</i> \$120.00
1	FRONT BUMPER CENTRE RETAINER		\$30.00
1	FRONT AIRCON CONDENSER AIR GUIDE RH		\$540.00
1	FRONT AIRCON CONDENSER BRACKET		\$330.00
		SUB TOTAL	\$14,976.00
		Less 10%	-\$1,497.60
		PARTS TOTAL	\$13,478.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	FRONT FENDER ARTING STICKER RH		<i>RM</i> \$180.00
1	FRONT BUMPER NUMBER PLATE		<i>RM</i> \$25.00
		S/N TOTAL	\$205.00

*Not authorized
I.B.I
Resurvey B4 paint
today*

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	20 March 2018	Third Party Insurer:	MSIG
Vehicle No:	SGH60B	Third Party Veh No:	GT264S
Model:	PORSCHE BOXSTER 2.7 TIP	Date of Accident:	14/03/2018
Chassis:	WPOZZZ98Z5U702520		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00	6000
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$750.00	6000
TO CHECK WIRING, WITH WATER LEAKAGE TEST	\$100.00	300
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	?
TO DISMANTLE & REINSTALL AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL	\$120.00	?

LABOUR TOTAL	\$2,250.00
--------------	------------

WINSON	TOTAL	\$15,933.40
--------	--------------	--------------------




































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Mar 2018		23 Mar 2018 15:15 Edit Adj Rpt	S\$17,205.40 Edit Estimates	S\$17,205.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	FONG TAT MOTOR CO PTE LTD , Co. Reg. No.: NA								
Main Claimant:	LIU HSIN SHAN , ID: S2761654B								
Vehicle Reg. No.:	SGH60B	Date of Loss:	14/03/2018 09:00 - :59 [148 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 552609	Policy/Cover Note No.:	P28933425MKC (TP, Fire & Theft) Coverage: 10/04/2017 - 30/09/2018						
Vehicle Reg. No. (Insured):	GT264S	Policy No. (Claimant):							
		Excess:							
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/04/2018]								
Driver/Custodian (Insured):	CHEANG GIOK CHUAN (52 / Male), NRIC: S1681783Z								
Adj Asg. Remarks:	ON WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGH60B (552609)
[GT264S]
TP
LIU HSIN SHAN
Mar 14 2018 9:00AM
[FONG TAT MOTOR CO PTE LTD]
Optima Werkz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	05/04/18 11:36	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
2	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
3	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
4	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
5	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
6	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
7	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
8	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
9	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
10	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
11	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
12	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
13	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
14	26/11/18 11:52	General View						Load JPG	<input checked="" type="checkbox"/>	
15	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
16	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
17	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
18	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
19	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
20	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
21	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
22	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
23	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
24	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
25	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
26	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
27	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
28	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
29	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
30	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
31	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
32	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
33	26/11/18 11:55	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
34	26/11/18 11:55	Reinspection Photo						Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/11/18 11:55	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/03/18 14:51	TP EST BILL & ACCDT REPORT	Load PDF	
2	23/03/18 14:52	E-FILE REPORT (GT264S)	Load PDF	
3	23/03/18 14:52	E-FILE REPORT (SGH60B)	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/18 09:29	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005452/KTD3E2

Date: 27/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: P28933425MKC

Claimant Vehicle No : SGH60B

Insured Vehicle No : GT264S

Date of Loss: 14/03/2018

Nature of Claim: TP

Claim No: 552609

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH60B

Make & Model: PORSCHE BOXSTER, 2.7 (A)

Engine No: 61506187

Reg. Date: 20/10/2005 (Man. Year: 2005)

Chassis No: WPOZZZ98Z5U702520

Colour: Metallic Silver

Odometer: 136584 km

Engine Capacity: 2687 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19

Rear Tyre Size: 265/35Z R19

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,707.40	15,615.40	92.00	0.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,590.00	780.00	32.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,077.40	17,205.40	872.00	4.82
+ GST 7.00/7.00% (S\$)	1,265.42	1,204.38	61.04	4.82
Nett Amount (S\$)	19,342.82	18,409.78	933.04	4.82

INSPECTION

Date of Assignment: 23/03/2018

Date Inspected: 23/03/2018

Inspected At:

Optima Werkz Pte Ltd (HQ)

9A Serangoon North Ave 5

Singapore 554500

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Nov 2018)	
Parts:	N/A	PORSCHE BOXSTER 2.7 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH60B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	2,220.00 FL	*2,220.00 FL
2	1		*FRONT FENDER INNER SHIELD FRONT	Cracked	660.00 FL	*660.00 FL
3	8		*FRONT FENDER INNER SHIELD CLIP	Necessary	64.00 FL	*64.00 FL
4	1		*FRONT HEADLAMP RH	Cut	4,200.00 FL	*4,200.00 FL
5	1		*FRONT HEADLAMP LOWER BRACKET RH	Bent	750.00 FL	*750.00 FL
6	1		*FRONT HEADLAMP NOZZLE RH	Missing	480.00 FL	*480.00 FL
7	1		*FRONT BUMPER	Cracked	4,050.00 FL	*4,050.00 FL
8	1		*FRONT BUMPER FOG LAMP RH	MTG Cracked	900.00 FL	*900.00 FL
9	1		*FRONT BUMPER LOWER SIDE GRILLE RH	Distorted	390.00 FL	*390.00 FL
10	10		*FRONT BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
11	8		*FRONT BUMPER RIVET	Necessary	72.00 FL	*72.00 FL
12	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	90.00 FL	*90.00 FL
13	1		*FRONT BUMPER SIGNAL LAMP RH	Cracked	120.00 FL	*120.00 FL
14	1		*FRONT BUMPER CENTRE RETAINER	Serviceable	30.00 FL	*- FL
15	1		*FRONT AIRCON CONDENSER AIR GUIDE RH	Cracked	540.00 FL	*540.00 FL
16	1		*FRONT AIRCON CONDENSER BRACKET	Distorted	330.00 FL	*330.00 FL
17	1		*FRONT FENDER ARTING STICKER RH	Necessary	180.00 FS	*180.00 FS
18	1		*FRONT BUMPER NUMBER PLATE	Serviceable	25.00 FS	*- FS
19	1		*FRONT RADIATOR AIR GUIDE RH	Cracked	570.00 FL	*570.00 FL
20	1		*FRONT RADIATOR BRACKET RH	Distorted	310.00 FL	*310.00 FL
21	1		*FRONT RADIATOR RH	Punctured	1,280.00 FL	*1,280.00 FL
22	1		*RADIATOR COOLANT (50%)	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,421.00	17,326.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,713.60	1,710.60
Total Parts (S\$)	15,707.40	15,615.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	750.00	600.00
3	TO CHECK WIRING, WITH WATER LEAKAGE TEST	New	100.00	30.00
4	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	280.00	180.00
5	TO DISMANTLE & REINSTALL AIRCON SYSTEM, VACUUM WITH FLUSHING / REFILL AIRCON GAS / OIL	New	120.00	100.00
6	TO DISMANTLE & REPLACED RADIATOR WITH HIGH PRESSURE TEST	New	120.00	80.00
Gross Labour Cost (S\$)			2,370.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >