



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT18001189	Page	1
Registration No	: SJW1885S	Date	: 20. Mar 2018	Customer No.	: WZA006
Chassis No	: MRHFC5650GT001504	Svc Advisor	:	Engine No	: R16B21601809
Model	: CIVIC 1.6 VTI YM2016	Date Time	: 20. Mar 2018 2:14:53 PM	Surveyor Name	:
Owner's Name	: DOREEN HENG GEK NOI	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/3/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:DOREEN HENG GEK NOI OWNER INSURER:TOKIO MARINE ACC DATE:17/3/2018 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE						
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10 <i>bt</i>	35	306.86	21.48	328.34
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00 <i>ne</i>	35	45.50	3.19	48.69
75722-TBA-A00	EMBLEM SETRR.	1	11.50 <i>ne</i>	35	7.47	0.52	7.99
75725-TEA-T01	EMBLEMRR.	1	10.60 <i>ne</i>	35	6.89	0.48	7.37
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1	617.20 <i>ne</i>	35	401.18	28.08	429.26
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	160.00 <i>?</i>	35	104.00	7.28	111.28
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50 <i>ne</i>	35	7.47	0.52	7.99
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50 <i>ne</i>	35	7.47	0.52	7.99
33550-TEA-T01	TAILLIGHT ASSYL.	1	273.10 <i>X</i>	35	177.51	12.43	189.94
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80 <i>?</i>	35	164.97	11.55	176.52
66100-TEC-307ZZ	PANEL SETRR.	1	236.00 <i>?</i>	35	153.40	10.74	164.14
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70 <i>X</i>	35	63.50	4.45	67.95
75701-TBA-A10	EMBLEM,H-MARK	1	11.90 <i>ne</i>	35	7.73	0.54	8.27
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1	35.30 <i>cut</i>	35	22.94	1.61	24.55
91505-TM8-003	CLIPBUMPER	6	2.00 <i>ne</i>	35	7.80	0.55	8.35
39680-TEX-Y41ZT	SENSOR ASSYPARKING	2	79.80 <i>?</i>	35	103.74	7.26	111.00
	Sum Item				1588.43	111.20	1,699.63
BOSUN	SUNDRIES	1	80.00 <i>30</i>		80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT.	1	100.00 <i>?</i>		100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	180.00 <i>/</i>		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	80.00 <i>/</i>		80.00	5.60	85.60



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT18001189	Page	2
Registration No	: SJW1885S	Date	: 20. Mar 2018	Customer No.	: WZA006
Chassis No	: MRHFC5650GT001504	Svc Advisor	:	Engine No	: R16B21601809
Model	: CMIC 1.6 VTI YM2016	Date Time	: 20. Mar 2018 2:14:53 PM	Surveyor Name	:
Owner's Name	: DOREEN HENG GEK NOI	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/3/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	60.00		60.00	4.20	64.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2400.00	1350	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2000.00	1050/1750-2400.00?	2000.00	140.00	2140.00
Sum Labor					4900.00	343.00	5,243.00
					8,900.00		
						10,488.43	
Total Amount						6,488.43	6,942.63
Total (Inclusive of GST)							6,942.63

Survey By: Ryann - Hp 90010068
Date & Time: 27/03/18 @ 09:55
Excess: _____
Status: _____
Signature: Ry

5 days
Rey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 20/3/2018 4:34:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)