

19/5/2010

INS. CASE OWNER:

CC4 / AIG18005758

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP: K. Kim Hin

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed)

Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2140.96

Loss of Rental (LOR):

S\$

700.00

(7 days)

x 100

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

2842.96

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2842.96

Name 1:

K. Kim Hin Auto Pte Ltd

Payee 2: (Strike if N.A.):

S\$

Name 2:

Payee 3: (Strike if N.A.):

S\$

Name 3:

RECEIVED 25 SEP 2018

CORRECT

0001

REF:

AXA ALG

8458/Kua3 - (u)

ASSIGNMENT

From:

Date:

04042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJT 2125L

at Workshop m/s

K Kim Hin

of

160 Sin Ming One

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-5

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJT 2125L

Yr Regn:

09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato

C.C

1591

Colour:

M. Gray

A/C

Insured / Std / NI / NA

Sp. Reading

184442

T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAFW411MA5124768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

20/3/18

D.O.I.

4/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/4 File pass to Catherine

\$2000.90 L (Red: \$2542.00 / 54%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

\$ - R6. SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18005458/ua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 23-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGL 2208J	Veh. Inspected	SJT 2125L
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	23/03/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	20/03/2018	Inspection Date	
	Survey held at	K KIM HIN AUTOMOTIVE PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 29646

Vehicle Insured : SGL 2208 J
Accident Date : 20-Mar-2018

Date : 21-Mar-2018

Our Ref : 180214 (AIG ASIA) / SHUMAN

PAGE : 1

SEE CHIN CHENG (MR)
Singapore

*Not Notified 4 days 3-5 days
6/1/18 87
Paying After Point*

ESTIMATED COST OF REPAIR FOR KIA CERATO FORTE 1.6 AT SX (2009) SJT2125L

1 pc rear bumper		Bu	601.00	—
1 pc n/s rear bumper parking sensor		Shan	226.00	—
1 pc rear bumper parking sensor wireharness		Sh	209.00	7X
4 pcs rear bumper parking sensor bracket	@ S\$ 22.00	Sh	88.00	7X
1 pc rear bumper lower cover		Sh	103.00	X
1 pc rear bumper sponge		Sh	120.00	X
1 pc rear bumper reinforcement		R	295.00	X
2 pcs rear bumper reinforcement bracket (lh/rh)	@ S\$ 52.00	R	104.00	X
1 pc n/s rear bumper inner shield		Sh	30.00	X
10 pcs rear bumper clips	@ S\$ 3.00	Sh	30.00	—
1 pc n/s taillamps		ngins	194.00	7X
1 pc n/s rear fender		R	881.00	7X
			2,881.00	
	Less 10% :		-288.10	
			2,592.90	

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

400 ✓ 750.00 7

To remove and refit reverse sensor assy.

80.00 60

To focus taillamps. To check rear wiring and lighting operation.

50.00 15/

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : SGL 2208 J

Our Ref : 180214

Page : 2

No. : 29646

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 *80*

To putty and respray on affected
portions.

750.00 *500*

Total : S\$ 4,342.90
=====

Singapore Dollars Four Thousand Three Hundred
and Forty Two and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

1051.00
- 10%
945.90 s/Parts
+ 1055.00 Labour
\$ 2000.90 ✓ ok

5 days

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

No. : 29646

Vehicle Insured : SGL 2208 J
Accident Date : 20-Mar-2018

Date : 21-Mar-2018

Our Ref : 180214 (AIG ASIA) / SHUMAN

PAGE : 1

SEE CHIN CHENG (MR)
Singapore

Not Authorized
1/1 Sy 87
Repair After Paint
3-5 days

ESTIMATED COST OF REPAIR FOR KIA CERATO FORTE 1.6 AT SX (2009) SJT2125L

1 pc	rear bumper		Bu	601.00	✓
1 pc	n/s rear bumper parking sensor		Shm	226.00	✓
1 pc	rear bumper parking sensor			209.00	?
	wireharness				
4 pcs	rear bumper parking sensor bracket	@ S\$ 22.00		88.00	?
1 pc	rear bumper lower cover		Sh	103.00	X
1 pc	rear bumper sponge		Sh	120.00	X
1 pc	rear bumper reinforcement		n	295.00	X
2 pcs	rear bumper reinforcement bracket (lh/rh)	@ S\$ 52.00	n	104.00	X
1 pc	n/s rear bumper inner shield		Sh	30.00	X
10 pcs	rear bumper clips	@ S\$ 3.00	Sh	30.00	✓
1 pc	n/s taillamps			194.00	?
1 pc	n/s rear fender			881.00	?
				2,881.00	
Less 10% :				-288.10	
				2,592.90	

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

750.00 ?

To remove and refit reverse sensor
assy.

80.00 60

To focus taillamps. To check rear
wiring and lighting operation.

50.00 15/

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SGL 2208 J

Our Ref : 180214

Page : 2

No. : 29646

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 *800*

To putty and respray on affected
portions.

750.00 *500*

Total : S\$ 4,342.90

=====

Singapore Dollars Four Thousand Three Hundred
and Forty Two and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and all is subject to final approval from Insurer/Underwriter

Acknowledged by Repairer

Signature:

Date:

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL2208J AND SGT2125L ON 20/03/2018

From: Md Ishak, Mohd Imran
To: assignments@kkauto.com, admin-a@kkauto.com
Cc: Abu Kassim, Noor Mariesa, Kaur, Baljit, Tan, Lily (AIG), Chan, Yoke Shi, Lim, Sheng Yang, Supramaniam, Darshene, Fong, Andy-SY, Chin, Lee-Ying
Sent: Thursday, 22 March, 2018 4:06:25 PM

WITHOUT PREJUDICE

Hi,

Please refer to the enclosed request from **K. Kim Hin Auto Pte Ltd**

Claim no : 9381913755SG003
Case Owner : BERNARD LER

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak
AIG
Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887194-D)
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: admin1@kkimhin.com.sg
To: Imran.Ishak@aig.com
Cc: NoorMariesa.AbuKassim@aig.com, Baljit.Kaur@aig.com, Lily.Tan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Darshene.Supramaniam@aig.com, Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, sandrakhong@gmail.com, survey@kkimhin.com.sg, simon@kkimhin.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL2208J AND SGT2125L ON 20/03/2018
Date: Thu, 22 Mar 2018 07:43:03 +0000
Dear Imran,

Kindly appoint LKK Auto Consultants Pte Ltd- Kenneth Kong.

Dear officer,

Kindly advise liability.

Thank you.

Best Regards,
Shuman
K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895

From: Md Ishak, Mohd Imran [mailto:Imran.Ishak@aig.com]
Sent: 22 March, 2018 11:03 AM
To: admin1@kkimhin.com.sg; survey@kkimhin.com.sg; simon@kkimhin.com.sg; sandrakhong@gmail.com
Cc: Abu Kassim, Noor Mariesa, Kaur, Baljit, Tan, Lily (AIG); Chan, Yoke Shi; Lim, Sheng Yang; Supramaniam, Darshene; Fong, Andy-SY; Chin, Lee-Ying
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL2208J AND SGT2125L ON 20/03/2018

WITHOUT PREJUDICE

Your Reference : SJT2125L
Our Reference : SGL2208J

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]

Sent: Thursday, March 22, 2018 10:40 AM

To: AIG SGP, Claims-Survey

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg

Subject: Accident involving SJT 2125 L and SGL 2208 J on 20/3/2018

Your ref: SGL 2208 J

Our ref: SJT 2125 L

Dear all

Enclosed the GIA report of our client SJT 2125 L, who was hit by your insured SGL 2208 J, on 20/3/2018.

Vehicle is not in yet, we will arrange for survey once ready.

Kindly provide the panel of surveyors to choose from.

Please advise liability.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2018 Edit Reg		22 Mar 2018 00:00 Edit Adj Rpt	S\$2,000.90 Edit Estimates	S\$2,000.90 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Pak Tung Sing , ID: S6972924Z		
Main Claimant:	SEE CHIN CHENG , ID: S1308139E		
Vehicle Reg. No.:	SJT2125L	Date of Loss:	20/03/2018 00:00 - :59 [101 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9381913755SG	Policy/Cover Note No.:	2100465066 (Comprehensive)
Vehicle Reg. No. (Insured):	SGL2208J	Policy No. (Claimant):	5071635727-02
		Excess:	
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJlQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (26/03/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SJT2125L (9381913755SG)**
[SGL2208J]
TP
SEE CHIN CHENG
Mar 20 2018 12:00AM
[Pak Tung Sing]
K Kim Hin Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Video															1 per page ▾			☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	27/03/18 10:29	Video - Accident From:OD - Reg. No: SGL2208J, Claimant: PAK TUNG SING													Load MP4					
Letters/Correspondences															1 per page ▾			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
Assessment Reports															1 per page ▾			☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	26/03/18 09:17	Accident Statement From:OD - Reg. No: SGL2208J, Claimant: PAK TUNG SING													Load HTM					
Documentation															1 per page ▾			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	23/03/18 16:14	EMAIL FROM AIG DD 22.03.2018													Load PDF					
2	23/03/18 16:14	ACKNOWLEDGEMENT EMAIL TO AIG DD 22.03.2018													Load PDF					
3	02/04/18 16:47	TP GIA REPORT													Load PDF					
4	09/04/18 10:18	TP ESTIMATE - MARKED													Load PDF					
5	08/10/18 13:08	AUTHORISATION TO ACT													Load PDF					
6	08/10/18 13:08	GIA SEARCH													Load PDF					
7	08/10/18 13:08	LETTER TO OI													Load PDF					
8	08/10/18 13:08	RELEASE VOUCHER													Load PDF					
9	08/10/18 13:08	RENTAL RECEIPT													Load PDF					
10	08/10/18 13:08	WORKSHOP INVOICE													Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGL2208J (Insd veh)	Model:	KIA CERATO FORTE 1.6 SX (A)
	SJT2125L (TP veh)		
Date of Accident:	20/03/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	: \$					4,646.90
Final Repair Cost	: \$					2,140.96
Loss of Use	: \$					days at \$0.00 per day
Rental (if any)	: \$					7 days
LTA / GIA Search Fee	: \$					2.00
Others:	: \$					
	: \$					
Final Settlement Sum	: \$					2,842.96

Is Third Party Workshop GIA Registered?		[X]	YES	[]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u>				
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	K. Kim Hin Auto Pte Ltd	: \$	2,842.96
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

08 Oct
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005458/KUA3S2

Date: 08/10/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100465066
Claimant Vehicle No :	SJT2125L	Insured Vehicle No :	SGL2208J
Date of Loss:	20/03/2018	Nature of Claim:	TP
		Claim No:	9381913755SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT2125L	Engine No:	G4FC9H291694
Make & Model:	KIA CERATO FORTE, 1.6 SX (A)	Chassis No:	KNAFW411MA5124768
Reg. Date:	29/09/2009 (Man. Year: 2009)	Odometer:	164442 km
Colour:	Metallic Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,592.90	945.90	1,647.00	63.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,055.00	695.00	39.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,342.90	2,000.90	2,342.00	53.93
+ GST 7.00/7.00% (S\$)	304.00	140.06	163.94	53.93
Nett Amount (S\$)	4,646.90	2,140.96	2,505.94	53.93
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,842.96		

INSPECTION

Date of Assignment:	22/03/2018	
Date Inspected:	04/04/2018	Inspected At: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	601.00 FL	*601.00 FL
2	1		*N/S REAR BUMPER PARKING SENSOR	Shorted	226.00 FL	*226.00 FL
3	1		*REAR BUMPER PARKING SENSOR WIREHARNES	Serviceable	209.00 FL	*- FL
4	4		*REAR BUMPER PARKING SENSOR BRACKET	Serviceable	88.00 FL	*- FL
5	1		*REAR BUMPER LOWER COVER	Serviceable	103.00 FL	*- FL
6	1		*REAR BUMPER SPONGE	Serviceable	120.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	295.00 FL	*- FL
8	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Repair	104.00 FL	*- FL
9	1		*N/S REAR BUMPER INNER SHIELD	Serviceable	30.00 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
11	1		*N/S TAILLAMPS	Mtg Cracked	194.00 FL	*194.00 FL
12	1		*N/S REAR FENDER	Repair	881.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,881.00	1,051.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	288.10	105.10
Total Parts (\$\$)	2,592.90	945.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	750.00	400.00
2	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	80.00	60.00
3	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.	New	50.00	15.00
4	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	80.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	750.00	500.00
Gross Labour Cost (S\$)			1,750.00	1,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >