



Insured Vehicle No.: YN877IK
Name of Insured: Yew Sheng Furniture
Insured Tel No.: HP:
Excess Sec II : \$5 D.O.A: 19/03/2018

Claim No.: 58M00BBZ
Policy No.: P1A05781
Make / Model: M7. Carter
Place of Accident: BKE 7 CLE

Is driver the owner? (YES / NO) Nature of Accident:
If NO, Driver Name / Age: Soh Kim Seng 47/49 (V/L: YES / NO)
Driver Tel No.: 97291488

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No

FBH 8941R



INSRS: WSP: Sg 98
Tel: Liability:
RMKS:



INSRS: WSP:
Tel: Liability:
RMKS:



INSRS: WSP:
Tel: Liability:
RMKS:



INSRS: WSP:
Tel: Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
3/4	Non-Reporting ltr (1st):	
1/4	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	28/6/19
	After call ltr to OI:	CPL
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

Msg: Request for PIR.

2/4 Pending Est & PA

28/6/19 - Requested PIR
- Red evidency. liability unclear.
- Email LOI (50%)
7/11 - TP PIR in, 50/50 email send TP. ✓
12/12 - TO seek Mandate.
16/12 - Pending mandate approval.
16/12 - 2nd reminder email LOI (Pending OI WOA / DL)

10-01-20 LIABILITY IS SHARED EQUALLY OTHERWISE TO APPLY PIR FOR REVIEW.

25/2 - DV in, pending A&A instructions to close w/o LOA TP.
28/3 - the pass me to close.

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Naz

Repair Cost: 45 \$5 4000.00 (4 days) Reduction: \$3708.50 % 48 Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 20/2/2020 Confirm with: Linda Email ☒ Call ☐

Final Liability: % 50 (Agreed / Assessed) BOLA S/N No.: 20 If NO or B 28, Ass. Lia: Side swipe

Repair Cost: \$4000 \$5 2000.00

Loss of Rental (LOR): \$5 - (days)

Loss of Use (LOU): \$140 \$5 70.00 (535 x 4 days)

Loss of Income (LOI): \$5 - (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$5 -

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$5 2070.00 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email ☒ Call ☐

Payee 1: \$5 2070.00 Name 1: Sg 98 motor pte ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT 20/3/2020

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 1P
3) Survey fee: \$350.

REF: AXA

ASSIGNMENT

From: Date: 13/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBH 8941R

at Workshop m/s

SG 98 Motor

of

Bik 4001 # 01-21 AMK Ind. Pk 1

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Wps

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBH 8941R Yr Regn:

Type: M.Car (M.Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KAWASAKI 21000 SX (18) cc

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading:

45,821

Ti/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 120/70 R17

R: 190/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZLER

Front:

Rear:

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: mm

L/Bal: mm

D.O.A:

D.O.I: 28/3/18

Survey held at

SG 98 MOTOR

Des. of Damages: Frt / Rear (O/S) / N/S / UIC / Rooftop or

Front (right)

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

HS #4000 / 4 repair days. (Red = \$708.50 / 48.1)

Call/Time File Pass to?

☐ : Preli. Report

Days Of Repair:

Is

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Call/Time File Return to?

Transportation

Is

I S + RT S

Report Format :

Lump Sum / L.B.I: IS

Add Fee: ☐ : Site Insp. IS☐ : Interview IS☐ : Tech. Insp. IS☐ : Weekend IS

Photos

Other

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005464/Nua3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 23-03-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8771K	Veh. Inspected	FBH 8941R	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00BBZ	Excess (\$)	0.00	
Assign From		Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/03/2018	Inspection Date	28/03/2017	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/12/2019

Survey Details:

Date of loss	19-Mar-18
Date of appointment	22-Mar-18
Date of survey	28-Mar-18
Location of survey	SG 98 MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	FBH 8941R
Make and Model	KAWASAJI 21000 SX (ABS)
Date of registration	8/11/2013
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 7,708.50
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,606.00
Check items (estimate)	\$ -
Labour	\$ 400.00
Total	\$ 5,006.00
Lump Sum(if applicable)	\$ 4,000.00

Number of days for repair	4
---------------------------	---

Appr. Mr. Rasul.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 559622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 14 May 2018

To : LKK

Pig Date: 8/11/13 call 7/11/23

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

Chassis: JKA2XT006H A023250

LIS

FBH 8941R

VEHICLE NO : FBH 8941R

Kawasaki S1000 SX

1061A

ACCIDENT DATE: 19 March 2018

Description	Qty	Quotation \$
1 Brake Lever	1	80 150.00 / SCR
2 Front Mudguard	1	300 550.00 / CRK
3 Front Cowling	1	600 780.00 / SCR
4 Signal RH	1	100 160.00 / CRK
5 Front RH Side Fairing	1	280.00 / SCR
6 Frame Slider	1 set	180 240.00 / SCR
7 Handle Bar RH	1	160 360.00 / BT
8 Mirror	1	150 370.00 / BR
9 Clutch Lever	1	125.00 X SVC
10 Gasket Set	1	180.00 X NN
11 Exhaust Guard	1	200 350.00 / SCR
12 Exhaust Pipe	1	1,800 2,300.00 / SCR
13 Rear Tail Panel	1	250 380.00 / CRK
14 Balancer	1 set	140 240.00 / SCR
Sub-Total		6,465.00 4,240
Less 10%		646.50
Sub-Total		5,818.50 3,516

Joy

FINALIZED

- Naz

22/4/19

(1)

VEHICLE NO : FBH 8941R

Kawasaki S1000 SX

Nett items

- 1 Z1000 sticker
- 2 Rear RH side box bracket
- 3 Towing fee
- 4 Remove & replace necessary parts, & etc
- 5 Putty & respray paint & touch up paint work

100 250.00 /NIEC
650.00 /SR
40 60.00 ✓ 300
450.00 150
480.00 250 400

Sub-Total 1,890.00

Nett Total 7,708.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



SG 98 MOTOR PTE LTD

LG

PARTS \$4,240
LESS 10% \$3,816
SINETT \$ 790
LABOUR \$ 400

\$5,006

LESS LIS 20% \$4,004.80

LIS TOTAL \$4,000.00 / 4 REPAIR DAYS


LX Auto Care Ltd hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Attn: Mr. Rasul.

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 14 May 2018

To : LKK

Fig. Date: 8/11/13 re: 11/13

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

Chassis: JKAZK00611A023250

L13

FBH 8941R

VEHICLE NO : FBH 8941R

Kawasaki S1000 SX

1061 A

ACCIDENT DATE: 19 March 2018

Description	Qty	Quotation \$
1 Brake Lever	1	80 150.00 / SCR
2 Front Mudguard	1	300 550.00 / CRK
3 Front Cowling	1	600 780.00 / SCR
4 Signal RH	1	100 160.00 / CRK
5 Front RH Side Fairing	1	280.00 / SCR
6 Frame Slider	1 set	180 240.00 / SCR
7 Handle Bar RH	1	160 360.00 / BT
8 Mirror	1	150 370.00 / BR
9 Clutch Lever	1	125.00 X SVC
10 Gasket Set	1	180.00 X NV
11 Exhaust Guard	1	200 350.00 / SCR
12 Exhaust Pipe	1	1,800 2,300.00 / SCR
13 Rear Tail Panel	1	250 380.00 / CRK
14 Balancer	1 set	140 240.00 / SCR
Sub-Total		6,465.00 4,240
Less 10%		646.50
Sub-Total		5,818.50 3,816

(1)

VEHICLE NO : FBH 8941R

Kawasaki S1000 SX

Nett items

- 1 Z1000 sticker
- 2 Rear RH side box bracket
- 3 Towing fee
- 4 Remove & replace necessary parts, & etc
- 5 Putty & respray paint & touch up paint work

100 250.00 / NIEL
650.00 / SR
40 60.00 ✓ 700
450.00 150
480.00 250 400

Sub-Total 1,890.00

Nett Total 7,708.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



SG 98 MOTOR PTE LTD

LG

PARTS \$4,240
LESS 10% \$3,816
S/NETT \$ 790
LABOUR \$ 400

\$5,006

LESS LIS 20% \$4,004.80

LIS TOTAL \$4,000.00 / 4 REPAIR DAYS



Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBH8941R
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	KAWASAKI
Vehicle Model :	Z1000SX M
Chassis No. :	JKAZXT00GHA023250
Propellant :	Petrol
Engine No. :	ZRT00DE049952
Engine Capacity :	1043 cc
Maximum Power Output :	-
Maximum Laden Weight :	426 kg
Unladen Weight :	216 kg
Year Of Manufacture :	2013
Original Registration Date :	08 Nov 2013
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	\$1,710.00
COE Expiry Date :	07 Nov 2023
Road Tax Expiry Date :	07 Nov 2019
Inspection Due Date :	07 Nov 2019
Intended Transfer Date :	15 Apr 2019
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	

Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



Service Request Details

Claim

S8M00BBZ

Reference

None

Loss Date

March 19, 2018

Request Date

March 22, 2018

Due Date

March 29, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

22032018 @ 329pm
Rose veh in
S818 motor.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBH8941R

Make

TPVD KAWASAKI

Service Address

...

Primary Contact/Insured

YEW SHENG FURNITURE
61 WOODLANDS INDL PARK E9, #02-17 E9 PREMIUM, 757047, Singapore
63636552

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
New Message						



<MANDATE IA> - S8M00BBZ (ACCIDENT INVOLVING YN 8771K & FBH 8941R ON 19/03/2018)

Type

🔗 Question

Message

LIABILITY: 50% BOLA S20 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$2070.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply



RE: Re:<MANDATE IA> - S8M00BBZ {ACCIDENT INVOLVING YN 8771K & FBH 8941R ON 19/03/2018}

Type

🔗 Question

Message

HI STACEY, TILL DATE OI STILL YET TO EMAIL US THE LOA. CALL OI BUT KEEP INFORM US THAT WILL EMAIL BUT TILL DATE AFTER 3 REMINDER TO THEM IN EMAIL, STILL NO LOA RECEIVED. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION TO SETTLE AND CLOSE OFF THE MATTER W/O OI LOA. AS TP HAS ALREADY SUBMIT SIGNED DV TO US. THANKS - CCL 25/02/2020

Reply



RE: Re:<MANDATE IA> - S8M00BBZ {ACCIDENT INVOLVING YN 8771K & FBH 8941R ON 19/03/2018}

Type

🔗 Question

Message

[2ND REMINDER] HI STACEY, TILL DATE OI STILL YET TO EMAIL US THE LOA. CALL OI BUT KEEP INFORM US THAT WILL EMAIL BUT TILL DATE AFTER 3 REMINDER TO THEM IN EMAIL, STILL NO LOA RECEIVED. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION TO SETTLE AND CLOSE OFF THE MATTER W/O OI LOA. AS TP HAS ALREADY SUBMIT SIGNED DV TO US. KINDLY LET US HAVE YOUR INSTRUCTION OR APPROVAL IF WE CAN SUBMIT AND CLOSE CASE W/O OI LOA. THANKS - CCL
03/03/2020

Reply



Re:RE: Re:<MANDATE IA> - S8M00BBZ {ACCIDENT INVOLVING YN 8771K & FBH 8941R ON 19/03/2018}

Type

🔗 Question

Message

Hi LKK, Please proceed

Reply

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 22 April 2019

Invoice No: SG98-PD-19-030

AXA Insurance S'pore Pte Ltd
8 Shenton Way
#27-01 AXA Towers
SINGAPORE 068811

PD - Direct Settlement

Your Insured: YN 8771K

Date of Accident: 19-Mar-18

Location: Near KJE Exit towards BKE / SLE

FINAL REPAIR COSTS

VEHICLE NO. FBH 8941R (Kawasaki S1000SX)

Cost of Repair for Vehicle No.: FBH 8941R (lump sum) \$4,000.00

Total: \$4,000.00

SINGAPORE DOLLARS: FOUR THOUSAND ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

.LG



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408668
Tel +65 6547 0000
Fax +65 6147 4583
www.police.gov.sg

Our Ref : TP/IP/41121/2018
Date : 13.AUGUST 2018

AKMAL SHAFIQ BIN MAJID
BLK 354 WOODLANDS AVENUE 1
#02-771
SINGAPORE 730354

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING FBH 8941 R AND YN 8771 K ALONG BUKIT TIMAH
EXPRESSWAY ON 19/03/2018 AT ABOUT 5.30PM**

I refer to the above accident.

Please be informed that our investigation has not produced any substantive result. However, this does not preclude further prosecution should new evidence emerge later.

Yours faithfully,

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



Re:<MANDATE IA> - S8M00BBZ (ACCIDENT INVOLVING
YN 8771K & FBH 8941R ON 19/03/2018)

Type

🔍 Question

Message

pls proceed

Reply

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

DATE: 22 April 2019

Invoice No: SG98-PD-19-030

AXA Insurance S'pore Pte Ltd
8 Shenton Way
#27-01 AXA Towers
SINGAPORE 068811

LETTER OF DEMAND

Your Insured: YN 8771K
Date of Accident: 19-Mar-18

Location: Near KJE Exit towards BKE / SLE

FINAL REPAIR COSTS

VEHICLE NO. FBH 8941R (Kawasaki S1000SX)

Cost of Repair for Vehicle No.:	FBH 8941R (lump sum)	\$4,000.00
Loss of Use:	\$35 x 4 days	\$140.00
Total:		\$4,140.00

SINGAPORE DOLLARS: FOUR THOUSAND ONE HUNDRED FORTY ONLY

Notes:

1. All cheque payment should be "Crossed" and made payable to SG 98 MOTOR PTE LTD
2. All cheque should have our "Invoice No" written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



SG 98 Motor Pte Ltd

LG

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005464/Nga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 27-03-2020		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8771K	Veh. Inspected	FBH 8941B	
Policy No.	P1805781	Coverage (\$)	0.00	
Claim No.	S8M00BBZ	Excess (\$)	0.00	
Assign From		Assign Date	22/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	KAWASAKI Z1000SX	c.c	1043	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JKAZXT00GHA023250	Colour	GREEN	
Odometer	45821	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	METZELER	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/55 R17	METZELER	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2018	Inspection Date	28/03/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 8941R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BRAKE LEVER (CONSISTENT)	SCRATCHED✓	150.00✓	80.00✓
1	FRONT MUDGUARD (CONSISTENT)	CRACKED✓	550.00✓	300.00✓
1	FRONT COWLING (CONSISTENT)	SCRATCHED✓	780.00✓	600.00✓
1	SIGNAL RH (CONSISTENT)	CRACKED✓	160.00✓	100.00✓
1	FRONT RH SIDE FAIRING (CONSISTENT)	SCRATCHED✓	280.00✓	280.00✓
1	SET FRAME SLIDER (CONSISTENT)	SCRATCHED✓	240.00✓	180.00✓
1	HANDLE BAR RH (CONSISTENT)	BENT✓	360.00✓	160.00✓
1	MIRROR (CONSISTENT)	BROKEN✓	370.00✓	150.00✓
1	CLUTCH LEVER (CONSISTENT)	SERVICEABLE✓	125.00✓	-
1	SET GASKET (CONSISTENT)	NOT NECESSARY✓	180.00✓	-
1	EXHAUST GUARD (CONSISTENT)	SCRATCHED✓	350.00✓	200.00✓
1	EXHAUST PIPE (CONSISTENT)	SCRATCHED✓	2,300.00✓	1,800.00✓
1	REAR TAIL PANEL (CONSISTENT)	CRACKED✓	380.00✓	250.00✓
1	SET BALANCER (CONSISTENT)	SCRATCHED✓	240.00✓	140.00✓
	LESS 10% DISCOUNT		-846.50✓	-424.00✓
			5,818.50✓	3,816.00✓
<u>SPECIAL NETT ITEMS</u>				
1	Z1000 STICKER (SN) (CONSISTENT)	NECESSARY✓	250.00✓	100.00✓
1	REAR RH SIDE BOX BRACKET (SN) (CONSISTENT)	SCRATCHED✓	650.00✓	650.00✓
			900.00✓	750.00✓
<u>LABOUR</u>				
	TOWING FEE.		60.00✓	40.00✓
	REMOVE & REPLACE NECESSARY PARTS.& ETC.		450.00✓	150.00✓
	PUTTY & RESPRAY PAINT & TOUCH UP PAINT WORK.		480.00✓	250.00✓
			-	-
			-	-
			-	-
			990.00✓	440.00✓
GRAND TOTAL			7,708.50✓	5,006.00✓

Report Ref No. CC4/ASM18005464/Nga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CC4/ASM18005464/Nga3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim	SIM008BZ
Reference	CCA/ASM18005464/NgaQg2
Loss Date	19 March 2018
Report Date	21 Mar 2018 10:12:00 AM
Request Date	22 March 2018
Due Date	

Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve invoice

Approve Invoice

Vehicle Information	
Incident Vehicle Registration #	FBH8941R
Make	TRINO KAWASAKI
Model	Z1000SX M GREEN
Service Address	
...	

Primary Contact/Insured
YEW SHENG FURNITURE
61 WOODLANDS INDUSTRIAL PARK E9, #02-17 E9
PREMIUM, 757047, Singapore
63636552

Claim Handler
NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 MANDATE IA DO 16122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 LOO AND TAX INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 TP PIR.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 PAIRF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 December 2019
 P1805781_C1_000003_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	NG Stacy	4 June 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 POLICY SCHEDULE.pdf	Other	Other	LEE Josephine	4 April 2018
 Preliminary Advice.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 April 2018
 FBH8941R- TP GIA report.pdf	Reports & Statement	Accident statement	NG Sacey	23 March 2018
 YH6771K INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	22 March 2018
 EMAIL FROM WORKSHOP INCLUDING CO- CLAIMANT.mig	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	22 March 2018
 GIA YH6771K INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	21 March 2018