

22/03/2002

ASS. REC. BY:

REF: CS/SPF/18005469 / R/ rd301

Special Instruction:

Surveyor:

Rasyi

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

22/3/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 9744Z

Insured:

QX 5258M

at Workshop m/s:

Tandla Automotive

Tel:

9838 5899

of

Blok 25 Kaki Blok Rd # 07-56 synergy

Policy No:

Claim No:

AEMD/105/009/2018/029

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/03/18

CA / REV / REP. / REV 24 HRS

lwp?

26/3/18

H.O.D. Endorsement:

Date/Time:

10:45am 23/3/18

Person Contacted:

Cheryl

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Don't findline

SLG 9744Z - X

QX 5258M - X

Submit 45 \$2400 @ 7 days

Red. \$5737.78, 71%.



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLG9744Z

Our Ref : AEMD/105/009/2018/029

Date : 22 March 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax Only: 62564315

Dear Sir,

**RTA ON 17 MARCH 2018 INVOLVING GOVT VEHICLE QX5258M AND OTHER VEHICLE
SLG9744Z**

We refer to the above matter.

- 2 Please arrange for a Pre- Repair Inspection of vehicle no. SLG9744Z at M/s Tanala Automotive Consultancy of Blk 25 Kaki Bukit Road #07-56 Synergy @ KB, Singapore 417800.
- 3 For appointment kindly contact Cheryl at HP : 98385899.
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for ASST DIRECTOR

A FORCE FOR THE NATION

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SINGAPORE POLICE FORCE			Ref : CS/SPF18005469/R1rd3	
?? POLICE DIVISIONSINGAPORE 			Date : 23-03-2018	
			Code : SPF1	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 5258M		Veh. Inspected	SLG 9744Z
Policy No.			Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/029		Excess (\$)	0.00
Assign From	ABDUL RAHMAN		Assign Date	23/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/03/2018		Inspection Date	
Survey held at	BLK 25 KAKI BUKIT RD # 07-56			
Repairer	TANALA AUTOMOTIVE CONSULTANCY			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Tanala Automotive Consultancy

My Mail Box 883230

Singapore 919191

ROB: 53240124K

MELANIE ANN TONG

16 Flora Drive

#03-21

Singapore 506945

Estimate No : ES2018/0091

Date : 04/04/2018

Vehicle No : SLG9744Z

Make/Model : KIA / FORTE

Date of Accident : 17/03/2018

S/N	Description	Qty	Unit Amount	Amount
<u>List Items</u>				
1	FRONT DOOR, RH	1	1,589.25	1,589.25 <i>PA</i>
2	REAR DOOR, RH	1	1,679.25	1,679.25 <i>repair</i>
3	SIDE PANEL, RH	1	1,333.50	1,333.50 <i>repair</i>
4	REAR BUMPER	1	868.25	868.25 <i>repair</i>
5	BUMPER SIDE BRACKET	1	123.20	123.20 <i>X sub</i>
6	BUMPER CLIP	6	8.50	51.00 <i>PA</i>
				5,644.45
Less: 15%				(846.67)
				4,797.78

Nett Item

1	SPORT RIM	1	450.00	<i>300 450.00 sub</i>
2	TYRE	1	250.00	250.00 <i>X PA</i>
3	REAR W/S WEATHERSTRIP	1	60.00	60.00 <i>X PA</i>
				760.00

Labour

TO REMOVE AND REFIX REAR WINDSCREEN

TO PANEL BEAT/REPAIR RIGHT SIDE BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

TO SPRAY PAINTING ON AFFECTED AREAS

TO APPLY TUFF KOTE

Rasul
Hp 90010068
7 days
45
26/03/18 @ 1620
Recovery after repair

150.00	<i>X</i>
980.00	<i>500</i>
1,200.00	<i>800</i>
250.00	<i>80</i>
2,580.00	

Days of Repair: 8 days

Cheryl

Tanala Automotive Consultancy

LKK Auto Consultants hence liability
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL 8,137.78

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18005469/R1rd3e2		
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 20-08-2018		
ATTN : ABDUL RAHMAN		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 5258M	Veh. Inspected	SLG 9744Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2018/029	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	22/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	KNAFX411MH5668451	Colour	BLUE	
Odometer	8395	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	NEXEN	6 mm	
L/H Front Tyre	205/55 R16	NEXEN	6 mm	
R/H Rear Tyre	205/55 R16	NEXEN	6 mm	
L/H Rear Tyre	205/55 R16	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/03/2018	Inspection Date	26/03/2018	
Survey held at	BLK 25 KAKI BUKIT RD # 07-56			
Repairer	TANALA AUTOMOTIVE CONSULTANCY			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9744Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR, RH	BENT	1,589.25	1,589.25
1	REAR DOOR, RH	TO REPAIR SEE LABOUR	1,679.25	-
1	SIDE PANEL, RH	TO REPAIR SEE LABOUR	1,333.50	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	868.25	-
1	BUMPER SIDE BRACKET	SERVICEABLE	123.20	-
6	BUMPER CLIP @\$8.50	NECESSARY	51.00	51.00
	LESS 15% DISCOUNT		-846.67	-246.04
			4,797.78	1,394.21
SPECIAL NETT ITEMS				
1	SPORT RIM (SN)	SCRATCHED	450.00	300.00
1	TYRE (SN)	NOT NECESSARY	250.00	-
1	REAR W/S WEATHERSTRIP (SN)	NOT NECESSARY	60.00	-
			760.00	300.00
LABOUR				
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO PANEL BEAT / REPAIR RIGHT SIDE BODY. INCLUSIVE OF THE REPAIR OF REAR DOOR, RH, SIDE PANEL, RH AND REAR BUMPER. }		980.00	500.00
	TO DISMANTLE / REPLACE ABOVEMENTIONED PARTS. }		-	-
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	800.00
	TO APPLY TUFF KOTE.		250.00	80.00
			2,580.00	1,380.00
GRAND TOTAL			8,137.78	3,074.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/SPF18005469/R1rd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.