

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

AXA INSURANCE

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 21/3/2018@09:15
VRN : SKW153R
MODEL : TOYOTA VELLFIRE
TP VRN :
:

PARTS REPLACEMENT

1. Body Repair

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1 Front LH Door	1	\$ 1,800.00	\$ 1,800.00	
2 Front LH Door Lower Garnish	1	\$ 702.00	\$ 702.00	
3 Front LH Door Panel Garnish (sample)	1			
4 Front LH Door Chrome Moulding	1	\$ 104.00	\$ 104.00	
5 LH Side Mirror	1	\$ 677.00	\$ 677.00	
6 LH Side Mirror Cover	1	\$ 125.00	\$ 125.00	
7 LH Side Mirror Singnal Lens (sample)	1		\$ -	
8 LH Sliding Door	1	\$ 2,500.00	\$ 2,500.00	
9 LH Sliding Door Lower Garnish	1	\$ 765.00	\$ 765.00	
10 LH Sliding Door Chrome Garnish	1	\$ 215.00	\$ 215.00	
11 LH Sliding Door Moulding	1	\$ 189.00	\$ 189.00	
12 LH Sliding Door Outer Rubber Strip (sample)	1		\$ -	
13 LH Sliding Door Panel Garnish (sample)	1		\$ -	
14 LH Rear Fender (repair)	1		\$ -	
15 LH Rear Fender Lower Garnish	1	\$ 325.00	\$ 325.00	
16 Rear Bumper (repair)	1		\$ -	
17 Rear Bumper LH Side Retainer	2	\$ 135.00	\$ 270.00	
18 Front Door LH Sticker	2	\$ 68.00	\$ 136.00	
19 Parts Discount 25%	1	\$ 1,952.00	\$ 1,952.00	
TOTAL			\$ 5,856.00	

2. Labor Charges


1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	\$ 1,400.00
2 putty,blend and paint affected area	\$ 1,200.00
3 cavity treatment on new parts	\$ 160.00
4 Remove & reinstall fuel tank to facilitate cutting and repairing work	\$ 180.00
5 Transfer door lock & mechanism to new door .	\$ 200.00
6 Remove & reinstall rear trim compartment to facilitate cutting and repairing work	\$ 150.00

Sub Total : \$ 3,290.00

Grand Total : \$ 9,146.00
Add 7% GST : \$ 640.22
Nett Total : \$ 9,786.22

No. of repair days: 8

CUSTOMER SIGNATURE



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)