

Stacey | cc 4, Asm 18005473, Nua32

Max

ASSIGNMENT


DOI: 23/3/18

Date/Time: 22/03/2018

Registered in Merimen:

Pre-assign / CCU / FTE

Shw 9023X



Insured Vehicle No.:
Name of Insured: Amy Gillian Kennedy
Insured Tel No.: HP:
Excess Sec II :SS D.O.A: 15/3/2018
Is driver the owner? (YES NO) Nature of Accident:
If NO, Driver Name / Age: Leo Li King
Driver Tel No.: 9099189 (V/L: YES / NO)

Claim No.: Sgm 0060J
Policy No.: GA229809/1
Make / Model: Honda Stream (8CA)
Place of Accident: Chanh Airport 72

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No


8LL 82552



INSRS: world auto
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
3/4	Non-Reporting ltr (1st):	
1/4	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 2/4 Sent By: [Signature]

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 9/10/18 Confirm with: Geraldine Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NV

Repair Cost: S\$ 1047.53

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ 120.00 (\$ 60 x 2 days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$ 2.00

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$ 1169.53 Global Sum S\$: 1150.00

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 1150.00 Name 1: WORLD AUTO PTE LTD

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT 15/10/18

NAZ

REF: AXA

5473/Kua3

ASSIGNMENT

From: Date: 23/3/18

Veh No: SLL 8255Z Yr Regn: 10 Mar 2017

Estimated Cost:

Type: (M) Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SLL 8255Z

Make: HONDA VEZEL HYBRID C.C. 1496

at Workshop m/s World Auto

Colour: SILVER A/C: (Insured) Std / NI / NA

of No 1 Krunji loop

Sp. Reading: 082412 T/Radio: (Insured) Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: RU31213080

Claims No:

Gen. Cond: (Good) Fair / Poor / Burnt

Sum Insured: Excess

Steering: (Inorder) Jammed / Leaked / Burnt or


(Client's Record)

Brake: (Inorder) Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / (S) / (STD) A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 215 / 60 R16

R: 215 / 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front: R/Bal. 6 mm Rear: R/Bal. 6 mm

IDAC Accident Rpt: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

D.O.A. 15/03/18 D.O.I. 23/03/18

Lum Sum: PIP % 3 Val: Yes or No

Survey held at WORLD AUTO PTE LTD

CA / REV / REP. / 24 HRS (w/p)

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 979.00 (Red: \$ 1057.40 / 52%)

Date/Time: File Pass to?

: Preli. Report

Days Of Repair:

1) *

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Transportation

2)

Add Fee: : Site Insp \$

) \$ - RE - SI

Interview \$

) Photos

Tech Insp \$

) Other

Weekend \$

Report Format :

Lump Sum / I.B.I. \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R.

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005473/Nua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 23-03-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGW 9023X	Veh. Inspected	SLL 8255Z
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00B0J	Excess (\$)	0.00
Assign From		Assign Date	23/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/03/2018	Inspection Date	23/03/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 089542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000018

Date : 22/03/2018
 Vehicle Num. : SLL 8255Z(LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 15/03/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT GRILLE BASE <i>CRA</i>	400.00	200
2.	1	FRONT CHROME MOULDING <i>CRA</i>	400.00	270
3.	1	FRONT CHROME STRIP <i>CRA</i>	158.00	80
4.	1	FRONT 'H' LOGO <i>NEC</i>	150.00	30
List Total S\$:			1,108.00	680
20.00% Discount S\$:			221.80	136
			886.40	544
<i>Part Price to check</i>				
SPECIAL NETT ITEMS :				
1.	1	FRONT NUMBER PLATE WITH CASING <i>CRA 20%</i>	50.00	35
Special Nett Total S\$:			50.00	
LABOUR :				
LABOUR FOR REMOVING & REPLACEMENT FRONT ACCIDENT DAMAGED PARTS.			500.00	200
TO SPRAY PAINT FRONT BUMPER, FRT BONNET & ACCIDENT AFFECTED AREAS.			800.00	200
Labour Total S\$:			1,300.00	979
			1,100.00	979
E. & O.E.			Total S\$:	2,036.40

for WORLD AUTO PTE LTD

3/7/2018

Confirmed part by part repair \$979 / 2 days

Naz
2 Days
PIP
After Repair photo
Naze Naz

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000018

Date : 22/03/2018
 Vehicle Num. : SLL 8255Z(LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 15/03/2018
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	FRONT GRILLE BASE		
2.	1	FRONT CHROME MOULDING		
3.	1	FRONT CHROME STRIP		
4.	1	FRONT 'H' LOGO		

LIST ITEMS :
 FRONT GRILLE BASE / CRA
 FRONT CHROME MOULDING / CRA
 FRONT CHROME STRIP / CRA
 FRONT 'H' LOGO / REC

List Total S\$:
 20.00% Discount S\$:

LKK Auto Consultant hereby notify the Repairer of the following:
 • To resurvey before/after spray painting.
 • To display damaged parts during resurvey.
 • Parts prices are subject to confirmation.
 • Third party survey is on a "Without Prejudice" basis.
 • No illegal modification(s) is allowed.
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date:

Part Price to check

400.00
 400.00
 158.00
 150.00

 1,108.00
 221.60

 886.40

1.	1	FRONT NUMBER PLATE WITH CASING		
----	---	--------------------------------	--	--

SPECIAL NETT ITEMS :
 FRONT NUMBER PLATE WITH CASING / CRA

Special Nett Total S\$:

~~50.00~~ 35

 50.00

LABOUR :
 LABOUR FOR REMOVING & REPLACEMENT FRONT ACCIDENT DAMAGED PARTS.

~~500.00~~ 200

TO SPRAY PAINT FRONT BUMPER, FRT BONNET & ACCIDENT AFFECTED AREAS.

~~600.00~~ 200

Labour Total S\$: 1,100.00

Total S\$: 2,036.40

for WORLD AUTO PTE LTD

E. & O.E.
 Signature:
 Acknowledged by Repairer
 is subject to final approval from Insurance Company
 • Supplementary item(s) must be resurveyed and
 • No illegal modification(s) is allowed.
 • Third party survey is on a "Without Prejudice" basis.
 • Parts prices are subject to confirmation.
 • To display damaged parts during resurvey.
 • To resurvey before/after spray painting.
 the Repairer of the following:
 LKK Auto Consultant hereby notify

K. Naz
 2 Days
 PIP
 After Repair photo

◀ Service Request Details

Claim

S8M00B0J

Reference

None 

Loss Date

March 15, 2018

Request Date

March 22, 2018

World Auto

Due Date

March 29, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLL8255Z

Make

TPVD HONDA

Service Address

Primary Contact/Insured

ANG FULIAN KENNETH
19 TAMPINES AVE 8, #09-32, ARC AT TAMPINES, 529603, Singapore
91117532
angkenneth@gmail.com

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

-
- Messages
 - Invoices
 - History
 - Documents
 - Assessment
 - Metrics
 - Notes

New Message



SERVICE REQUESTS

MESSAGES

CLAIMS

⏪ RE: Request for Mandate approval S8M00B0J

Type

📍 Question

Message

Dear Sir / Madam, OI reversed into the parking lot and collided onto TP vehicle. Liability(TP) 100%
Proposed Nett Value \$ 1,047.53 w/gst Loss of use \$ 120.00 no. of 2 days x \$60 LTA search fees \$
2.00 Proposed Total \$ 1,169.53 Thanks, Best Regards, Thin Thin

Reply



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:RE: Request for Mandate approval S8M00B0J

Type

Question

Message

pls proceed

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SGW 9023X (Insd veh)	Model:	HONDA VEZEL HYBRID 1.5 AUTO
	SLL 8255Z (TP veh)		
Date of Accident:	15/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$		2,178.95
Final Repair Cost	: \$		1,047.53
Loss of Use	: \$		120.00
Rental (if any)	: \$		2 days at \$60.00 per day
LTA / GIA Search Fee	: \$		2.00

Others: : \$

: \$

Final Settlement Sum (GLOBAL SUM) : \$ 1,150.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	WORLD AUTO PTE LTD	: \$ 1,150.00

NUR SHAQILAH BTE ABDOL
WAHAB

01/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005473/Nua3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG		Date : 01-11-2018 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGW 9023X	Veh. Inspected	SLL 8255Z
Policy No.	GA229809/1	Coverage (\$)	0.00
Claim No.	S8M00B0J	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	22/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31213080	Colour	SILVER
Odometer	82412	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	MICHELIN	6 mm
L/H Front Tyre	215/60R16	MICHELIN	6 mm
R/H Rear Tyre	215/60R16	MICHELIN	6 mm
L/H Rear Tyre	215/60R16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/03/2018	Inspection Date	23/03/2018
Survey held at	NO.1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8255Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT GRILLE BASE (CONSISTENT)	CRACKED	400.00	300.00
1	FRONT CHROME MOULDING (CONSISTENT)	CRACKED	400.00	270.00
1	FRONT CHROME STRIP (CONSISTENT)	CRACKED	158.00	80.00
1	FRONT 'H' LOGO (CONSISTENT)	NECESSARY	150.00	30.00
	LESS 20% DISCOUNT		-221.60	-136.00
			886.40	544.00
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	CRACKED	50.00	35.00
			50.00	35.00
LABOUR				
	LABOUR FOR REMOVING & REPLACEMENT FRONT ACCIDENT DAMAGED PARTS.		500.00	200.00
	TO SPRAY PAINT FRONT BUMPER, FRT BONNET & ACCIDENT AFFECTED AREAS.		600.00	200.00
			1,100.00	400.00
GRAND TOTAL			2,036.40	979.00
RECOMMENDED COST OF REPAIRS				979.00

Report Ref No. CC4/ASM18005473/Nua3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.