



SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M00BMY
Reference	None
Loss Date	22 March 2018
Request Date	22 March 2018
Due Date	23 June 2018
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step

PAST DUE: Report that your work is blocked, and modify the Expected Completion Date.

Complete Work

More ▾

Vehicle Information

Incident

Vehicle

Registration #

SJY2240K

Make

FORD

Model

FIESTA 1.4

Service Address

Blk 3 Pioneer Road North, , , 628457

Primary Contact/Insured

GUO JIANHAO

05-723, 305B Punggol Road, 822305, Singapore

anthonyguojianhao@gmail.com

Claim Handler

ANG Yvonne

6568804461

Additional Instructions

EXCESS 0 PENDING EST & DL WORKSHOP : SNG AH TEE

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Letter of undertaking.pdf	Forms / Claim Documents	Letter of undertaking	LKK AUTO CONSULTANTS PTE LTD (OD)	14 August 2018
 PHOTO RESURVEY.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	8 August 2018
 PHOTO RESURVEY.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	8 August 2018
 NIRC DL.pdf	Forms / Claim Documents	Driver's License / IDP	LKK AUTO CONSULTANTS PTE LTD (OD)	27 March 2018
 PRELI ADVISED SJY 2240K - 1.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	27 March 2018
 ESTIMATE SJY 2240K.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	27 March 2018
 SJY 2240K PHOTO.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	26 March 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PRELI ADVISED SJY2240K.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	26 March 2018
 SJY2240K..PDF	Reports & Statement	GIA Report	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	22 March 2018



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2010 FORD FIESTA 1.4 (SJY2240K)
Date of Loss	22 March 2018
Time of Loss	8.00
Loss Description	REFER TO POLICE REPORT J/20180322/7014
Comment	

Workshop Details

Total Rebate Amount	14551
Nett Loss Amount	\$11,449.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	215



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SJY2240K	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	12/08/2010
Mileage	166266	Age of Vehicle	7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2010	2010
Make	FORD	FORD
Model	FIESTA 1.4	FIESTA TREND 1.4

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	GUO JIANHAO	
Date of Birth	27 August 1983	dd/mm/yyyy
Age	35	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		▼
Type of Paint		
Chassis No	WF0JXXGAJJAU82284	WF0JXXGAJJAU8:
Engine No	AU82284	AU82284
Engine Capacity		1388
Sum Insured	0	0
Market Value	0	26000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	▼
Driving Experience	11	
Driver License #		
License Type		▼
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	05-723, 305B Punggol Road, 822305, Singapore	
Address type	Residential	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S8326408Z	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/50R15

Rear Tyre Size

195/50R15

Front left side

TOYO6mm

Rear left side

TOYO6mm

Front right side

TOYO6mm

Rear right side

TOYO6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRT BUMPER			Deformed	500				500	Reviewing	
		2	1			FRT BUMPER SIDE RETAINER LH (NPA)			Serviceable	0	0	0	0	0	Deny	
		3	10			FRT BUMPER CLIP			Necessary	6.5				65	Reviewing	
		4	1			FRT HEADLAMP (LH)			Cut	320				320	Reviewing	
		5	1			FRT BONNET			Bent	450				450	Reviewing	
		6	1			FRT BONNET INSULATOR			Serviceable	0	0	0	0	0	Deny	
		7	10			FRT BONNET INSULATOR CLIP			Serviceable	0	0	0	0	0	Deny	
		8	2			FRT BONNET RUBBER SEAL			Serviceable	0	0	0	0	0	Deny	
		9	1			FRT WIPER GARNISH			Serviceable	0	0	0	0	0	Deny	
		10	1			FRT WINDSCREEN			Cut	950				950	Reviewing	
		11	1			SET FRT WINDSCREEN MOULDING (NPA)			Cut	0				0	Reviewing	
		12	1			FRT WIPER BLADE (LH)			Cut	50				50	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		13	1			FRT WINDSCREEN SIDE GARNISH (LH) (OUTER MOULDING)			Cut	120				120	Reviewing	
		14	1			FRT SHOCK ABSORBER (LH)			Serviceable	0	0	0	0	0	Deny	
		15	1			FRT KNUCKLE ARM (LH)			Serviceable	0	0	0	0	0	Deny	
		16	1			FRT LOWER ARM (LH)			Serviceable	0	0	0	0	0	Deny	
		17	1			FRT WHEEL HUB (LH)			Serviceable	0	0	0	0	0	Deny	
		18	1			FRT WHEEL BEARING (LH)			Serviceable	0	0	0	0	0	Deny	

Labour

Add		Approve		Deny		Submit All				
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO REPAIR & REPLACE UNDERCARRIAGE	0	0	0	Deny		
		2		TO CHECK WIRING	30	0	0	Reviewing		
		3		TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	500	0	0	Reviewing		
		4		TO PUTTY & RESPRAY PAINTING ON FRT BUMPER, FRT BONNET, FRT FENDER (LH)	500	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
☐		2	FRT TYRE (LH) (196/50R15)	Reviewing	200	PUNCTURED	
☐		3	FRT RIM (LH)	Reviewing	280	CUT	
☐		4	FRT WINDSCREEN SEALANT	Reviewing	40	NECESSARY	
☐		5	ERP BRACKET	Reviewing	26	NECESSARY	
☐		6	WHEEL ALIGNMENT	Reviewing	80	ADDITIONAL	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$4,111.00			Claim Amount	\$4,111.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$2,455.00	\$2,455.00
Labour	\$1,030.00	\$1,030.00
Miscellaneous	\$626.00	\$626.00

Submit for Review

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	3250		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$3,250.00

Claim Amount

\$3,250.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$3,250.00	\$3,250.00

Submit for Review