

SMRT Accident Vehicle Repair Estimates

Cc/11/18

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB741P
 Ref. No : TAX/03/18/2108
 Reg. Date : 10/10/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : JASON GOH HOCK BENG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 21/03/2018 09:05:00 AM
 Accident Reported Date / Time : 21/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095144
 Special Instruction to ARC, if any :
 SKV1989U
 Prepared Date : 21/03/2018 04:09:02 PM


21/03/2018 @ 1530h
Hit Antenna
? Part. 3 dgs.
Photo BT spray
ryen
LKK Auto
97237799


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU703572762

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,014.00

0.00

Total Spray Painting Charges : 1,296.00

0.00

Total Material Charges : 5,613.86

5,613.86

Other Charges : 840.00

0.00

TOTAL : 8,763.86**0.00****Lum Sum Total : 0.00****0.00**

No. of Repair Days : 6.00

0.00

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 21/03/2018 04:44:15 PM

01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/03/2018 04:41:11 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY ✓	1	423.90	25.00	317.92	Replace	Replace	No <i>distorted</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER ✓	10	1.50	25.00	11.25	Replace	Replace	No <i>NH</i>
5256547900			FILLER, RR BUMPER, RH ✗	1	119.90	25.00	89.92	Replace	Replace	No <i>SVC</i>
5246247030			PAD, RR BUMPER, RH & LH, 1 ✗	2	3.80	25.00	5.70	Replace	Replace	No <i>SVC</i>
5246247020			PAD, RR BUMPER, RH & LH, 2 ✗	2	3.80	25.00	5.70	Replace	Replace	No <i>SVC</i>
5246247010			PAD, RR BUMPER, RH & LH, 3 ✗	2	3.80	25.00	5.70	Replace	Replace	No <i>SVC</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH ✗	2	11.00	25.00	16.50	Replace	Replace	No <i>SVC</i>
5259147050			SEAL, RR BUMPER, RH ✗	1	85.20	25.00	63.90	Replace	Replace	No <i>SVC</i>
			SENSOR REVERSE ✗	1	180.00	0.00	180.00	Replace	Replace	No <i>SVC</i>
			PIXEL STICKER ✓	2	60.00	0.00	120.00	Replace	Replace	No <i>NH</i>
5202347030			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No ?
5245347010			GUARD, RR BUMPER, LOWER ✓	1	558.30	25.00	418.72	Replace	Replace	No <i>distorted</i>
5216947020			COVER, GUARD RR BUMPER LOWER ✓	1	14.80	25.00	11.10	Replace	Replace	No <i>distorted</i>
5246147010			PAD, RR BUMPER, CTR ✓	3	2.20	25.00	4.95	Replace	Replace	No <i>NH</i>
5839847050			COVER, REAR FLOOR UNDER, RH ✗	1	169.50	25.00	127.12	Replace	Replace	No <i>SVC</i>
6625947010			COVER, REAR FLOOR UNDER CENTER ✗	1	222.60	25.00	166.95	Replace	Replace	No <i>SVC</i>
1756522040			SUPPORT, EXHAUST PIPE NO.5 ✗	2	41.10	25.00	61.65	Replace	Replace	No <i>SVC</i>
1743037730			PIPE ASSY, EXHAUST, TAIL ✗	1	1,173.90	25.00	880.42	Replace	Replace	No <i>NH</i>
5257547040			RETAINER, RR BUMPER, RH ✗	1	112.70	25.00	84.52	Replace	Replace	No <i>SVC</i>
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR ✗	1	929.60	25.00	697.20	Replace	Replace	No <i>NH</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY ✗	1	891.20	25.00	668.40	Replace	Replace	No <i>NH</i>
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE ✗	2	27.90	25.00	41.85	Replace	Replace	No <i>NH</i>
3935047050			TAIL GATE LOCK ASSY, BACK DOOR ✗	1	452.10	10.00	406.89	Replace	Replace	No <i>SVC</i>
3932147010			TAIL GATE LOCK COVER, BACK DOOR ✗	1	25.30	25.00	18.97	Replace	Replace	No <i>SVC</i>
7557447010			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH ✗	1	29.90	25.00	22.42	Replace	Replace	No <i>NH</i>
755734710			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH ✗	1	29.90	25.00	22.42	Replace	Replace	No <i>NH</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
75571470 10			TAIL GATE MOULDING GLASS, BACK DOOR	X 1	29.70	25.00	22.27	Replace	Replace	No SVC
75575470 51			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	X 1	19.70	25.00	14.77	Replace	Replace	No SVC
62785470 10			TAIL GATE SPACER, QUARTER BACK DOOR GLASS	X 1	5.50	25.00	4.12	Replace	Replace	No SVC
69430520 50			TAIL GATE STRIKER ASSY, BACK DOOR	✓ 1	24.90	25.00	18.67	Replace	Replace	No HCC
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	✓ 1	52.30	25.00	39.22	Replace	Replace	No HCC
75442471 30			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	✓ 1	52.30	25.00	39.22	Replace	Replace	No HCC
75403480 10			EMBLEM SUB-ASSY REAR	✓ 1	46.30	25.00	34.72	Replace	Replace	No HCC
	COMMO N		SEALANT W/SCREEN	X 3	37.00	0.00	111.00	Replace	Replace	No HCC
	COMMO N		SMRT LOGO	✓ 1	7.80	0.00	7.80	Replace	Replace	No HCC
			STICKER DECAL 6555 8888	✓ 1	21.60	0.00	21.60	Replace	Replace	No HCC
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	? 1	629.80	25.00	472.35	Replace	Replace	No ?
	COMMO N	4006314	SEALANT SIKAFLEX	✓ 1	37.00	0.00	37.00	Replace	Replace	No HCC
65637470 60			LINER, REAR FENDER, RH	X 1	135.80	25.00	101.85	Replace	Replace	No HCC
TOTAL MATERIALS								5,613.94	5,613.86	
TOTAL MATERIALS(Discounted)								5,613.86	5,613.86	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 400/-
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200/-
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 NH
TO RESPRAY TAIL GATE	378.00	0.00 200/-
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100/-
TO RESPRAY REAR PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,296.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30/-
TO REMOVE & REFIT EXHAUST	120.00	0.00 NH X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 NH X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 NH X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40/-
TO REPLACE SUNDRY PARTS	100.00	0.00 X NH
TO WASH AND VACUUM	60.00	0.00 X NH
Total Other Costs	840.00	0.00