



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN. : MOTOR CLAIMS FAX :		NAME : STUTTGART AUTO PTE LTD ADDRESS : NO:12 SUNGEI KADUT AVE SINGAPORE 729648 TEL : 63633003	WIP : 14770 EXCESS : DATE: 23-Mar-18
VEH NO :	SLC8512D	DATE IN :	CONTACT PERSON : JOBI THOMAS 6395 7875
CHASSIS NO :	JM6BM42A8G0335207	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG.: 27-May-16	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	FRONT BUMPER	1	MBHN1-50-031BBB	det	\$ ✓ 925.10
2	FRONT BUMPER RETAINER RH	1	MBHN1-50-0T1F	dis	\$ ✓ 18.70
3	FRONT BUMPER RETAINER LH	1	MBHN1-50-0U1E	dis	\$ ✓ 18.70
4	FRONT BUMPER BRACKET RH	1	MBHN1-50-152		\$ 7 15.10
5	FRONT BUMPER BRACKET LH	1	MBHN1-50-162		\$ 7 15.10
6	FRONT BUMPER GROMMET,SCREW	2	MGHP9-50-0Z5	rel	\$ X 5.40
7	FRONT BUMPER LOWER COVER RH	1	MBHN1-50-101	gnc	\$ X 28.00
8	FRONT BUMPER LOWER COVER LH	1	MBHN1-50-102	wig	\$ 28.00
9	FRONT BUMPER TOWING COVER	1	MBHN1-50-A11 BB		\$ 7 28.60
10	FRONT BUMPER FASTENER	2	MB45A-56-146A		\$ X 5.60
11	FOG LAMP COVER LH	1	MBHN1-50-C21A	gnc	\$ X 43.20
12	RADIATOR GRILLE CHROME MOULD RH	1	MBHN1-50-7J1A		\$ X 176.70
13	RADIATOR GRILLE CHROME MOULD LH	1	MBHN1-50-7K1A		\$ 176.70
14	RADIATOR GRILLE LOGO	1	MC235-51-731A		\$ X 44.20
15	RADIATOR GRILLE RIVET	6	MS51S-51-833		\$ X 22.80
16	RADIATOR GRILLE	1	MBHN1-50-712B		\$ X 119.60
17	RADIATOR GRILLE BRACKET RH	1	MBHN1-50-153		\$ X 15.10
18	RADIATOR GRILLE BRACKET LH	1	MBHN1-50-163		\$ X 15.10
19	RADIATOR GRILLE CLIP	2	MEA01-50-037		\$ X 15.20
20	RADIATOR GRILLE PIN LOCATOR	2	MKD45-50-1K5A		\$ X 5.40
21	RADIATOR GRILLE GROMMET	2	MKD45-50-ES1		\$ X 5.40
22	RADIATOR GRILLE BRACKET TOP	1	MBHN1-50-717D		\$ X 102.40
23	RADIATOR GRILLE FASTENER	8	MGD7A-50-EA1		\$ X 24.00
24	RADIATOR GRILLE CLIP	1	M9YA5-90-602A		\$ X 2.50
25	RADIATOR GRILLE RIVET	4	MTK21-50-355		\$ X 34.80
26	RADIATOR GRILLE TOP	1	MBHN1-50-033 50		\$ X 335.00
TOTAL PARTS					\$ 2,226.40
LESS 10%					\$ 222.64
TOTAL PARTS COST					\$ 2,003.76
Labour Description					
1	TO REPLACE FRONT BUMPER AND RADIATOR GRILLE ASSY. TO REPAIR ALL				\$ 1,650.00

	AREAS AFFECTED BY THE ACCIDENT.		
2	TO RESPRAY FRONT BUMPER AND RADIATOR GRILLE TOP.	640\$	1,500.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ X 250.00
4	TO SUPPLY 1 PC NUMBER PLATE.	NETT	\$ - 70.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 100 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 350.00
7	SUNDRIES.	NETT 50	\$ 100.00

TOTAL LABOUR	\$ -	\$ 4,170.00
TOTAL PARTS	\$ -	\$ 2,003.76
TOTAL	\$ -	\$ 6,173.76
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Not Authorized
PIP Review
Before paint work
27/3/2018
3 weeks
LKK Auto Max

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: