

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/4

2018

SSX 2475E - X ; SKK 4882 G - X

Please proceed w/

Email liability to C/2018.

26/04/18

Inquiry PIP 4013.68 with 3 days

3.5.18 @ 3.25

CALLED ON CONFIRMED ACCIDENT. OI REAR ENDED TP. INFORM TP. CLAIM ADDED TO SETtle AND AMARE ABOUT NCD ISSUES.

→ LOD → payable to Volkswagen Group (G) P/L

* other final check - Volkswagen Centre SG.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 21.5.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: REPAIR INVOICE.

PRELIMINARY ADVICE

Date/Time:

27/3/18

Sent By:

J

FINALIZATION

Date/Time:

26.4.18

Confirm with:

J

Confirm by:

JBT

Repair Cost:

PP \$4,013.69

(3 days)

Reduction:

58 %

Email

Call

FINAL SETTLEMENT

Date/Time:

29.8.18

Confirm with: SHH SHH

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

w/65

\$4,294.65

OI REAR ENDED TP.

Loss of Rental (LOR):

w/65

\$321.00

(3 days)

x \$100

Loss of Use (LOU):

\$

-

(\$

x

days)

Loss of Income (LOI):

\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$2.00

Medical:

\$

-

Disbursement: (RE-COST)

\$50.00

(e.g. Tow/ Independent)

Legal Cost

\$

-

Total:

\$4,661.65

Global Sum \$:

FINAL PAYMENT

Date/Time:

29.8.18

Confirm with: SHH SHH

Email

Call

Payee 1:

\$4,661.65

Name 1:

VOLKSWAGEN CENTRE SINGAPORE

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

REF: ASM (AXA)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 717 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 8JX 2475 E Yr Regn: 2016 JuneType: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf c.c. 1395Colour: white A/C: Insured / Std / NI / NASp. Reading: 20314 T/Radio: Insured / Std / NI / NAEng/No: C2D512274C/No: WVW22ZAUZGW273392Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 225/35 R19R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 22/03/2018 D.O.I. 26/03/2018Survey held at Volkswagen kg Impact

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

MV 751CCTA 591C26/04/18 Inspector 717 4013.60 with 3 days 7 hr(RED: + 5,585.89 58%)

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

By:

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

By:

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Workshop: \$

Report Format:

Lump Sum / I.B.I: \$

Survey Fee

Transportation

1. S + P + M

2. Photo

3. Chart

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005505/Dka3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 24-03-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 4882G	Veh. Inspected	SJX 2475E	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00BQL	Excess (\$)	0.00	
Assign From		Assign Date	24/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/03/2018	Inspection Date	26/03/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PDI TUAS

PDI TUAS

LEE SOK HOON
(LI SHUFEN)
122 JALAN KELICHAP
Singapore, 534323
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV010971
Quote No. SER/QUO/1800498
QuoteDate 23/03/18
Salesperson MARCUS LIU
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 R-Line 110 (DSG)	13,015	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJX2475E	WVWZZZAUZGW273392	30/06/16	MARCUS LIU
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZD 512274	5G14NZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR	4	UNIT	1260/-	3,360.00
P B&P MACP PAINT	SPRAY PAINT	4	UNIT	800/-	3,200.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un	2400/-	280.00
	Sum Labor				7,400.00
P 1K8943021D	LIC PL LIG HN	2	Pieces		158.03 HN
P 5G0807305B	REINFORCEMENT HN Successor 5G0807305D	1	Pieces		629.03 HN
P 5G0853675B JZQ	NAME PLATE (TSI) HN	1	Pieces		53.68 HN
P 5G0853687 2ZZ	NAME PLATE (GOLF) HN	1	Pieces		60.66 HN
P 5G0919491	SENSOR BRACKET HN	2	Pieces		25.48 HN
P 5G0919491A	SENSOR BRACKET HN	1	Pieces		12.74 HN
P 5G0919492A	SENSOR BRACKET HN	1	Pieces		12.74 HN
P 5G6807393	BUMPER SIDE BRACKET LH HN	1	Pieces		31.59 HN
P 5G6807393A	TAILLIGHT LOWER BRACKET LH HN	1	Pieces		31.59 HN
P 5G6807394	BUMPER SIDE BRACKET RH HN	1	Pieces		31.59 HN
P 5G6807394A	TAILLIGHT LOWER BRACKET RH HN	1	Pieces		31.59 HN
P 5G6807417ASGRU	REAR BUMPER HN	1	Pieces		629.76 HN
P 5G6807568M 041	SPOILER HN	1	Pieces		270.04 HN
P 5G6807863A	BUMPER CENTRE BRACKET HN Use Predecessor 5G6807863	1	Pieces		58.12 HN
P D 180KU2A1	2KADHESIVE HN	1	Pieces		89.84 HN
	Sum carried forward				9,526.48

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

LEE SOK HOON
(LI SHUFEN)
122 JALAN KELICHAP
Singapore, 534323
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV010971
Quote No. SER/QUO/1800498
QuoteDate 23/03/18
Salesperson MARCUS LIU
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 R-Line 110 (DSG)	13,015	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SJX2475E	WVWZZZAUZGW273392	30/06/16	MARCUS LIU
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZD 512274	5G14NZ

	Continued	9,526.48
P D 822150A1	1 Pieces	- 64.27
P WHT005263	6 Pieces	- 8.81
Sum Item		2,199.57

Sum Labor	7,400.00
Sum Item	2,199.57

Total SGD	9,599.57
7% GST	671.96
Total SGD Incl. GST	10,271.53

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.:

26/03/2018 @ 1600h

Not Authored

? 1 Part 3 days



LKK Auto


 Photo B4 spray

4013.68

SERVICE ORDER NO: 18IP0975

CUSTOMER NO.: CV010971

CUSTOMER NAME: LEE SOK HOON

TELEPHONE NO.:

ADDRESS: 122 JALAN KELICHAP
Singapore

Order Date: 12/04/18

Reg Date: 30/06/16

KM: 21,390

VIN NO.: WVVZZZAUZGW273392

ENGINE NO:

SA: Tang Shu Shi

MODEL: GOLF A7 1.4 R-Line 110 (DSG)

MODEL NO.: 5G14NZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH CHECK WIRE HARNESS, ECU, SENSOR, SOCKET	1	TU	280		280 ✓
2	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480 ✓
3	B&P MACP LABOUR LABOUR	1.5	UNIT	840		1,260 ✓
4	B&P MACP PAINT SPRAY PAINT	1	UNIT	800		800 ✓
5	B&P NUMBER PLATE B&P NUMBER PLATE -NETT	1	ST	80		80 ✓
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
8	5G6807417ASGRU REAR BUMPER	1	PCS	629.76		629.76 ✓
9	5G6807568M 041 SPOILER	1	PCS	270.04		270.04 ✓
10	WHT005263 POP-RIVET	6	PCS	1.47		8.81 ✓
11	5G0919492A SENSOR BRACKET	1	PCS	12.74		12.74 ✓
12	5G0919491 SENSOR BRACKET	2	PCS	12.74		25.48 ✓
13	5G0919491A SENSOR BRACKET	1	PCS	12.74		12.74 ✓
14	D 180KU2A1 2KADHESIVE	1	PCS	89.84		89.84 ✓
15	D B22150A1 BONDAGENT	1	PCS	64.27		64.27 ✓

Remarks : AXA DIRECT SETTLEMENT

DOA: 22/03/2018

TP VEHICLE: SKX4882G

SURVEY BY: BRYAN (LKK)

SERVICE ORDER NO: 18IP0975

CUSTOMER NO.: CV010971

CUSTOMER NAME: LEE SOK HOON

TELEPHONE NO.:

ADDRESS: 122 JALAN KELICHAP

Singapore

Order Date: 12/04/18

Reg Date: 30/06/16

KM: 21,390

VIN NO.: WVVZZZAUZGW273392

ENGINE NO:

SA: Tang Shu Shi

MODEL: GOLF A7 1.4 R-Line 110 (DSG)

MODEL NO.: 5G14NZ

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	4,013.68
-------	----------

GST AMOUNT	280.96
------------	--------

TOTAL AMOUNT	4,294.64
--------------	----------

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00BQL
Our ref: CC4/ASM18005505/Dka3

Date: 27.03.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJX 2475E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.03.2018 at the premises of M/s Volkswagen Centre Singapore and have the following to report:-

Workshop Estimate Amount	: S\$	9,599.57
Revised Estimate Amount	: S\$	4,013.68
"Check" Items Amount	: S\$	939.95
Total (Including Check Items)	: S\$	4,953.63
Market Value	: S\$	75,000.00
LTA Reimbursement Value	: S\$	59,892.00
Nett Value	: S\$	15,108.00

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

Service Request Details

Claim

S8M00BQL

Reference

None 

Loss Date

March 22, 2018

Request Date

March 23, 2018

Due Date

April 2, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

23/03/2018 @ 226pm
Shu Shi veh not in

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SJX2475E

Make

TPVD VOLKSWAGEN

Service Address

...

Primary Contact/Insured

TANG GEHONG
BLK 130 EDGEDALE PLAINS, #13-16, 820130, Singapore

t_gh@hotmail.com_

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

C/Thush



MANDATE REQUEST FOR S8M00BQL

Type

Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,294.65 (w/GST) Loss of Rental: \$321.00 (3days x \$100) (w/GST) Disbursement: \$50.00 GIA Search: \$2.00 Total: \$4,667.65 Revised Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (20/07/2018)

[Reply](#)



Re:RE: MANDATE REQUEST FOR S8M00BQL

Type

🔔 Question

Message

MANDATE APPROVED

Reply

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
GST No. M20098505-2

DISCHARGE VOUCHER

I / We Lee Sok Hoon (Passport No. S 7512272A) the
owner of vehicle number SJX 247SE hereby accept from
AXA (Insurance Company) the sum of
_____ (total repair cost) in full and final settlement for the cost of repairs
arising from the loss damage of property as a result of the accident involving
SJX 247SE & SX 48824 along Braddell Road
on 22/3/18.

Please pay to Volkswagen Group Singapore Pte Ltd who is authorized to receive
only on the total cost of repair on my/our behalf.

The lost of use (transport allowance / rental receipts) to be payable to
VOLKSWAGEN GROUP SINGAPORE PTE LTD.

Dated this on 26/4/18 (DD/MM/YYYY)


(Signature of owner / Company stamp)

Name : Lee Sok Hoon

NRIC No. : S7512272A

Date : 26/4/18

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK 4882G (Insd veh)	Model:	VOLKSWAGEN
	SJX 2475E (TP veh)		GOLF 1.4 TSI R-LINE AT SR
Date of Accident:	22/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,271.54
Final Repair Cost	:	\$	4,294.65
Loss of Use	:	\$	days at \$00.00 per day
Rental (if any)	:	\$	321.00 3 days
LTA / GIA Search Fee	:	\$	2.00

Re-Coat	:	\$	50.00
---------	---	----	-------

	:	\$	
Final Settlement Sum	:	\$	4,667.65

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____100____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	VOLKSWAGEN CENTRE SINGAPORE	:	\$ 4,667.65

NUR SHAQILAH BTE ABDOL
WAHAB

17/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim

S8M00BQL

Reference

CC4/ASM18005505/Dea3s2

Loss Date

March 22, 2018

Request Date

March 23, 2018

Due Date

March 23, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

Move

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SJX2475E

Make

TPVD VOLKSWAGEN

Model

GOLF A7 1.4 R-LINE

Service Address

TANG GEHONG
BLK 130 EDGE DALE PLAINS, #13-16, 820130, Singapore

Primary Contact/Insured

TANG GEHONG
BLK 130 EDGE DALE PLAINS, #13-16, 820130, Singapore

Primary Contact Email

t_gh@hotmail.com_

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

DATE UPLOADED

TYPE

SUB-TYPE

AUTHOR

<< Service Request Details

Claim

SBM00BQL

Reference

CC4/ASM18005505/Dea3s2

Loss Date

March 22, 2018

Request Date

March 23, 2018

Due Date

March 23, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SJX2475E

Service Address

Make

TPVD VOLKSWAGEN

Model

GOLF A7 1.4 R-LINE

Primary Contact/Insured

TANG GEHONG

BLK 130 EDGEDALE PLAINS, #13-16, 820130, Singapore

t_gh@hotmail.com_

Claim Handler

LOH Cynthia

6568904843

cynthia.loh@axa.com.sg

Additional Instructions

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

STATUS

SHARE

CLONE

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Vehicle & Driver Details

Vehicle Registration#	SJX2475E	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	06/30/2016
Mileage	20314	Age of Vehicle	1

POLICY INFORMATION		ASSESSMENT INFORMATION	
CATEGORY		CATEGORY	FNOL INFORMATION
Manufacturing Year	2016	Driver Name	SOK HOON LEE
Make	TPVD VOLKSWAGEN	Date of Birth	April 24, 1975
Model	GOLF A7 1.4 R - LINE	Age	43
Type		Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	WVWZZZAUZGW273392	Driving Experience	0
Engine No	CZDS12274	Driver License #	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

03/26/2018



General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Young/Inexperienced/Unarmed Driver Excess

0

Engine Modification

Yes No

Other Excess

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

225/35R19

Rear Tyre Size

225/35R19

Front left side

BRIDGESTONE 6mm

Rear left side

BRIDGESTONE 6mm

Front right side

BRIDGESTONE 6mm

Rear right side

BRIDGESTONE 6mm

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Add		Approve	Deny	Submit All		
EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		3	
	2	LIC PL LIG	Reviewing	0	NOT NECESSARY	
	3	REINFORCEMENT	Reviewing	0	NOT NECESSARY	
	4	NAME PLATE (TSI)	Reviewing	0	NOT NECESSARY	
	5	NAME PLATE (GOLF)	Reviewing	0	NOT NECESSARY	
	6	SENSOR BRACKET	Reviewing	25.48	NECESSARY	
	7	SENSOR BRACKET	Reviewing	12.74	NECESSARY	
	8	SENSOR BRACKET	Reviewing	12.74	NECESSARY	
	9	BUMPER SIDE BRACKET LH	Reviewing	0	NOT NECESSARY	
	10	TAILLIGHT LOWER BRACKET LH	Reviewing	0	NOT NECESSARY	
	11	BUMPER SIDE BRACKET RH	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$4,013.69

Claim Amount \$4,013.69

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,820.00	\$2,820.00
Miscellaneous	\$1,193.69	\$1,193.69

Submit for Review