

ASS. REC. BY:

REF:

CS/MSGL18005510 / Agbn2

Special Instruction:

Surveyor

ASSIGNMENT (Office)

McMen

From (Person):

Katherine Wong

of

MSCH

Date/Time:

23032018 11:04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 852J

Insured:

SGC 3283G

at Workshop m/s

Modern Automotae

Tel:

6747 4422

of

Blk 3023A Ubi Rd 1 #01-61

Policy No:

287974366QMX

Claim No:

553187

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

23032018 12pm

Person Contacted:

Cmell

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 852J - X
	SGC 3283 G - NA / INCUB017065/s
21/3/18 @ 11:40am	Informed Katherine Wong, we pending estimate from Repairs
30/4/18 @ 5:24pm	Revised to Katherine Wong via McMen.
	US \$5500 (Red \$10071.92, 65%.)
	30/4

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

23/09/09.

2009, Sept.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJT852J Yr Regn: 2009, Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 176411 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm68L1021A011552Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 23/03/18Survey held at ModernDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP MS/G.MV : 23KPV : 14.5KNett : 8.5K

RECEIVED 02 MAY 2018

Date/Time, File Pass to?

1) 01/10/09

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: 300S + RS: 10 SI

Photos

Others

TOTAL

310Report Format: MR-TPLump Sum / B.I. (\$) 5500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005510/Aqb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGC 3283G	Veh. Inspected	SJT 852J	
Policy No.	287974366QMX	Coverage (\$)	0.00	
Claim No.	553187	Excess (\$)	0.00	
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	23/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/03/2018	Inspection Date	23/03/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 30 Apr 2018

Preliminary Advice

Insured Vehicle No : SGC3283G
TP Vehicle No : SJT852J
Make : MAZDA 3
Date of Inspection : 23/03/2018
Inspection At : MODERN AUTOMOTIVE PTE LTD

Accident Date : 22/03/2018
Assignment Date : 23/03/2018
Est. Duration of Repair : 7

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,571.92
Revised Amount	:S\$	6,875.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,875.20
Lump Sum Repair	:S\$	5,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ () The vehicle is economical/not economical for repair.
- ☒ (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2018		23 Mar 2018 11:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Liaw Siew Ngoh, ID: S17125198		
Main Claimant:	Ong See Tong, ID: S8721529F		
Vehicle Reg. No.:	SJT852J	Date of Loss:	22/03/2018 09:00 - :59
Claim Type:	TP / 553187	Policy/Cover Note No.:	287974366QMX Coverage: 01/12/2017 - 30/11/2018
Vehicle Reg. No. (Insured):	SGC3283G	Policy No. (Claimant):	
		Excess:	
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/03/2018]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Monday, 26 March 2018 11:40 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJT 852J (YOUR REF: 553187)

This mail is associated with :

***SJT852J (553187)**

[SGC3283G]

TP

Ong See Tong

Mar 22 2018 9:00AM

[Liaw Siew Ngoh]

Modern Automotive Pte Ltd

Dear Katherine,

Please be informed that we have inspected the vehicle SJT 852J on 23/03/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



1 Owner Since New, A Very Practical Sedan With It's Sleek Look! Boot Space Is Huge, No Issues For Loading Bulky Item! Loan Available, Trade In Welcome, Excellent Original Condition, Smooth Drive, Sell...

Posted: 17-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A

\$23,800

\$8,700 /yr

14-Aug-2009

1,999 cc

165,000 km

Sedan

Available

Almost New Tyres! Low Monthly Installment! Extremely Value For Money, High Specs And Powerful! Extended Warranty Available! Purchase From A Company Accredited With Outstanding Awards And Professional ...

Dickson Automobile

Posted: 11-Feb-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A

\$22,800

\$7,920 /yr

18-Aug-2009

1,999 cc

-

Sedan

Available

Most Popular Mazda 3 Sedan For Your Family, Well Maintained And Service. No Further Repairs Needed. Beautiful Paintwork With Clean And Neat Interior, Bank Or In-House Loan Available. Purchased With As...

Henly Enterprises Co

Posted: 17-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Mazda 3 1.6A Luxury

\$23,800

\$9,090 /yr

31-Aug-2009

1,598 cc

136,800 km

Sedan

Available

100% In House Loan Or Bank Loan Available. Exciting And Sporty Outlook, Sports Rims Lowest Depreciation! Car Is In Good Working Condition. Wait No More And Call Us

Tai Huat Automobile

Posted: 19-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury

\$23,800

\$8,800 /yr

17-Sep-2009

1,598 cc

-

Sedan

Available

Graded B by **STA**

Extended Warranty Provided! Buy With A Peace Of Mind From A Company Accredited With Outstanding Awards, Professional After Sales Service Assured, No Hassle When We Can Proceed With Immediate Transfer ...

Dickson Automobile

Posted: 11-Feb-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury

\$22,900

\$8,080 /yr

28-Sep-2009

1,598 cc

138,779 km

Sedan

Available

All Our Quality Preowned Cars Are Selling At The Most Reasonable Price And With A Peace Of Mind! STA/VICOM Evaluate Are Welcome. Easy Approval! Down Payment \$2,900 Loan \$20K Our Flexible Bank/In House...

Posted: 23-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A Luxury

\$26,800

\$10,820 /yr

13-Oct-2009

1,598 cc

118,804 km

Sedan

Available

Beautiful Appearance, Passionate Red. Well Maintained By Owner. Only \$2,680 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Pack...

Classic Credit Pte Ltd

Posted: 09-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A

\$25,800

\$8,940 /yr

21-Oct-2009

1,999 cc

-

Sedan

Available

10% Downpayment. \$1,172/mth. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.

Posted: 22-Jan-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A

\$25,800

\$9,470 /yr

17-Nov-2009

1,598 cc

91,500 km

Sedan

Available

1 Owner, Low Mileage! Regularly Serviced And Maintained By Mazda Agent. Pristine Condition. 100% Accident Free. Call Now For Viewing.

Posted: 23-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 1.6A

\$26,800

\$9,870 /yr

30-Nov-2009

1,598 cc

-

Sedan

Available

1 Owner Only! Extended Warranty Available! Low Mileage! High Trade-In! Well Maintained Stylish Sedan, For You To View And Let The Car Speak For Itself! Buy It From Us With A Peace Of Mind, A Company A...

Dickson Automobile

Posted: 14-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 2.0A

\$25,800

\$8,020 /yr

21-Dec-2009

1,999 cc

156,000 km

Sedan

Available

Low Down Cash Up Front And Flexible Loan Schemes Available! Immaculately Maintained! View To Believe Condition! Buy From Trustworthy Dealer And We Will Workout A Win Win Package For Your Dream Car. Ca...

Car Times Automobile Pte Ltd

Posted: 10-Mar-2018 Tags: 2009 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1529F
Vehicle Details	
Vehicle No.:	SJT852J
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN LUX
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	Z6803762
Chassis No.:	JM6BL10Z1A0111552
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$21,455.00
Original Registration Date:	23 Sep 2009
First Registration Date:	23 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$21,455.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2019
PARF Rebate Amount:	\$11,800.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,020.00
COE Rebate Amount:	\$2,701.00
Total Rebate Amount:	\$14,501.00

The information contained herein is correct as at 23 Mar 2018

OK

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

MSIG INSURANCE (S) PTE LTD

4 Shenton Way # 21 - 01

SGX Centre 2

Singapore 068807

Hot line : 6827 - 7660

Fax : 6225- 7402 (CLAIM)

Quotation

DATE : 23.03.2018

VEH NO : SJT852J

MODEL : Mazda 3

D O A : 22.03.2018

YR REF : SGC3283G

Attn : Motor Claim Dept

(pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJT852J (Mazda 3)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>deformed</i>	1	1,043.00 ✓
2	Front Bumper Clips <i>nr</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>nr</i>	2	56.80 ✓
4	Front Bumper Grille <i>lt</i>	1	216.30 ✓
5	Front Bumper Reinforcement <i>Best</i>	1	382.70 ✓
6	Front Bumper Sponge <i>Deformed</i>	1	89.30 ✓
7	Front Bumper Logo <i>nr</i>	1	34.30 ✓
8	Front Bumper Undercover <i>nr nr</i>	1	202.40 ✗
9	Front Bumper Grille Inner Garnish - Upper <i>Deformed</i>	2	84.20 ✓
10	Front Bumper Grille Inner Garnish - Lower	2	79.00 ✓
11	Headlamp - LH & RH <i>Not nr</i>	2	4,584.00 ✗
12	Rear Number Plate Lamp - LH & RH <i>cracked</i>	2	288.80 ✓
13	Rear Bumper <i>Distorted</i>	1	947.30 ✓
14	Rear Bumper Clips <i>nr</i>	1	30.00 ✓
15	Rear Bumper Side Holder - LH & RH <i>nr</i>	2	68.60 ✓
16	Rear Bumper Reflector - LH & RH <i>cracked</i>	2	189.20 ✓
17	Rear Bumper Reinforcement <i>Best</i>	1	491.70 ✓
18	Rear End Panel <i>Repair</i>	1	365.40 ✗
19	Rear End Panel Top Garnish <i>deformed</i>	1	225.00 ✓
20	Taillamp - LH & RH <i>Not nr</i>	2	2,076.80 ✗
21	Bootlid <i>Buckled</i>	1	1,026.70 ✓
22	Bootlid Lock <i>changed</i>	1	156.40 ✓
23	Bootlid Lock Sensor <i>changed</i>	1	125.50 ✓
24	Bootlid Weatherstripe <i>lt</i>	1	130.60 ✓
25	Mazda Logo <i>?</i>	1	29.20 ✓
26	Mazda Wording <i>nr</i>	1	36.70 ✓
27	3 Wording	1	20.20 ✓
28	Spare Tyre Panel Top Cover <i>nr</i>	1	380.50 ✗
29	Rear Exhaust Pipe <i>nr</i>	1	953.80 ✗

RE : ESTIMATE FOR ACCIDENT REPAIR SJT852J (Mazda 3)

30	Rear Exhaust Mounting	<i>Not New</i>	<i>5781.5</i>	<i>45.50</i>	<i>X</i>
			<i>4625.20</i>		
				\$	14,389.90
					(2,877.98)
				\$	11,511.92

S/NET ITEMS

1	Front Number Plate	<i>Best</i>	1	30.00	<i>✓</i>
2	Front Number Plate Holder	<i>Delid</i>	1	30.00	<i>✓</i>
3	Rear Number Plate	<i>Missing</i>	1	30.00	<i>✓</i>
4	Rear Number Plate Holder	<i>320</i>	1	30.00	<i>✓</i>
5	Reverse Sensor	<i>Don't</i>	1	280.00	<i>200</i>
6	Rear End Panel Sealant	<i>Here</i>	1	60.00	<i>X</i>
				\$	460.00

Total parts

\$ 11,971.92

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$	1,400.00	<i>900</i>
2	To putty and spray up paint works	\$	1,400.00	<i>800</i>
3	To check wiring system	\$	100.00	<i>60</i>
4	To underseal	\$	150.00	<i>X</i>
5	To remove upholstery	\$	150.00	<i>40</i>
6	To remove reverse sensor	\$	100.00	<i>50</i>
7	To remove exhaust pipe	\$	150.00	<i>X</i>
8	To transfer bootlid fittings	\$	150.00	<i>80</i>
		\$	3,600.00	

GRAND TOTAL

\$ 15,571.92

GST Will be reflected in the final bills

NOTE:
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair completion
 - To display damaged part(s) during resurvey
 - Parts price is subject to confirmation
 - Third party involvement is not allowed
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.**

Acknowledged by Repairer

Signature:

Date:

total 6875.20
2/s 5.5K
07 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005510/AQBN2

Date: 03/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28794366QMX
Claimant Vehicle No :	SJT852J	Insured Vehicle No :	SGC3283G
Date of Loss:	22/03/2018	Nature of Claim:	TP
		Claim No:	553187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT852J	Engine No:	Z6803762
Make & Model:	MAZDA 3, 1.6 L (A)	Chassis No:	JM6BL10Z1A0111552
Reg. Date:	23/09/2009 (Man. Year: 2009)	Odometer:	176411 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,971.92	4,945.20	7,026.72	58.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,930.00	1,670.00	46.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,571.92	6,875.20	8,696.72	55.85
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	15,571.92	5,500.00	10,071.92	64.68
+ GST 7.00/7.00% (S\$)	1,090.03	385.00	705.03	64.68
Nett Amount (S\$)	16,661.95	5,885.00	10,776.95	64.68

INSPECTION

Date of Assignment: 23/03/2018

Date Inspected: 23/03/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2018)
Parts: 143	MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJT852J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,043.00 FL	*1,043.00 FL
2	1	*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2	*FRONT BUMPER SIDE HOLDER-LH & RH	Necessary	56.80 FL	*56.80 FL
4	1	*FRONT BUMPER GRILLE	Cut	216.30 FL	*216.30 FL
5	1	*FRONT BUMPER REINFORCEMENT	Bent	382.70 FL	*382.70 FL
6	1	*FRONT BUMPER SPONGE	Deformed	89.30 FL	*89.30 FL
7	1	*FRONT BUMPER LOGO	Necessary	34.30 FL	*34.30 FL
8	1	*FRONT BUMPER UNDERCOVER	Not Necessary	202.40 FL	*- FL
9	2	*FRONT BUMPER GRILLE INNER GARNISH-UPPER	Deformed	84.20 FL	*84.20 FL
10	2	*FRONT BUMPER GRILLE INNER GARNISH-LOWER	Deformed	79.00 FL	*79.00 FL
11	2	*HEADLAMP-LH & RH	Not Necessary	4,584.00 FL	*- FL
12	2	*REAR NUMBER PLATE LAMP-LH & RH	Cracked	288.80 FL	*288.80 FL
13	1	*REAR BUMPER	Distorted	947.30 FL	*947.30 FL
14	1	*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
15	2	*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	68.60 FL	*68.60 FL
16	2	*REAR BUMPER REFLECTOR-LH & RH	Cracked	189.20 FL	*189.20 FL
17	1	*REAR BUMPER REINFORCEMENT	Bent	491.70 FL	*491.70 FL
18	1	*REAR END PANEL	Repair	365.40 FL	*- FL
19	1	*REAR END PANEL TOP GARNISH	Deformed	225.00 FL	*225.00 FL
20	2	*TAILLAMP-LH & RH	Not Necessary	2,076.80 FL	*- FL
21	1	*BOOTLID	Buckled	1,026.70 FL	*1,026.70 FL
22	1	*BOOTLID LOCK	Damaged	156.40 FL	*156.40 FL
23	1	*BOOTLID LOCK SENSOR	Damaged	125.50 FL	*125.50 FL
24	1	*BOOTLID WEATHERSTRIPE	Cut	130.60 FL	*130.60 FL
25	1	*MAZDA LOGO	Necessary	29.20 FL	*29.20 FL
26	1	*MAZDA WORDING	Necessary	36.70 FL	*36.70 FL
27	1	*3 WORDING	Necessary	20.20 FL	*20.20 FL
28	1	*SPARE TYRE PANEL TOP COVER	Not Necessary	380.50 FL	*- FL
29	1	*REAR EXHAUST PIPE	Not Necessary	953.80 FL	*- FL
30	1	*REAR EXHAUST MOUNTING	Not Necessary	45.50 FL	*- FL
31	1	*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
32	1	*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
33	1	*REAR NUMBER PLATE	Missing	30.00 FS	*30.00 FS
34	1	*REAR NUMBER PLATE HOLDER	Missing	30.00 FS	*30.00 FS
35	1	*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
36	1	*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,849.90	6,101.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,877.98	1,156.30
Total Parts (\$\$)	11,971.92	4,945.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	1,400.00	900.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	1,400.00	800.00
3	TO CHECK WIRING SYSTEM	New	100.00	60.00
4	TO UNDERSEAL	New	150.00	-
5	TO REMOVE UPHOLSTERY	New	150.00	40.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE EXHAUST PIPE	New	150.00	-
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			3,600.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >