

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref: NS/INC18005511/Svb		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date:	24-03-2018 INC4		
		Policy Particulars	,10000.0000000	and the second	
	Insured Veh.	GV 4199K		nspected	SHB 5115P
	Policy No.	5081541278-01	Cover	age (\$)	0.00
	Claim No.		Exces	s (\$)	0.00
	Assign From		Assig	n Date	16/03/2018
2.		Vehicle Parti	culars &	Condition	n of the table
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year o	of Reg.	
	Chassis No.		Colou	r	
	Odometer	<u> </u>	Steeri	ng	
	Brakes		Modif	cation	
	General				
3.		Condit	ions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.		Descripti	on of D	amages	
5.	Name and the	Genera	ıl Inform	ation	
	Accident Date	15/03/2018	Inspe	ction Date	16/03/2018
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	7705
5a.		R	emarks	JAN EINE HIE	
		ON WAS CONDUCTED ON A"WI			

TP Claims against NTUC Income: Follow-Through Survey

C/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.0.A	Estimate	Tentative repair cost
-	MT/0985649-002	SMRT TAXIS PTE LTD	SHB 5685K	SHD 2900Z	9/3/2018	\$16,906.80	\$6,560.24
1 0	NOT OIL	SMRT BUSES LTD	SMB 345R	SJZ 4060U	3/3/2018	\$6,580.60	\$2,400.00
7 6	MT/0986413-002	SMRT TAXIS PTE LTD	SHB 5115P	GV 4199K	15/3/2018	\$5,679.73	\$2,200.00
0 <	MT/0986530-002	SMRT TAXIS PTE LTD	SHC 4705M	SJK 565K	18/3/2018	\$3,114.88	\$700.00
+ 1	AAT/0005554.002	SMRT TAXIS PTF I TD	SHC 4075Y	SHD 2745E	9/3/2018	\$9,551.10	\$2,150.00
0 4	MT/008/003-002	SMRT TAXIS PTF LTD	SHB 1968X	SKA 9766D	6/3/2018	\$7,649.50	\$1,925.94
0 1	MT/0988280-002	SMRT TAXIS PTE LTD	SHB 1169K	SJR 3086U	12/3/2018	\$7,887.10	\$2,350.00

Claim received from LKK Auto

eBaoTech						Gene	ralClaim			
Hello, NAC_PAYA_UBI_80	0601						Change La	nguage	· Change Passwor	d · Log Out
My Desktop	Poli	cy Query								79
Notice of Loss	Policy N	No.				Date of Aco	cident	15/03	/2018 17:41	
	Vehicle	No.(For Motor)	GV4199K							
					1	Search				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	6	5081541278-01	THE ICE CREAM FACTORY PTE. LTD.	201541107C	GCV	Third Party	GV4199K	GV4199K	27/06/2017	26/06/2018
					10	Continue				

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
ehicle Details	Security Company
ehicle No.:	SHB5115P
ehicle to be Exported:	No
ntended De-registration Date:	19 Mar 2018
ehicle Make:	CHEVROLET
ehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
rimary Colour:	Maroon
lanufacturing Year:	2012
ngine No.:	Z20S1461330K
nassis No.:	KL1LA69RJBB128393
aximum Power Output:	110.0 kW (147 bhp)
pen Market Value:	\$14,281.00
riginal Registration Date:	05 Apr 2012
st Registration Date:	05 Apr 2012
ansfer Count:	0
tual ARF Paid:	\$14,281.00
tended PARF Rebate Details	
RF Eligibility:	Yes
ARF Eligibility Expiry Date:	04 Apr 2020
ARF Rebate Amount:	\$9,996.00
tended COE Rebate Details	
DE Expiry Date:	04 Apr 2020
OE Category:	A - Car (1600cc & below)
OE Period(Years):	8
QP Paid:	\$42,384.00
OE Rebate Amount:	\$10,825.00
otal Rebate Amount:	\$20,821.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Mar 2018

Message

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

新聞於雙身的第二人	ACCIDENT STATEMENT	
Date Of Report	15/03/2018 16:25	THE RESERVE TO BE STORY OF THE RESERVE TO SHARE THE RESERVE THE RE
Date Of Accident	15/03/2018 14:15	
Exact Location Of Accident	TIONG BAHRU ROAD	
Country/State of Loss	SINGAPORE	

《维约斯 图》,在"维约亚"的"特别"。	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB5115P	
Insured/Policyholder		
Name Of Registered Owner	SMRT TAXIS PTE LTD	
Co Reg No	198905369K	
Email Address	NOEMAIL	
Mobile Phone No		
Alternative Phone No	OFFICE-80000000	
Vehicle Particulars		
Manufacturer	COLUMN TO THE CO	

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT

Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	

rollcy Number	D-17087562MFSH
Cover Note Number	

Driver	
Name of Driver	LIM CHOON HIONG
NRIC No	S7402057G
Date Of Birth	02/02/1974
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE

Fax Number	
Contact Number	
EMail Address	NOEMAIL

Mobile Number

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

5

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG TIONG BAHRU ROAD AT THE RIGHT MOST LANE WHEN THE VEHICLE GV4199K FROM MY LEFT ABRUPTLY CUT INTO MY LANE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO LARGE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GV4199K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category Name of Driver

COMMERCIAL VEHICLE HUANG ZHONG MING

NRIC/Passport Number

S8936995I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

LIM CHOON HIONG

SHB5115P

YES

NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

dh 15/3/201

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN		butram RD			
	MANGZ HOTEL)) A-SHESIIS B-GV4199			
€	TIONS RAHRU RO				
DESCRIBE CIRCUMSTAN					
**					
1840	rticulars are true in every respect.	du 15/3/2018			
licyholder's Signature te & Time:	Driver's Signature (If driver is not the policyholder) Date & Time;	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:			



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB5115P

Ref. No.

TAX/03/18/2075

Reg. Date

05/04/2012

Vehicle Type

TAXI

Make

CHEVROLET EPICA 2.0 VCDI

Model

EPICA-2.0

Name of Driver

LIM CHOON HIONG

Type of Accident

SIDE SWIPE

Date / Time of Accident

15/03/2018 02:14:00 PM

Accident Reported Date / Time :

15/03/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024095062

Special Instruction to ARC, if any :

GV4199K

Prepared Date

15/03/2018 04:44:34 PM

@sanu

- Long Sun Repair. - Question Mark Iran - Photo After Point

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: KL1LA69RJBB128393

Mileage

: (

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

0.00

Total Spray Painting Charges
Total Material Charges

936.00

O .

2,945.06

2,945.06

Other Charges

700.00

:

0.00

TOTAL

5,426.06

0.00

Lum Sum Total

5,450.00

0.00

No. of Repair Days

F 00

0.00

Prepared / Adjusted By

5.00

4 4272

Arc / Surveyor Sing Off Date

: 15/03/2018 07:45:25 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

tomanto

Prepared Date : 15/03/2018 07:45:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR LH FRONT PORTION	845.00	0.00 600		
Total Labour	845.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY FRONT FENDER LH	378.00	0.00 200		
TO RESPRAY RIM	180.00	0.00 ×		
TO REPSRAY FRONT BUMPER	378.00	0.00 300		
Total Spray Painting & Panel Beating	936.00	0.00		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00-30
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 ×
TO REMOVE AND REFIT TYRE	120.00	0.00 ×
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 😾
TO REPLACE SUNDRY PARTS	100.00	0.00 >0
TO WASH AND VACUUM	60.00	0.00 🔀
Total Other Costs	700.00	0.00

Part 4 - Spare Parts / Material Usage


Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
96636324	FRONT	6504580	PANEL FRT FENDER LH	1	606.00	10.00	545.40	Replace	Replace	No
96633939	FRONT	6504582	LINER FENDER FRT LH (PROTECTOR)	1	49.00	10.00	44.10	Replace	Replace De	No Fairm
	COMMO N	6503708	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
	COMMO N	6504666	TYRE RIM	1	328.99	0.00	328.99	Replace	Replace ×	No
93744489	FRONT	6504592	BUMPER FRT ASSY	- 1	1,238.00	10.00	1,114.20	Replace	Replace J	No
96633983			BRACKET FRT BUMPER SIDE LH	1	9.00	10.00	8.10	Replace	Replace 1	No
96644857	FRONT	6504613	LAMP HEAD LH	1	841.00	10.00	756.90	Replace	Replace	No
TOTAL MATERIALS								2,924.43	2,924.43	
		TOTAL	MATERIALS(Discour	nted)				2,945.06	2,945.06	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS (%)					Sin Took				

Page:





22-3-18/08:06

60 Woodlands Industrial Park E4, Singapore 757705


FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

19-3-18/08:01





Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: KL1LA69RJBB128393

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

600.00

Total Spray Painting Charges

936.00

400.00

Total Material Charges

1,579.97

1,703.70

Other Charges

700.00

-503.70

TOTAL

2,200.00

4.060.97

Lum Sum Total No. of Repair Days 0.00

0.00

5.00

4.00

Prepared / Adjusted By

5679.73

SEBASTIAN (LKK)

Arc / Surveyor Sing Off Date

15/03/2018 07:45:25 PM

16/03/2018 02:27:07 PM

Prepared / Adjusted Date

Remarks

Prepared Date :

15/03/2018 07:45:25 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

: QN-1803-0552

Invoice No

Quotation Date : 23 3

Invoice Date :

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	600.00
Total Labour	845.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY RIM	180.00	0.00
TO REPSRAY FRONT BUMPER	378.00	200.00
Total Spray Painting & Panel Beating	936.00	400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO REMOVE AND REFIT TYRE	120.00	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-553.70
Total Other Costs	700.00	-503.70

TAX/03/18/2075 Page: 3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
96636324	FRONT	6504580	PANEL FRT FENDER LH	1	606.00	10.00	545.40	Replace	Replace	No /
96633939	FRONT	6504582	LINER FENDER FRT LH (PROTECTOR)	1	49.00	10.00	44.10	Replace	Replace	No /
	COMMO N	6503708	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X
	COMMO N	6504666	TYRE RIM	0	328.99	0.00	0.00	Replace	Not given	Nολ
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace	No.
96633983			BRACKET FRT BUMPER SIDE LH	1	9.00	10.00	8.10	Replace	Check	No X
96644857	FRONT	6504613	LAMP HEAD LH	1	841.00	10.00	756.90	Replace	Check	No X
areces Accessory			TOTAL MATERIALS		*			2,468.70	1,703.70	
	TOTAL MATERIALS(Discounted) 5679.73							1,579.97	1,703.70	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOT	AL SUPPLEMENTARY	MATERIA	LS					

1703.70/ + 600.00/ + 450.00/ + 2753.70/ \$2/5/18 -202.96/

Veron Chen (LKKAuto)

From:

Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) < YeoPohsuan@smrt.com.sg>

Sent:

Tuesday, 27 March 2018 4:06 PM

To:

Sebastian Yeang (LKK Auto)

Cc: Subject: SUR; CS A Team RE: SHB5115P

Hi

Amount confirmed as per your recommendation, thanks.

Regards Poh Suan

----Original Message----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]

Sent: Tuesday, 27 March 2018 10:35 AM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Cc: SUR; CS A Team Subject: RE: SHB5115P

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 email: sebastianyeang@lkkauto.com| fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi

Avenue 1, #02-25 | S(408933)

----Original Message----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Monday, 26 March 2018 4:21 PM

To: Sebastian Yeang (LKK Auto)

Cc: SUR; CS A Team Subject: SHB5115P

Hi Sebastian,

Attached herewith the repair estimate of SHB 5115P having Case No: TAX/03/18/2075.

There is no change to the approved amount of \$2,200 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards Poh Suan

----Original Message----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 26 March 2018 3:44 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref: NS/INC180055	NS/INC18005511/Svbe2	
73 BRAS BASAH ROA #05-01 NTUC TRADE 189556	D UNION HOUSESINGAPORE	Date: 10-04-2018 Code: INC4		
	Policy Particulars	:- THIRD PARTY CLAIM	1	
Insured Veh.	GV 4199K	Veh. Inspected	SHB 5115P	
Policy No.	5081541278-01	Coverage (\$)	0.00	
Claim No.	MT/0986413-002	Excess (\$)	0.00	
Assign From		Assign Date	16/03/2018	
2.	Vehicle Parti	culars & Condition		
Make & Model	CHEVROLET EPICA 2.0	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1LA69RJBB128393	Colour	MAROON	
Odometer	834588	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3.	Condit	ions of Tyres		
	Size	Make	Balance	
R/H Front Tyre	205/55 R15	FALKEN	6 mm	
L/H Front Tyre	205/55 R15	FALKEN	6 mm	
R/H Rear Tyre	205/55 R15	FALKEN		
L/H Rear Tyre	205/55 R15	FALKEN	6 mm	
4.	Descript	ion of Damages		
THE VEHICLE SU	JSTAINED DAMAGES AT THE FF	RONT N/S PORTION.		
DAMAGES SEE I	DETAILS.			
5.		al Information		
Accident Date	15/03/2018	Inspection Date	16/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICE	ES PTE LTD		
	60 WOODLANDS INDUSTRIAL	PARK E4 SINGAPORE 75	57705	
5a.		Remarks		
A)THE INSPECT	ON WAS CONDUCTED ON A'WI	THOUT PREJUDICE" BAS WE HAVE NOT AUTHORIS	IS. ED REPAIRS.	
5b.		Days of Repair		
	RMAL PERIOD FOR REPAIR:	4 Working Day	S	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5115P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			(4)
1 1 1	PANEL FRT FENDER LH (DISC 10%) INER FENDER FRT LH (PROTECTOR) (DISC 10%) SUMPER FRT ASSY (DISC 10%) YRE YRE RIM FRACKET FRT BUMPER SIDE LH	DENTED DEFORMED TORN NOT NECESSARY NOT NECESSARY NOT NECESSARY	606.00 49.00 1,238.00 126.74 328.99	545.40 44.10 1,114.20
	LAMP HEAD LH	NOT NECESSARY	9.00 841.00 3,198.73	1,703.70
	LABOUR THATCHAM STANDARD REPAIR TIME ON BODY WORKS. THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,285.00 1,036.00	600.00 430.00
	TO REPLACE SUNDRY PARTS. TO WASH AND VACUUM.	NOT NECESSARY	100.00 60.00 2,481.00	1,050.00
	GRAND TOTAL		5,679.73	2,753.70

2,200.00	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)
	(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)

Report Ref No. NS/INC18005511/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.