

REF: NS/TNC18005512/Srber

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJK 565K

Policy No. 5097656244 31012018

Claims No.

MT/0986530-002

Sum Insured:


Excess:

(Client's Record)

Make of Vch:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SNC 4905M

Yr Regn: 10/12/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

cc 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

353853

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN 3646057 3749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fuller

Front

Rear

R/Bal.

6 mm

R/Bal.

6

m

L/Bal.

6 mm

L/Bal.

6

m

D.O.A.

18/3/18

D.O.I.

20/3/18

Survey held at

SPART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time | Action / Instruction

SNC 4905M - NS/TNC17003053 / High 3 m2

DUA: 110217 TAX/03/18/2072

SJK 565K - X

LKK

NINC

26/3/18 Sebastian Confirmed LS \$700 (Red 2414.88, 7812)

SJK 565K

RECEIVED 3 APR 2018

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2) 4/4 - typist

Report Format:

Lump Sum / L.B.I. (\$

TP

700k

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS - SI

Phone

Others

TOTAL

Add Foo:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005512/Svb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 24-03-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 565K	Veh. Inspected	SHC 4705M	
Policy No.	5097656244	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/03/2018	Inspection Date	20/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/0985649-002	SMRT TAXIS PTE LTD	SHB 5685K	SHD 2900Z	9/3/2018	\$16,906.80	\$6,560.24
2	NOT OI	SMRT BUSES LTD	SMB 345R	SJZ 4060U	3/3/2018	\$6,580.60	\$2,400.00
3	MT/0986413-002	SMRT TAXIS PTE LTD	SHB 5115P	GV 4199K	15/3/2018	\$5,679.73	\$2,200.00
4	MT/0986530-002	SMRT TAXIS PTE LTD	SHC 4705M	SJK 565K	18/3/2018	\$3,114.88	\$700.00
5	MT/0985664-002	SMRT TAXIS PTE LTD	SHC 4075Y	SHD 2745E	9/3/2018	\$9,551.10	\$2,150.00
6	MT/0984993-002	SMRT TAXIS PTE LTD	SHB 1968X	SKA 9766D	6/3/2018	\$7,649.50	\$1,925.94
7	MT/0988280-002	SMRT TAXIS PTE LTD	SHB 1169K	SJR 3086U	12/3/2018	\$7,887.10	\$2,350.00

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5097656244	EASYDRIVE CAR RENTAL	53375868L	GFT	Third Party	SJK565K	SJK565K	31/01/2018	

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHC4705M
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS TAXI (SMRT)
Chassis No. :	JTDKN36U605753749
Propellant :	Petrol-Electric
Engine No. :	2ZR6230133
Motor No. :	3JM6230133
Engine Capacity :	1798 cc
Power Rating :	60.0 kW
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	1805 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2014
Original Registration Date :	10 Dec 2014
Lifespan Expiry Date :	09 Dec 2022
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$51,668.00
COE Expiry Date :	09 Dec 2022
Road Tax Expiry Date :	09 Jun 2018
PARF Eligibility Expiry Date :	09 Dec 2022
Inspection Due Date :	09 Jun 2018
Intended Transfer Date :	21 Mar 2018
CO2 Emission :	92.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$30,000.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 09 Jun 2018. You may renew the road tax from 10 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 09 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 10 Jun 2018 to 09 Dec 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			535.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 09:56
Date Of Accident	18/03/2018 14:05
Exact Location Of Accident	LOWER DELTA ROAD TOWARDS TELOK BLANGAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4705M
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	TAN ENG LEE
NRIC No	S0179534A
Date Of Birth	15/04/1954
Occupation	OUTDOOR
Date Of Driving Pass	01/09/1990
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	812
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180318/2092 On the 18/03/2018 at about 1355 hrs I was driving my vehicle bearing plate number, SHC4705M along Lower Delta Road towards Telok Blangah Road and was travelling on the 2nd lane. As I am approaching the traffic light junction, it turns red so I decided to slow down my vehicle until I came to a complete stop. There was another vehicle in front of me. At that juncture, I saw from my rear view mirror a vehicle approaching bearing plate number, SJK565K, from behind me. From what I could hear he dropped to 2nd gear and did managed to stop in time. Not long after there was a strong collision involving me and the vehicle behind me. I did not hit the vehicle in front of me. I then exited my vehicle and saw that there was a third vehicle bearing plate number, SKS4854X, who collided with the vehicle behind me and thus collided onto me. I then exchange particulars with the person involving with the accident. There was no police or ambulance that attended to the accident. After the accident I drove to SMRT workshop under my company and parked my vehicle there. I was still feeling pain and sore from the accident so I decided to go to Khoo Teck Puat Hospital. I received 7 days mc from the hospital. I planned on claiming this accident through my company's insurance.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK565K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	YUGANESVARAN S/O NALATHAMBY
NRIC/Passport Number	S8732024C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKS4854X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO SIEW HIANG LAWRENCE
NRIC/Passport Number	S7120002G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN ENG LEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC4705M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

19/3/2018

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 7/20180318/2092

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

du 19/3/2018



**SINGAPORE
POLICE FORCE**



T/20180318/2092

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

1 of 4

Report No. T/20180318/2092

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2018 21:16		Vide Report No.:		Station Diary No.: 82	
Informant's Particulars					
Name of Informant: TAN ENG LEE			Address: APT BLK 812 YISHUN RING ROAD #03-4159 SINGAPORE 760812		
ID Type / ID No.: NRIC NO / S0179534A			Contact No.: Home/Office: Mobile: 92344508		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 15/04/1954	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/03/2018 14:05	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 LOWER DELTA ROAD TELOK BLANGAH ROAD At the traffic light				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 70 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Chain Collision				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC4705M	Car				Slightly Damaged	0
SJK565K	Car				Slightly Damaged	1
SKS4854X	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180318/2092

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

2 of 4

Report No. T/20180318/2092

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN ENG LEE	ID No.	S0179534A
Related Vehicle	SHC4705M (Car)	Contact No.	92344508
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Driver			
Name	Yuganesvaran S/O Nalathamby	ID No.	S8732024C
Related Vehicle	SJK565K (Car)	Contact No.	92705045
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Yeo Siew Hiang Lawrence	ID No.	S7120002G
Related Vehicle	SKS4854X (Car)	Contact No.	92390854
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 18/03/2018 at about 1355 hrs I was driving my vehicle bearing plate number, SHC4705M, along Lower Delta Road towards Telok Blangah Road and was travelling on the 2nd lane. As I am approaching the traffic light junction, it turns red so I decided to slow down my vehicle until I came to a complete stop. There was another vehicle in front of me. At that juncture, I saw from my rear view mirror a vehicle approaching bearing plate number, SJK565K, from behind me. From what I could hear he dropped to 2nd gear and did managed to stop in time. Not long after there was a strong collision involving me and the vehicle behind me. I did not hit the vehicle in front of me. I then exited my vehicle and saw that there was a third vehicle bearing plate number, SKS4854X, who collided with the vehicle behind me and thus



**SINGAPORE
POLICE FORCE**



T/20180318/2092

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 4

Report No. T/20180318/2092

CONTINUATION OF REPORT

collided onto me. I then exchange particulars with the person involving with the accident. There was no police or ambulance that attended to the accident. After the accident I drove to SMRT workshop under my company and parked my vehicle there. I was still feeling pain and sore from the accident so I decided to go to KHOO TECK PUAT hospital. I received 7 days mc from the hospital. I planned on claiming this accident through my company's insurance.



**SINGAPORE
POLICE FORCE**



T/20180318/2092

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

4 of 4


Report No. T/20180318/2092


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: 
F /
MUHAMAD NAUFAL BIN MUHAMAD NEZAM

Signature Of Informant: 

Signature Of Interpreter:
Not applicable


Date/Time:
18/03/2018 21:16

Officer In Charge Of Case:
TP / AEIT /

Sgt 2 YEO KIA HUAT
Contact No: 65476325

SN 085

Classification Of Case:

Authentication Stamp
NP168 

Singapore Police Force

SMRT Accident Vehicle Repair Estimates

G17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4705M
 Ref. No : TAX/03/18/2092
 Reg. Date : 10/12/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN ENG LEE
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 18/03/2018 02:05:00 PM
 Accident Reported Date / Time : 19/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095101
 Special Instruction to ARC, if any :
 DROVE IN / SJK565K
 Prepared Date : 19/03/2018 10:21:35 AM



Sebastian
 20/3/18
 - Long Sun Repair
 - Question Mark Item
 Photo
 - Photo After Paint

[Signature]
 26/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605753749

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	338.00	0.00
Total Spray Painting Charges	:	558.00	0.00
Total Material Charges	:	1,057.19	1,057.19
Other Charges	:	556.88	0.00
TOTAL	:	2,510.07	0.00
Lum Sum Total	:	2,500.00	0.00
No. of Repair Days	:	3.00	0.00
Prepared / Adjusted By	:		2 days
Arc / Surveyor Sign Off Date	:	19/03/2018 02:52:11 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/03/2018 02:51:19 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 300
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 300
TO RESPRAY BUMPER BEAM	180.00 1	0.00
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
Total Other Costs	556.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
TOTAL MATERIALS								1,321.50	1,321.49	
TOTAL MATERIALS(Discounted)								1,057.19	1,057.19	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4705M
 Ref. No : TAX/03/18/2092
 Reg. Date : 10/12/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN ENG LEE
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 18/03/2018 02:05:00 PM
 Accident Reported Date / Time : 19/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095101
 Special Instruction to ARC, if any :



DROVE IN / SJK565K NTWL HS
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang@lkkauto.com HP:90036121

Prepared Date : 19/03/2018 10:21:35 AM

QC 21/3/18 18:00 P955

 Date 2nd witness

 Date 1st witness

☐ ☐ Radio Antenna

☐ ☐ Recording Camera

Recording Camera

Radio Antenna

1st witness

2nd witness

☐

☐

Date

Date

353833
 1
 1 1 2 1
 4 2 4 1

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

Vehicle Return Time:

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605753749


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	200.00
Total Spray Painting Charges :	558.00	200.00
Total Material Charges :	211.26	120.00
Other Charges :	556.88	180.00
TOTAL :	1,664.14 3114.88	700.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	2.00
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	19/03/2018 02:52:11 PM	20/03/2018 03:40:24 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 19/03/2018 02:51:19 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0594

Invoice No :

Quotation Date : 26/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	200.00
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	558.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88
Lump Sum Adjustment by Surveyor	0.00	-146.88
Total Other Costs	556.88	180.00

3114 28

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
76891-47020		6505619	BUMPER LIP REAR	0	228.90	25.00	0.00	Replace	Not given	No <i>X</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No <i>X</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Check	No <i>X</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>X</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>
TOTAL MATERIALS							805.88	120.00		
TOTAL MATERIALS(Discounted)							211.26	120.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

120.00
+ 200.00
+ 526.88

846.88

- 20%

677.50

L/S \$700/-

Sebastian
26/3/18

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 27 March 2018 3:39 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: RE: SHC4705M

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Tuesday, 27 March 2018 10:35 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: RE: SHC4705M

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi
Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 26 March 2018 2:22 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: SHC4705M

Hi Sebastian,

Attached herewith the repair estimate of SHC 4705M having Case No: TAX/03/18/2092.

There is no change to the approved amount of \$700 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 26 March 2018 2:03 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005512/Svbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 10-04-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJK 565K	Veh. Inspected	SHC 4705M	
Policy No.	5097656244	Coverage (\$)	0.00	
Claim No.	MT/0986530-002	Excess (\$)	0.00	
Assign From		Assign Date	20/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U605753749	Colour	MAROON	
Odometer	353833	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/03/2018	Inspection Date	20/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4705M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER REAR	TO REPAIR	458.60	-
			1,662.00	120.00
	<u>LABOUR</u>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		834.88	526.88
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		558.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,452.88	726.88
GRAND TOTAL			3,114.88	846.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				700.00

Report Ref No. NS/INC18005512/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.