

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3223M

MAKE :

MODEL : HYUNDAI i40

Argenta - CP/P)

DATE 23/3/2018

LKK -

IS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover cut			\$ 562.30	✓
	Front Bumper Bracket Top (RH) src			\$ 22.40	×
	Front Bumper Retainer Mounting src			\$ 9.20	×
	Headlamp (RH) check			\$ 1,388.00	✓
	Front Fender (RH) Dented			\$ 619.00	✓
	Front Fender Shield (RH) deformed			\$ 169.80	✓
	Front Fender Retainer src			\$ 9.20	×
	Frt Wheel Hub Cap (RH) cut			\$ 150.70	✓