

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

23-Mar-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1113 K

|      |                                                |          |          |          |
|------|------------------------------------------------|----------|----------|----------|
| 1 pc | o/s mirror Assy <i>broken</i>                  | \$       | 590.00   | ✓        |
| 1 pc | Front o/s door <i>Dented</i>                   | \$       | 791.00   | ✓        |
| 1 pc | Front o/s door hinge upper <i>src</i>          | \$       | 33.00    | X        |
| 1 pc | Front o/s door hinge lower <i>src</i>          | \$       | 33.00    | X        |
| 1 pc | Front o/s door rubber weatherstrip <i>huc</i>  | \$       | 104.00   | ✓        |
| 1 pc | Front o/s door outer handle <i>cut</i>         | \$       | 40.00    | ✓        |
| 1 pc | Front o/s door outer handle cover <i>cut</i>   | \$       | 10.00    | ✓        |
| 1 pc | Front o/s door out handle base Assy <i>cut</i> | \$       | 39.00    | ✓        |
| 1 pc | Rear o/s door <i>src</i>                       | \$       | 765.00   | ✓        |
| 1 pc | Rear o/s door hinge upper <i>src</i>           | \$       | 33.00    | X        |
| 1 pc | Rear o/s door hinge lower <i>src</i>           | \$       | 33.00    | X        |
| 1 pc | Rear o/s door lock <i>?</i>                    | \$       | 289.00   | ?        |
| 1 pc | Rear o/s door checker <i>src</i>               | \$       | 44.00    | X        |
| 1 pc | Rear o/s door rubber weatherstrip <i>huc</i>   | \$       | 104.00   | ✓        |
| 1 pc | Rear o/s door motor <i>?</i>                   | \$       | 270.00   | ?        |
| 1 pc | Rear o/s door regulator <i>?</i>               | \$       | 290.00   | ?        |
| 1 pc | Rear o/s fender <i>cut</i>                     | \$       | 1,205.00 | ✓        |
| 1 pc | Rear o/s fender inner shield <i>dented</i>     | \$       | 120.00   | ✓        |
| 1 pc | Rear windscreen moulding <i>huc</i>            | \$       | 87.00    | ✓        |
| 1 pc | Rear o/s wheel cover <i>cut</i>                | \$       | 116.00   | ✓        |
| 1 pc | o/s rocker panel garnish <i>cut</i>            | \$       | 286.00   | ✓        |
|      |                                                | \$       | 5,282.00 |          |
|      |                                                | Less 10% | \$       | 528.20   |
|      |                                                |          | \$       | 4,753.80 |

### S/NETT

|       |                                               |    |        |      |
|-------|-----------------------------------------------|----|--------|------|
| 1 set | o/s door sticker <i>huc</i>                   | \$ | 100.00 | ✓    |
| 1 pc  | Rear o/s fender sticker <i>huc</i>            | \$ | 60.00  | ✓    |
| 1 set | o/s rocker panel garnish clips <i>huc</i>     | \$ | 38.00  | 30/- |
| 1 set | Rear o/s fender inner shield clips <i>huc</i> | \$ | 28.00  | 15/- |

23-Mar-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1113 K**

|                                                                                                                                                                                                                                               |                        |                 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------------|
| Sundry                                                                                                                                                                                                                                        | \$ 50.00               | NY              |
| To check wheel alignment                                                                                                                                                                                                                      | \$ <del>80.00</del>    | 60/-            |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                                                                                                                        | \$ <del>120.00</del>   | 80/-            |
| To dismantle / refit the front o/s door & rear o/s door inner component into new shell door                                                                                                                                                   | \$ <del>400.00</del>   | 60/-            |
| To labour charge for dismantle and renew the accident damaged parts. To heat/weld and cut off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the o/s door centre pillar, front o/s windscreen pillar etc | \$ <del>1,300.00</del> | 1000/-          |
| To putty and spray painting on front o/s windscreen pillar, front o/s door, rear o/s door, rear o/s fender, o/s rocker panel garnish, o/s centre pillar, rear o/s fender, rear bumper, o/s mirror                                             | \$ <del>1,500.00</del> | 1000/-<br>800/- |
| To apply rustproofing on the repaired and replaced panels.                                                                                                                                                                                    | \$ <del>300.00</del>   | 80/-            |
|                                                                                                                                                                                                                                               | <u>\$ 8,729.80</u>     |                 |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT  
INCLUDE ANY UNFORESEEN DAMAGES.**

23/03/2018 @ 15:00hr

Kia Optima

L/Side 5 dgs.



2KE Auto

Photo after repair