



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Foo Kok Leng  Blk 232 Bishan Street 22 #11-102 Singapore 570232  Contact No	Cust No/Name	LCV01959/Ms Foo Kok Leng
	Reg No/Reg Date	SLU2504Y / 28/11/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MJ5751916
	Engine No	G4FGHH685336
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV01959	CRDVCH	23/03/2018/ 14:12	TLC	442 / CocoLu	25457

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW REAR BUMPER, REPAIR REAR END PANEL				825 1650.00
E PNT98000 TO SPRAY PAINT FOR REAR BUMPER, REAR END PANEL				840 1260.00
E PNT88000 TO REMOVE & INSTALL PARKING SENSOR				60 100.00
M SUNDRY TO SUPPLY PARKING SENSOR				? 220.00
M SUNDRY Sundry				20.00
M COVER-RR BUMPER	1.00	688.00	00.00	PE 688.00
M COVER-RR BUMPER,CTR	1.00	347.00	00.00	PE 347.00
M BRACKET-RR BEAM LWR MTG	1.00	5.00	00.00	? 5.00
M BRACKET-RR BEAM LWR,CTR	1.00	5.00	00.00	? 5.00
M BEAM-RR BUMPER	1.00	318.00	00.00	? 318.00
M BRACKET-RR BEAM UPR MTG,RH	1.00	3.00	00.00	? 3.00
M BRACKET-RR BEAM UPR MTG	1.00	3.00	00.00	? 3.00
M STAY-RR BUMPER RH	1.00	120.00	00.00	? 120.00

# Estimate

Rasul  
Hp 90010068  
4 days  
09/04/18 @ 1745  
Resny 64 paint

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

	Nett	4,739.00
7% GST on	4739.00	331.73
<b>Total Payable</b>		<b>5,070.73</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.