

ASS. REC. BY:

REF: TMI / (C3/TMI 6003553/Kd02

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Tans Cob

of _____

Insured: YL 7201G

Policy No. M309672

Claims No. M150546

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH16 6525 Yr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: Renault Latitude c.c. 1995

Colour M-White / Red A/C: Insured / Std / NI / NA

Sp. Reading 494334 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1ABL15AUC 278390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Gri 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 7 mm

L/Bal. 9 mm L/Bal. 7 mm

D.O.A. 22/3/18 D.O.I. 23/3/18

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/3	Mile pass to Catherine 11 Rps @ 3850 (Red @ 19547-74, 84%) SH16 6525 - NGA / ENC16024172 / Y
	YL 7201G - NGA / ENC16024173 / Y
22/3/18 @ 3.46 pm	email GIA report & estimate to Shirley.

RECEIVED 29 MAR 2018

Date/Time, File Pass to? : Prell. Report

1) 28/3 Theresa : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Report Format: TP
Lump Sum / I.B.I: (\$) 3850

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation: 250

S + RS: 10

Photos _____

Others _____

TOTAL

260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CC3/TMI18005553/Kqb

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 26-03-2018



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 7201G	Veh. Inspected	SHF 652S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/03/2018	Inspection Date	23/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 27 March 2018 3:46 PM
To: Too Joon Hwa
Cc: Priscilla Tan; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 22/03/2018 , SHF 652S (TP Vehicle), YL 7201G (OI Vehicle)
Attachments: SHF652 ESTIMATE.pdf; SHF652 GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle **SHF 652S** M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 23/03/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHF652S
Vehicle to be Exported: Yes
Intended De-registration Date: 22 Mar 2018
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2014
Engine No.: M9R8839C001571
Chassis No.: VF1ABL15AUC278390
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 30 Jun 2014
First Registration Date: 30 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Jun 2022
PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2022
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$57,338.00
COE Rebate Amount: \$30,600.00
Total Rebate Amount: \$39,973.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2018.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/03/2018 16:41
Date Of Accident	22/03/2018 15:00
Exact Location Of Accident	CHOA CHU KANG NORTH 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF652S
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	CHUA CHIN SIANG
NRIC No	S1226839D
Date Of Birth	25/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	05/11/1980
Driving Experience	37 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96747322
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 461 CHOA CHU KANG AVENUE 4 #07-77
Postcode	680461
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 22.03.2018 at about 1500hours, I was stationary straight on the extreme right lane along Choa Chu Kang North 7 when the traffic light was red, Suddenly Vehicle B (YL7201G) in front of me making reverse without observing oncoming vehicle and hit onto my taxi's front portion

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL7201G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	ZHANG SHAODONG
NRIC/Passport Number	07518056
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach BIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 652S

Not Notified
11 Rm @ 3850/-

AAD1803-198

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHF 652S
VF1ABL15AUC278390
RENAULT
LATITUDE
22.3.2018
TOKIO MARINE

PART		LIST
1	1	BUMPER COVER FRT \$ <i>Bul/RU</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT \$ <i>Sen</i> 181.75
3	1	BUMPER ABSORBER FRT \$ <i>Sen</i> 394.68
4	1	BUMPER RETAINER FRT LH \$ <i>Sen</i> 151.41
5	1	BUMPER SUPPORT FRT \$ <i>Sen</i> 123.88
6	1	BUMPER RETAINER FRT RH \$ <i>Sen</i> 150.77
7	1	BUMPER SUPPORT FRT \$ <i>Sen</i> 123.88
8	1	BUMPER UNDERTRAY FRT \$ <i>Sen</i> 472.83
9	1	BUMPER GRILLE LOWER FRT \$ <i>Sen</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH \$ <i>Sen</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH \$ <i>Sen</i> 207.21
12	1	BUMPER BEAM FRT \$ <i>R</i> 914.08
13	1	TOW COVER FRT \$ <i>Sen</i> 28.61
14	1	RADIATOR GRILLE \$ <i>CRM</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT' \$ <i>CRM</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME \$ <i>Sen</i> 600 1,353.75 X
17	1	FRAME FULL SUPPORT PANEL \$ <i>Sen</i> 615.90 <
18	1	FRAME FULL SUPPORT BRACKET \$ <i>R</i> 89.79 X
19	1	HEADLAMP LH \$ <i>Sen</i> 1,184.43 X
20	1	HEADLAMP RH \$ <i>Not in</i> 1,184.43 ✓
21	1	HEADLAMP PANEL FRT LH \$ <i>R</i> 152.15
22	1	HEADLAMP PANEL FRT RH \$ <i>R</i> 152.15
23	1	BONNET \$ <i>R</i> 1,941.63
24	1	BONNET INSULATOR \$ <i>Sen</i> 405.73
25	1	BONNET STRUT LH \$ <i>Sen</i> 88.61
26	1	BONNET STRUT RH \$ <i>Sen</i> 88.61
27	1	BONNET HINGE LH \$ <i>R</i> 348.31
28	1	BONNET HINGE RH \$ <i>R</i> 348.31
29	1	BONNET LOCK \$ <i>R</i> 305.48
30	1	BONNET CABLE \$ <i>Sen</i> 119.19

Trans-cab Auto Services Pte Ltd

AAD1803-198

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 652S

31	1	BONNET CABLE COVER	\$	Sn	161.03	} X
32	1	BONNET SEAL OUTER	\$	Sn	92.36	
33	1	BONNET SEAL INNER	\$	Sn	157.28	
34	1	FENDER PANEL FRT LH	\$	R	783.83	
35	1	FENDER PANEL FRT RH	\$	R	783.83	
TOTAL			\$		16,772.49	47
10%			\$		1,677.25	
			\$		15,095.24	

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	Sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
21	1	Windscreen moulding	\$	na	100.00	
22	1SET	Front licence plate with holder	\$	nd	80.00	455n
TOTAL			\$		562.50	
TOTAL PARTS			\$		15,657.74	

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,450.00 *5001*

To apply paint protection system (PPS) maintain and enhancement

\$ *nn* 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 652S

AAD1803-198

Putty and spray painting of the affected portion.	\$	2,200.00	2200
To rust-proofing of the affected areas.	\$	170.00	na 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	na 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	200
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1600 X
To replace, refix and top up coolant for radiator	\$	170.00	na 170.00 500 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	na 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	na 170.00 X

TOTAL \$ 7,790.00

Over All Total \$ 23,447.74

72

7 DAYS
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

(LUMP SUM) Repair Days

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18005553/KQBN2

Date: 03/04/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MB019672
Claimant Vehicle No :	SHF652S	Insured Vehicle No :	YL7201G
Date of Loss:	22/03/2018	Nature of Claim:	TP
		Claim No:	M1801546

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF652S	Engine No:	M9R8839C001571
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC278390
Reg. Date:	30/06/2014 (Man. Year: 2014)	Odometer:	494334 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,657.72	4,102.29	11,555.43	73.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,790.00	740.00	7,050.00	90.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,447.72	4,842.29	18,605.43	79.35
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	23,447.72	3,850.00	19,597.72	83.58
+ GST 7.00/7.00% (S\$)	1,641.34	269.50	1,371.84	83.58
Nett Amount (S\$)	25,089.06	4,119.50	20,969.56	83.58

INSPECTION

Date of Assignment: 27/03/2018

Date Inspected: 23/03/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2018)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHF652S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled/Dented	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	151.41 FL	*- FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
12	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
13	1		*TOW COVER FRT	Serviceable	28.61 FL	*- FL
14	1		*RADIATOR GRILLE	Cracked	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Cracked	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	*- FL
17	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
18	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
19	1		*HEADLAMP LH	Serviceable	1,184.43 FL	*- FL
20	1		*HEADLAMP RH	Dented/Cut	1,184.43 FL	*1,184.43 FL
21	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
22	1		*HEADLAMP PANEL FRT RH	Repair	152.15 FL	*- FL
23	1		*BONNET	Repair	1,941.63 FL	*- FL
24	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
25	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
26	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
27	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
28	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
29	1		*BONNET LOCK	Repair	305.48 FL	*- FL
30	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
31	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
32	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
33	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
34	1		*FENDER PANEL FRT LH	Repair	783.83 FL	*- FL
35	1		*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
36	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
37	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
38	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
39	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
40	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
41	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
42	1		*TOW COVER FRT	Serviceable	14.50 FS	*- FS
43	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
44	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
45	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS	
46	2		*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS	
47	2		*SET FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS	
48	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS	
49	1		*SET FRONT LICENCE PLATE WITH HOLDER	Dented	80.00 FS	*45.00 FS	
					Sub Total (\$\$)	17,334.97	4,539.99
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,677.25	437.70
					Total Parts (\$\$)	15,657.72	4,102.29

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,450.00	500.00
2	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	-
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	-
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	-
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	-
12	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	-
13	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	-
14	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (S\$)			7,790.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >