



簡福星摩多工廠 KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147

Tel: (65) 6747 9560, 6743 5344, 6858 4361 • Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

TAX INVOICE

No. 46094

Business Reg. No. 221468-00E
GST Reg. No. M9-0005333-E

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

INVOICE NO : 46094

DATE : 27-12-2018

VEHICLE NO. : SCJ811M
ACCIDENT DATE : 21-03-2018 10:45
THIRD PARTY REF. : GU3490E

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SCJ811M BMW 523I 2.5 AT ABS

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
	LABOUR CHARGES	
1	LMUP SUM REPAIRS	19150.00
TOTAL (D)		19,150.00
TOTAL REPAIR COST :		19,150.00
G S T % :		1,340.50
INVOICE AMOUNT :		20,490.50



IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在鈑金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。