

INVOICE

ASS. REC. BY:

REF: CS/CTI18005570/R1rd3

(Special Instruction)

Survivor:
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

23/3/18 @ 4:16pm

Estimated Cost

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT1034Z

Insured:

SKH 8267Y

at Workshop in/s

Performance Technik

Tel:

9180 0520

of

25 Kaki BK Rd 4 Synergy #01-28

Policy No:

DMPCSN3007921801

Claim No:

SNM18D01551C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/02/2018

CA / REV / REP. / REV 24 HRS lwp?

H.O.D. Endorsement:

Date/Time:

11:21am @ 26/3/18

Person Contacted:

Mr. Ghua

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT1034Z -X
	SKH 8267Y -X
	Confirm L/s \$3200 @ 4 days
	Rec: \$14017.60, 87%

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Mar 2018		23 Mar 2018 16:16 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	CHUA BOON WEI TONG		
Vehicle Reg. No.:	SLT1034Z	Date of Loss:	21/02/2018 00:00 - :59
Claim Type:	TP / SNM18D01551C02	Policy/Cover Note No.:	DMPCSN3007921801
Vehicle Reg. No. (Insured):	SKH8267Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Performance Techni (HQ) 25 Kaki Bukit Road 4 SYNERGY@KB, #01-28, 417800 Kaki Bukit - Tel: 9180 0520		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/04/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Crystal Tan <crystal@legaloptions.biz>
Sent: Friday, 23 March, 2018 3:52 PM
To: Lucas Lee
Subject: Re: PRS FOR SLT1034Z (CTI REF: SNM18D01551C02) (YrRef: 18-A38-9193-VLJP.CT)

Dear Lucas,

Our client propose Kenneth Kong.

Your said surveyor may contact, Mr Myron at 9180 0520, M/s Performance Technik at 25 Kaki Bukit Road 4 #01-28, Synergy @ KB, Singapore 417800.

Thanks n regards,

Crystal
Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

On Fri, Mar 23, 2018 at 3:49 PM, Pinky Wong <pinky@legaloptions.biz> wrote:

Thanks n regards,

Pinky
Legal Executive

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

----- Forwarded message -----

From: Lucas Lee <lucas.lee@sg.cntaiping.com>

Date: Fri, Mar 23, 2018 at 3:35 PM

Subject: PRS FOR SLT1034Z (CTI REF: SNM18D01551C02) (YrRef: 18-A38-9193-VLJP.CT)

To: "PINKY@LEGALOPTIONS.BIZ" <PINKY@legaloptions.biz>

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Regards,

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6181

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18005570/T1rd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 26-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 8267Y	Veh. Inspected	SLT 1034Z
Policy No.	SNM18D01551C02	Coverage (\$)	0.00
Claim No.	SNM18D01551C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/02/2018	Inspection Date	
Survey held at	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2018 11:38
Date Of Accident	21/02/2018 19:40
Exact Location Of Accident	SHENTON WAY (OUTSIDE MAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1034Z
Insured/Policyholder	
Name Of Registered Owner	CHUA BOON WEI TONY
NRIC No	S9108040J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98229952
Alternative Phone No	OFFICE-98229952

Vehicle Particulars

Manufacturer	AUDI
Model	A5 2.0L TFSI QUATTRO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096390023 CLASSIC
Cover Note Number	

Driver

Name of Driver	CHUA BOON WEI TONY
NRIC No	S9108040J
Date Of Birth	07/03/1991
Occupation	INDOOR
Date Of Driving Pass	14/10/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98229952
Fax Number	
Contact Number	OFFICE-98229952
Email Address	NOEMAIL

Address BLK 93A TELCK BLANGAH ST 31 #23-163
 Postcode 101093
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle: -
 -
 -

General information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : ALYN MAGENTA MOK HUIYI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWNER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKH8267Y
 Vehicle Make/Model/Colour VOLKSWAGEN POLO 1.4 AT 6R13E7
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHUA BOON WEI TONY
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLT1034Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name ALYN MAGENTA MOK HUIYI (WIFE)
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLT1034Z
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me to be processed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims (including the settlement of the claims and any necessary investigations relating to the claims);
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and assignment in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurer(s) and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, litigation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

2-2 FEB 2018

Driver's Signature
(If different from the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: feedback@singnet.com.sg
Name
Title/Position

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE MAIN WAY, INSIDE MAS BUILDING, AND I WAS STOPPING BY THE BACK VERANDAH SKH82674 SUDDENLY HIT ME FROM BEHIND.

DECLARATION

I declare the foregoing particulars are true to every respect.


 Name & Title

22 FEB 2018


 Name & Title

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933

Tel: 67416697 Fax: 67492305

Email: yackb@singnet.com.sg


 Name & Title

9115 2737

Attn : Person In Charge
 Vehicle No : SLT 1034 Z
 Model : Audi A5
 Chassis : WAUZZZ8T6BA084948
 Year / CC : 2011 / 2.0

Eno Gray
 CLK
 29/3/18

Spare Parts	Price
Rear Bumper	\$ 1,177.00
Rear Bumper Reverse Sensor x4pcs (2PC)	\$ S/N 343 686.40
Rear Bumper Towing Cover X	\$ 39.60
Rear Bumper Sensor Hardness	\$ 508.20
Rear Bumper Retainer Left	\$ 50.60
Rear Bumper Retainer Right X	\$ 50.60
Rear Bumper Top Retainer 2pcs LH - CCA	\$ 50.60
Rear Bumper Spoiler	\$ 175.00
Exhaust - Labour (400) Labor	\$ 4,400.00
Exhaust bracket 2pcs	\$ 100.00
Exhaust mounting 6pcs	\$ 318.00
LH outer Tail light X	\$ 803.00
RH outer Tail light X	\$ 803.00
LH Inner Tail Light X	\$ 532.40
RH Inner Tail Light X	\$ 532.40
Rear Reinforcement	\$ 413.60
Rear Panel Top Garnish X	\$ 783.20
Rear Lid	\$ 1,870.00
Rear Lid Latch	\$ 149.60
Rear Boot Rubber Seal	\$ 176.00
Heat Shield Left Rear	\$ 136.40
Heat Shield Right Rear	\$ 136.40
Rear Emblem	\$ 110.00
Alignment	\$ 120.00
Spray Paint	\$ 500 1,000.00
Labour	\$ 500 1,400.00
Support Panel	\$ 413.00

Rear Reinforcement Support Bracket x 2 pcs \$ 281.60

DE-
 nn-
 X nn
 cut-
 nn-
 X Svc
 ERS-
 sca-
 2376
 59
 2257.20
 nn
 nn

Please assist the above mention spare parts list price. Thank You

Repair
 Hp 90010068
 3 days
 4/3
 26/03/18 @ 1640
 Resurvey after repair

4/3 - 3,200
 4 days

S/N - 343.00
 parts - 2257.20
 labour 1400.00
 4000.20
 20%
 3,200.16

labour - 1100

X 17,117.60

Attn : Person In Charge

Vehicle No : SLT 1034 Z

Model : Audi A5

Chassis : WAUZZZ8T6BA084948

Year / CC : 2011 / 2.0

Spare Parts	Price	
Rear Bumper	\$ 856.00	DE ✓
Rear Bumper Reverse Sensor x4pcs <i>2 pcs</i>	\$ 499.20	? p 2 pcs
Rear Bumper Towing Cover	\$ 28.80	X
Rear Bumper Sensor Hardness	\$ 369.60	? int ✓
Rear Bumper Retainer Left	\$ 36.80	X ✓
Rear Bumper Retainer Right	\$ 36.80	X
Rear Bumper Top Retainer 2pcs	\$ 36.80	X ✓
Rear Bumper Spoiler	\$ 128.00	SCR ✓
Bumper Top Retainer 2pcs		
Exhaust <i>(M+M)</i>	\$ <i>price?</i> 2,800.00	?
Exhaust bracket 2pcs		X
Exhaust mounting 6pcs		X
LH outer Tail light	\$ 584.00	X
RH outer Tail light	\$ 584.00	X
LH Inner Tail Light	\$ 387.20	X
RH Inner Tail Light	\$ 387.20	X
Rear Reinforcement Sponge		?
Rear Reinforcement	\$ 300.80	? ✓
Rear Panel Top Garnish	\$ 569.60	?
Rear Lid	\$ 1,360.00	X
Rear Lid Latch	\$ 108.80	X
Rear Boot Rubber Seal	\$ 128.00	X
Heat Shield Left Rear	\$ 99.20	X
Heat Shield Right Rear	\$ 99.20	X
Rear Emblem	\$ 80.00	X
Alignment	\$ 120.00	✓
Spray Paint		

Please assist the above mention spare parts list price. Thank You

Rasul
 Hp 90010068
 3 days
 4/8
 26/03/18 @ 1640
 Reay after repair
 28/3/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Mar 2018		23 Mar 2018 16:16 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	- ID: -								
Main Claimant:	CHUA BOON WEI TONG								
Vehicle Reg. No.:	SLT1034Z	Date of Loss:	21/02/2018 00:00 - :59 [79 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01551C02	Policy/Cover Note No.:	DMPCSN3007921801						
Vehicle Reg. No. (Insured):	SKH8267Y	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Performance Techni (HQ) 25 Kaki Bukit Road 4 SYNERGY@KB, #01-28, 417800 Kaki Bukit - Tel: 9180 0520								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/04/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT1034Z (SNM18D01551C02)
[SKH8267Y]
TP
CHUA BOON WEI TONG
Feb 21 2018 12:00AM
[-]
Performance Techni

Upload Documents		Upload Photos		Compose New Letter		View View in Browser <input type="button" value="v"/>		
Photos/Images							3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
2	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
3	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
4	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
5	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
6	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
7	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
8	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
9	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
10	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
11	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
12	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
13	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
14	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
15	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
16	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
17	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
18	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
19	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
20	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
21	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
22	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
23	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
24	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
25	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
26	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
27	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
28	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
29	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
30	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
31	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
32	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
33	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
34	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
35	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
36	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	
37	20/08/18 14:49	General View				 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/08/18 14:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/08/18 14:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/03/18 16:15	PRS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118005570/RD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3007921801	
Claimant Vehicle No: SLT1034Z	Insured Vehicle No: SKH8267Y	
Date of Loss: 21/02/2018	Nature of Claim: TP	Claim No: SNM18D01551C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1034Z		
Make & Model: AUDI A5, 2.0 (A)	Engine No: CDN202168	
Reg. Date: 21/07/2011 (Man. Year: 2011)	Chassis No: WAUZZZ8T6BA084948	
Colour: Black	Odometer: 100930 km	
Engine Capacity: 1984 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19	Rear Tyre Size: 275/35 R19
Front Left Side: Goodyear 6 mm	Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm	Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,884.60	2,600.20	7,284.40	73.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,333.00	1,400.00	5,933.00	80.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,217.60	4,000.20	13,217.40	76.77
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	17,217.60	3,200.00	14,017.60	81.41

INSPECTION

Date of Assignment: 23/03/2018		
Date Inspected: 26/03/2018	Inspected At:	Performance Techni (HQ) 25 Kaki Bukit Road 4 SYNERGY@KB, #01-28 Singapore 417800
Estimated Period of Repair: 4.0 days		

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 06 Sep 2018)
Parts:	N/A AUDI A5 2.0 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1034Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,177.00 F	*1,177.00 FL
2	4		*REAR BUMPER REVERSE SENSOR	Not Working (2 PCS ONLY)	686.40 FS	*343.00 FS
3	1		*REAR BUMPER TOWING COVER	Not Necessary	39.60 F	*- FL
4	1		*REAR BUMPER SENSOR HARDNESS	Cut	508.20 F	*508.20 FL
5	1		*REAR BUMPER RETAINER LEFT	Necessary	50.60 F	*50.60 FL
6	1		*REAR BUMPER RETAINER RIGHT	Serviceable	50.60 F	*- FL
7	2		*REAR BUMPER TOP RETAINER	N/S Cracked	50.60 F	*50.60 FL
8	1		*REAR BUMPER SPOILER	Scratched	176.00 F	*176.00 FL
9	2		*EXHAUST BRACKET	Not Necessary	100.00 F	*- FL
10	6		*EXHAUST MOUNTING	Not Necessary	318.00 F	*- FL
11	1		*LH OUTER TAIL LIGHT	Not Necessary	803.00 F	*- FL
12	1		*RH OUTER TAIL LIGHT	Not Necessary	803.00 F	*- FL
13	1		*LH INNER TAIL LIGHT	Not Necessary	532.40 F	*- FL
14	1		*RH INNER TAIL LIGHT	Not Necessary	532.40 F	*- FL
15	1		*REAR REINFORCEMENT	Bent	413.60 F	*413.60 FL
16	1		*REAR PANEL TOP GARNISH	Not Necessary	783.20 F	*- FL
17	1		*REAR LID	Not Necessary	1,870.00 F	*- FL
18	1		*REAR LID LATCH	Not Necessary	149.60 F	*- FL
19	1		*REAR BOOT RUBBER SEAL	Not Necessary	176.00 F	*- FL
20	1		*HEAT SHIELD LEFT REAR	Not Necessary	136.40 F	*- FL
21	1		*HEAT SHIELD RIGHT REAR	Not Necessary	136.40 F	*- FL
22	1		*REAR EMBLEM	Not Necessary	110.00 F	*- FL
23	2		*REAR REINFORCEMENT SUPPORT BRACKET	Not Necessary	281.60 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,884.60	2,719.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	118.80
Total Parts (\$\$)	9,884.60	2,600.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	EXHAUST	New	4,400.00	400.00
2	ALIGNMENT	New	120.00	0.00
3	SPRAY PAINT	New	1,000.00	500.00
4	LABOUR	New	1,400.00	500.00
	}			
5	SUPPORT PANEL	New	413.00	0.00
	}			
Gross Labour Cost (S\$)			7,333.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >