

EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

AXA INSURANCE SINGAPORE PTE LTD

143 CECIL STREET

#01-01 GB BUILDING

SINGAPORE 069542

Attention : Motor Claim Department

Contact : 63387288 63387288 Fax No. : 63382522/68804838

Estimate : T118/004

Date : 23/03/2018

Vehicle Num. : SLJ 7600 C

Make/Model : TOYOTA LEXUS GS300

Chassis/Eng# : JTHBH96S405063084

Accident Date : 23/03/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.		FRONT BUMPER <i>Disturbed</i>		770.00 ✓
2.		FRONT GRILLE ASSY <i>Cracked</i>		435.45 ✓
3.		INNER SEAL <i>New</i>		422.65 ✓
4.	2pcs	HEAD LAMP ASSY <i>Cracked</i>	1,292.65	2,585.30 2585.30 ✓
5.		FRONT BUMPER REINFORCEMENT <i>But</i>		424.80 ✓
6.	2pcs	SIDE RETAINER <i>RH</i>	117.80	235.60 117.80 ✓
7.		BUMPER BEAM <i>But</i>		406.86 ✓
8.		GRILLE BOTTOM FRONT <i>Cracked</i>		165.95 ✓
9.		FENDER - FRONT - RH <i>Cracked</i>		526.10 ✓
10.		FOG LAMP <i>Cracked</i>		418.30 ✓
11.	10PCS	CLIPS <i>on</i>	7.80	78.00 30 ✓
List Total S\$:				6,469.01
LABOUR :				
ACCIDENT REPAIR PANEL BEATING				960.00 <i>SW</i>
RESPRAY PAINT WORK ON REPAIR AREA				980.00 <i>6.00</i>
RUSTPROOFING TREATMENT				200.00 <i>x</i>
WIRING SERVICE & FOCUS HEAD LAMP				80.00 <i>30</i>
Labour Total S\$:				2,220.00

SingDollars : Eight Thousand Six Hundred Eighty-Nine & Cents One Only

Total S\$: 8,689.01

EVER SEN AUTO SERVICE

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

H/s Admin Lj
26/03/18.
052yp

total: 6422.50
H/s: S.K