



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
Mr TAY KOK ENG Blk 927 Hougang St 91 #11-75 Singapore 530927	Cust No/Name /Mr Tay Kok Eng Reg No/Reg Date SLT8064R / 14/11/2017 Date In/Mileage / 0 Chassis No KNAFJ411MJ5743750 Engine No G4FGHH679737 Make/Model KIA/FORTE K3 1.6 A L 189 Colour/Trim B4U / WK
Contact No Mobile: 97337245	

Account No	Term	Date/Time Printed	CSE	Opn No	WIP No
CSM00001	Cash	22/03/2018/ 19:03		218 / MarsLer	54396

Description of Goods/Service	Qty	Unit Price	Amount
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS			60. 80.00
S MIPNT88088 TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS			300 600.00
S MIPNT88088 TO REPLACE REAR BUMPER, REAR BEAM, ETC -REPAIR ON REAR END PANEL STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS			bumper - 600 end panel - 1200 1800.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS			bumper - 420 end panel - 840 1260.00
S MIPNT88088 TO CONDUCT COMPUTERIZE SCANNING & DIAGNOSTIC			✓ 250.00
M SUNDRY REVERSE SENSOR			? 280.00
P KS 86611 A7 800 COVER - REAR BUMPER	1.00	688.00 10.00	de 619.20
M KS 86695 A7 800 COVER - REAR BUMPER,	1.00	347.00 10.00	ant 312.30
M KS 86613 A7 001 LH BRACKET - REAR BU	1.00	29.00 10.00	? 26.10
M KS 86614 A7 001 RH BRACKET - REAR BU	1.00	29.00 10.00	? 26.10
P KS 92401 A7 600 LH LAMP ASSY - REAR	1.00	354.00 10.00	ant 318.60
P JJMR328954 CLIP, RR BUMPER	10.00	3.00 10.00	not 27.00
P KS 86631 A7 800 BEAM - REAR BUMPER	1.00	318.00 10.00	? 286.20
M KS 86636 A7 000 BRACKET - REAR BEAM	2.00	5.00 10.00	? 9.00
M KS 86635 A7 000 BRACKET - REAR BEAM	1.00	5.00 10.00	? 4.50
M KS 86641 A7 800 LH STAY - REAR BUMPE	1.00	120.00 10.00	? 108.00
Z NOTES ACCIDENT ON 22/03/2018 ALONG DEFU LANE AVENUE 1 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SHA4352H TP INS :			

Estimate

Taughtin 97445749
3-4 days 'w/p'
sur@lhand.com
26/3/18 @ 11pm

Confirm & accepted by	<ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	Resurvey Parts before paint Labour Standard Menu Specialist Job Others (Lub, etc) Sundry Total (w/o GST)	1,737.00 0.00 0.00 3,990.00 0.00 280.00 6,007.00
Authorized signatory and company stamp			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.