

INS. CASE OWNER

CC 4, EQ11800 5584, K3 Ka39

LKK:
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

26/3/18

Date / Time:

7/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 1173C

Name of Insured:

388 P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/03/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Rahmah Subhanawati

Driver Tel No.:

83994573 (V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DmacPH817-0043001

T-Dyna

Leston Puyugue

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGP 8794 Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

LANK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Slp
26miSGP 8794 Y - N/A/M/S/L/43 20/03/18, D.O.A. 23/0/14
GBE 1173C - X

HEAD TO R LAMP, OI BEHIND

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 2.4.15 JAY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

2/4

Sent By:

Hm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

25-2/4

Confirm with:

JENNY

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 21

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

8,070

Loss of Rental (LOR):

S\$

300

13 days)

100

Loss of Use (LOU):

S\$

-

(5 x days)

Loss of Income (LOI):

S\$

-

(5 x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

22.22

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

1,372. x x

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

1,372. x x

Name 1:

LAI HUAT (MENG KEE) MOTOR PTE LTD

Payee 2 (Strike if N.A.)

S\$

x

Name 2:

x

Payee 3 (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

REF: EQI

ASSIGNMENT

From: Date: 26/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGP 8794Y
at Workshop m/s: Lei Huet (Meng Kee)
of: 160 Sin Ming Drive # 04-01

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

13 File pass to Catherine

B/K

Veh No: SGP 8794Y Regn: 12 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes 3 SP cc 1598

Colour: M. Blue A/C Insured / Std / NI / NA

Sp. Reading: 74986 TiRadio: Insured / Std / NI / NA

Eng No:

C.No: JM69K106270319245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 5 mm R/Bal: 7 mm

L/Bal: 5 mm L/Bal: 7 mm

D.O.A: 20/3/18 D.O.I: 26/3/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) 3-400 M

2) Phone

3) Other

Report Format:

Lump Sum / I.B.I: US

Add Fee: ☐ Site Insp US☐ Interview US☐ Tech. Insp US☐ Weekend US

TOTAL

R (\$631.85/397)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ118005584/Kka3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 26-03-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 1173C	Veh. Inspected	SGP 8794Y	
Policy No.	DMCPHQ17-004300	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/03/2018	Inspection Date	26/03/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18005584/Kka3

Date: 04.04.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SGP 8794Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.03.2018 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	1,631.85
Revised Estimate Amount	: S\$	1,290.85
"Check" Items Amount	: S\$	161.00
Total (Including Check Items)	: S\$	1,451.85
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

来發 (明记) 嘛哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575079. Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0018847
Mah Peng Ann Calvin

Page 1 of 2
Your ref TP-GBE 1173G EQ
Job No 69335
Our ref 18.03.35
Payment
Date 23/3/2018

Attn

Vehicle No SGP 8794Y
Vehicle Model Mazda 3
Accident on 20/3/2018

*Not wither
Resurvey B4 pain
3 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts					
1.00	Pc	Rear bumper	285.00		285.00
1.00	Pc	Rear bumper reinforcement	140.00		140.00
1.00	Pc	Rear Mazda logo emblem	20.00		20.00
1.00	Pc	Rear Mazda emblem	14.00		14.00
1.00	Pc	Rear 3 emblem	10.00		10.00
1.00	Pc	Rear SP emblem	50.00		50.00
Total amount of parts supplied - S\$519.00					
1.00		15% of parts supplied	77.85		77.85
Special nett item					
1.00	Pc	Rear number plate	35.00		35.00
Labour & Misc					
1.00		To straighten rear body, to knock dents on	500.00		500.00

*Ph
NN
na
na
na
na
na*

CRT 35.00 ✓

400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式, 同时, 我们亦提供最新方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repair. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

EST. No ... EST0018847
 Mah Peng Ann Calvin

Page ... 2 of 2
 Your ref ... TP-GBE 11730 EQ
 Job No ... 89335
 Our ref ... 18.03.35
 Payment ...
 Date ... 23/3/2018

Attn ...

Vehicle No ... SGP 8794Y
 Vehicle Model ... Mazda 3
 Accident on ... 20/3/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
		rear boot lid and renew of parts			
1.00		To spray paint	500.00		500.00

4201

Sub-Total 1,631.85
 GST 7.00% 114.23
 Total SS 1,746.08

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Catherine Chong (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 23 March, 2018 4:58 PM
To: assignments
Cc: Admin-D (LKKAuto); Admin A
Subject: FW: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Attachments: SGP 8794Y.pdf; GBE1173C.pdf
Importance: High

Dear Assignment Team,

Fyi.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

23032018 @ 5:03pm
Jenny veh not in
26-03-2018

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Friday, 23 March 2018 4:21 PM
To: Admin A <admin-a@lkkauto.com>
Cc: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: FW: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Importance: High

Dear all,

Please arrange to attend to this PRS on Monday.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately.

From: Tan Wei Yin
Sent: Friday, March 23, 2018 4:15 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: FW: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Importance: High

FYNA

Regards,

Tan Wei Yin
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 64969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]
Sent: Friday, March 23, 2018 2:42 PM
To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Subject: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Importance: High

Dear Sir

We refer to the above matter.

Please can you arrange for survey of our client's vehicle no. SGP 8794Y on Monday (26.03.2018)?

Supporting documents are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 4 April, 2018 10:24 AM
To: Joel Goh
Cc: EQI PRS; Janet Tan; Admin A; CS A Team
Subject: RE: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Attachments: LKK SURVEY PHOTO.pdf; TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf
Categories: HMK

WITHOUT PREJUDICE

Your ref: TBA
LKK ref: CC4/EQI18005584/Kka3

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SGP 8794Y

Date of survey: 26.03.2018

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Friday, 23 March, 2018 4:21 PM
To: Admin A <admin-a@lkkauto.com>
Cc: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: FW: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Importance: High

Dear all,

Please arrange to attend to this PRS on Monday.

Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :

From: Tan Wei Yin
Sent: Friday, March 23, 2018 4:15 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: FW: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)
Importance: High

FYNA

Regards,

Tan Wei Yin
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 64969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]
Sent: Friday, March 23, 2018 2:42 PM
To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>

Subject: Request for Survey (TP) - Your Ref: GBE 1173C / Our Ref: SGP 8794Y (Date of Accident: 20.03.2018)

Importance: High

Dear Sir

We refer to the above matter.

Please can you arrange for survey of our client's vehicle no. SGP 8794Y on Monday (26.03.2018)?

Supporting documents are enclose for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

REMINDER

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 18 December 2018 7:21 PM
To: 'Jenny Lim'
Cc: Admin A
Subject: SGP 8794Y -2018 JL ON 20.03.2018 / EQ GBE 1173C

WITHOUT PREJUDICE

Dear Jenny,

On without prejudice basis and without admission of liability, we offer settlement as follows:

Repair Cost	: \$1,070.00 (GST included)
Loss of Rental	: \$ 300.00 (\$100 x 3 days)
GIA Search	: \$ 2.00
Total	: \$ 1,372.00

Kindly confirm acceptance.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

來發(明記)摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

Your Ref: GBE 1173C
Our Ref: SGP 8794Y - 2018/JL

16 November 2018

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
Attention: Motor Claims

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING VEHICLE NOS. SGP 8794Y AND GBE 1173C ON 20/03/2018 AT LEFT TURN TO BISHAN ROAD FROM BRADDELL ROAD

We refer to the above matter wherein your insured's vehicle no. GBE 117EC was involved in an accident with our client's vehicle no. SGP 8794Y.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

- Repair cost: \$1,070.00 (include GST)
- Rental cost: \$ 750.00 (5 days x \$150 per day)
- GIA search fee: \$ 2.00
- Total: \$1,822.00**


Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hesitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully



LAI HUAT (MENG KEE) MOTOR PTE LTD

encs



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQ118005584/Kja3

13 APRIL 2018

388 PTE LTD
48 Toh Guan Rd E
Singapore 608586

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 1173C AND SGP 8794Y ON 20/03/18

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Joy Irene
DID: 6841 2409
FAX: 6741 4108
Email: joyirene@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORITY

To: Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS: SGP 8794Y & GBE 1173C ON 20/03/2018
AT LEFT TURN TO BISHAN ROAD FROM BRADDELL ROAD

This is to confirm that on 20/03/2018, I / We gave you instructions to repair my / our vehicle no. SGP 8794Y which was damaged in the above accident.

In consideration of your agreement to repair my vehicle no. SGP 8794Y, pay for my other expenses and to defer demanding for payment of the costs of repair which was damaged as a result of the above accident, I / We hereby authorise you and/or your solicitors as my / our representative to write, negotiate and settle the accident claim on my / our behalf against any party involved in the abovementioned accident.

I / We hereby undertake to co-operate with you and render you all the assistance (including having my / our vehicle re-inspected and being a witness at trial) that may be necessary for you to recover the cost of repairs and the loss of use to my / our vehicle. I / We further undertake to keep you informed at all times of any communication received from any party involved in the abovementioned accident.

I / We hereby confirm that by signing this Letter of Authority, I / We are not entitled in law to receive any payment. If a cheque is sent to me, I / We shall return the same to the sender as I am precluded in law from accepting any payment.

In the event of my / our claim against any party involved in the abovementioned accident being unsuccessful for any reason whatsoever, I / We shall bear the repair / excess cost payable to Lai Huat (Meng Kee) Motor Pte Ltd either by cash / cheque or claim against my / our insurance policy.

I / We hereby authorise the payment of my / our claim (including any or all medical related invoices / receipts) to be made directly to my / our representative, Lai Huat (Meng Kee) Motor Pte Ltd accordingly.

In relation to the personal and vehicle information collected or otherwise provided during the course of the claim process (including by way of recordings), I agree and consent that Lai Huat (Meng Kee) Motor Pte Ltd may use, disclose and process my personal data for the purpose of responding and administering all activities related to my insurance claim.

Yours faithfully

Signature:



Name:

Calvin Mah Peng Ann

NRIC No:

S1724090J

来發 (明记) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autocity Singapore 575722. Tel: 6453 8110 Fax: 6459 6267
UEN: 199407592C

TAX INVOICE

EST No.: EST0018847
Mah Peng Ann Calvin

GST Reg No: M2-0128609-3
Page: 1 of 1
Number: INV0020360
Your ref.: TP-GBE 1173C EQ
Job No.: 69335
Our ref: 18.03.35
Payment
Date: 6/11/2018

Attn

Vehicle No: SGP 8794Y
Vehicle Model : Mazda 3
Accident on ...: 20/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To supply and replace parts, labour charges for repairing, knocking, welding and to respray paint	1,000.00		1,000.00

Sub-Total 1,000.00
GST 7.00% 70.00
Total S\$ 1,070.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

APEX Car Rental Pte Ltd

37A BARTLEY ROAD SINGAPORE 539777

~~TEL: 6459 8206 FAX: 6553 4645~~

~~GST REGISTRATION NO: 20-0102894-H~~ RCB NO: 200102894H

HIRING AGREEMENT CUM TAX INVOICE NUMBER:

1004235

(Please quote this number in all payments and correspondence)

Vehicle number : SKT 6454Z
Make & model : Toyota Altis 1.6A

HIRER'S PARTICULARS

Hirer : MAH PENG ANN CALVIN NRIC No: S1724090J
Address : BLK 117 CLEMENTI STREET 13 #08-75, SINGAPORE 120117

Contact Number Off : H/p: 96340819
Res:

Nationality : SINGAPOREAN Licence Number: AS NRIC NO
Date Of Birth : 09.04.1965 Licence Expiry : NEW PHOTO LIC.

Driver : AS ABOVE NRIC No: AS ABOVE
Address : AS ABOVE

Contact Number Off : H/p: AS ABOVE
Res:

Nationality : SINGAPOREAN Licence Number: AS NRIC NO
Date Of Birth : Licence Expiry : NEW PHOTO LIC.

RENTAL PRICING

Daily Rental Rate	: S\$ 150.00	Date Out	: 24.03.2018
Days On Rental	: 05 /Day	Time Out	: 9.30am
Sub-Total	: S\$ 750.00	Date Return:	29.03.2018
G.S.T.@7.0%	: S\$ -	Time Return:	5.15pm
Total	: S\$ 750.00		

***RENTER'S Liability for Vehicle Damage EXCESS is S\$1,500.00 ON ALL CLAIMS.
***Applicable to driver below 23YRS old and above 70YRS old OR with less than 2YRS driving experience
EXCESS is S\$5,000.00

REMARK - Vehicle no: SGP 8794Y
Job no: 69335

HIRER'S DECLARATION

I agree to the terms and conditions above and as set out overleaf. If I opt to pay by credit/charge card, my signature here is deemed to have been made on the application credit card charge slip.

Authorised Signatory and Company Stamp

Date:

APEX CAR RENTAL PTE LTD

Prepared by:

Date:

Third Party Insurer Enquiry

Our Ref No: GR-18-042360

Date of Request: 20/03/2018

Your Ref No:

Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 20/03/2018
Enquiry By: Deborah Lai Mei Ling
TP Vehicle No.: GBE1173C
Accident Date: 20/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBE1173C	EQ Insurance Company Ltd	04/09/2017-03/09/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-18-042360

Date of Request: 20/03/2018

Your Ref No:

Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date: 20/03/2018
Enquiry By: Deborah Lai Mei Ling
TP Vehicle No: GBE1173C
Accident Date: 20/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 28/02/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBE 1173C (Insd Veh)	Your Ref. No. : DMCPHQ17-004300
	SGP 8794Y (TP Veh)	Our Ref. No. : CC4/EQ18005584/Kja3q2
Date of Accident	20/3/2018	

Liability	100%	
Final Repair Cost	: \$ 1,070.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 300.00	3 days
Others:	: \$ 2.00	
	: \$	
	1,372.00	
Final Settlement Sum	: \$ 1,372.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	LAI HUAT (MENG KEE) MOTOR PTE LTD	: \$ 1,372.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ118005584/Kja3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 28-02-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 1173C	Veh. Inspected	SGP 8794Y
Policy No.	DMCPHQ17-004300	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	23/03/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 SP (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JM6BK106270319245	Colour	METALLIC BLUE
Odometer	74996	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	5 mm
L/H Front Tyre	205/55 R16	MICHELIN	5 mm
R/H Rear Tyre	205/55 R16	MICHELIN	7 mm
L/H Rear Tyre	205/55 R16	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/03/2018	Inspection Date	26/03/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 8794Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (WCP)	BUCKLED	285.00	285.00
1	REAR BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	140.00	-
1	REAR MAZDA LOGO EMBLEM (WCP)	NECESSARY	20.00	20.00
1	REAR MAZDA EMBLEM (WCP)	NECESSARY	14.00	14.00
1	REAR 3 EMBLEM (WCP)	NECESSARY	10.00	10.00
1	REAR SP EMBLEM (WCP)	NECESSARY	50.00	50.00
	COST PLUS 15%		77.85	56.85
			596.85	435.85
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	TO STRAIGHTEN REAR BODY, TO KNOCK DENTS ON REAR BOOT LID AND RENEW OF PARTS.		500.00	400.00
	TO SPRAY PAINT.		500.00	420.00
			1,000.00	820.00
	GRAND TOTAL		1,631.85	1,290.85
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CC4/EQ118005584/Kja3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.